REPORT NUMBER: 20/2/K602-02/G/4/22/1

DAM SAFETY EVALUATION REPORT:

ROODEFONTEIN

FOURTH REPORT

CARRIED OUT IN TERMS OF GOVERNMENT NOTICE R 139 OF 24 FEBRUARY 2012



MARCH 2020

IBOM: Dam Safety Surveillance

DEPARTMENT OF WATER & SANITATION Private Bag X313, Pretoria, 0001

REPORT NUMBER. 20/2/ K602-02/D/1/22/4

i

DEPARTMENT OF WATER AND SANITATION NATIONAL WATER RESOURCES INFRASTRUCTURE DIRECTORATE: STRATEGIC ASSET MANAGEMENT

ROODEFONTEIN DAM

REPORT ON FOURTH DAM SAFETY EVALUATION

(Carried out in terms of Government Notice R139 of 24 Feb 2012)

COMPILED BY

Author: RW Siwelani 13/12/2019

States and subsystems are sub-

12/12/2019 Hu CN Mahlabela

Approved Professional Person (APP)

APPROVED BY:

Chief Director: Strategic Asset Management

ROODEFONTEIN DAM | FOURTH DAM SAFETY EVALUATION REPORT

Professional Team

PROFESSIONAL TEAM	
Task Team Member	
Hydrological Studies	Mr D Van Der Spuy HS: Flood Studies Engineering Services
Mechanical Inspection	J Kolarovic Mechanical Maintenance Strategic Asset Management
Geological Evaluation	CN Mahlabela

CONFIDENTIALITY NOTICE

All information contained in this document and its appendices is privileged and confidential and is under no circumstances to be made known to any person or institution without the prior written approval of the Director-General of the Department of Water and Sanitation.

ACKNOWLEDGEMENTS

The authors would like to acknowledge the contribution made by the following:

- 1. Engineering services for allowing the team to utilize their Rock-Science: Slide licence and for provide reference report as well as their valuable input.
- 2. The regional office for assisting Dam Safety Surveillance to conduct a physical inspection of the dam and providing valuable information that enabled completion of this report.
- 3. The Dam Safety Office for providing support and guidance during this evaluation.
- 4. Members of sub-directorate: Dam Safety Surveillance for their input in this report.

EXECUTIVE SUMMARY

Roodefontein Dam is situated on Piesang River, about 2 km east of Plettenberg Bay Town in Western Cape Province, Republic of South Africa. The dam can be located in block 3423AB in the geographic grid system.

Roodefontein Dam was design by Ninham Shand Consulting Engineers and constructed by Herbst Broers Civil Contractors and was completed in 1989. In 1995, the grassed cascade downstream of the concrete spillway was replaced with concrete spillway chute. The full supply level was raised by 2 m in 2004 and the NOC was raised by 1.3 m. Furthermore, the outlet works were modified by adding a multi-level draw-off pipe stack in 2000.

The dam comprises of a 315 m long zoned earthfill embankment with a 3.91 m width and a 19.5 m height. The upstream slope has a 1:3 (V: H) gradient and is protected by a 500 mm layer of rip-rap. The downstream slope has 1:2 (V:H) gradient and is protected by a grass layer.

The dam has a 40 m long reinforced concrete ogee spillway situated on the left flank. The spillway is 3.72 m high and on the downstream side, there is a concrete lined stilling basin with under-drains. The side slopes of the reinforced concrete stilling basin are 1:2 and the total with is 35.44 m with a total length of 15.01 m. The spillway has 3.7 m freeboard and a total capacity of 620.6 m³/s. The spillway is able to pass the recommended design flood and the safety evaluation floods without overtopping the non-overspill crest.

The outlet works consist of a single 700 mm diameter pipe, situated on the right flank of the dam. The 700 mm pipe splits into a 500 \emptyset mm and 300 \emptyset mm pipes. The upstream side of the 700 mm dia. pipe is controlled by a plate flap valve while the downstream is controlled by a 500 \emptyset mm and 300 \emptyset mm gate valves. The maximum discharge rate of the outlet works is 2.1 m³/s. It will take 16 days to lower the reservoir level from full supply level to the lowest invert level.

The Dam is founded on a succession of alluvial material, comprising clayey to sandy silt material with gravel layers underlined by stiff clay and silt derived from weathering of the underlying Kirkwood Formation mudrock strata. The spillway is founded on a very dense variably of grey, yellow, and orange silty-sand residual material derived from the in-situ weathered Kirkwood sandstone strata inter-beded with residual silty-clay. On the downstream slope of the embankment, sub-parallel horizontal cracks near the crest were observed. North of the spillway, there is a longitudinal crack at the break in slope. Either than this, the geology of the site is satisfactory.

The presence of the dam puts between 700 to 1 500 people at risk should the dam failures. It is estimated that between 15 and 30 people will lose their lives in the unfortunate event of dam failure. Furthermore, it is estimated that failure will results in direct economic cost ranging from R 458 million to R 533 million.

Mechanical and electrical components were inspected on 11 February 2020. The inspection revealed that conditions of outlet works are reasonable and the outlet works are functioning satisfactorily. However, the required maintenance work was not performed due to a lack of maintenance contractor.

A physical dam safety inspection took place on 25 September 2019. In general, the physical conditions of Roodefontein Dam are satisfactorily. However, the evaluation revealed that certain components of the dam do not meet minimum requirements of Dam Safety Regulations, Regulation 139 of 24 February 2012 and therefore the following is recommended to remedy the situation:

- a) All recommendations from mechanical report should be implement as indicated in the report.
- b) Complete outstanding recommendations from the previous evaluations
- c) Formalise a contractual arrangement between the Owner (Department of Water and Sanitation) and the Operator of the Dam (Bitou Municipality) to allow for efficient operation of the dam.
- d) Increase Freeboard of the dam to ensure compliance with 2011 Guidelines on Freeboard for Dams.
- e) Repair the damaged roof of the outlet house.
- f) Install a proper toe drain system to manage seepage on the downstream of the dam.
- g) Install a lined channel on the toe of the dam to collect run-off water from the toe of the dam and discharge in the river.
- h) Install guardrails on the stairway leading to the gauge plate to improve safety of personnel working at the dam.
- i) Request owners of the property immediate downstream of the dam to re-route the newly installed surface drain away from the dam to avoid saturating the toe of the dam which might trigger slip failure of the earthfill embankment.
- j) Department should determine an appropriate action concerning the newly built horse stable downstream of the earthfill embankment.
- k) Rehabilitate the earthfill embankment in order to address the horizontal crack on the embankment and the slope instability.
- I) Monitor survey beacon F13 on the downstream left side of the spillway channel for a possible movement of the support material.
- m) Install a safety boom upstream of the spillway
- n) Provide a Civil Logbook
- o) Provide training to the Operator of the dam

TABLE OF CONTENTS

EXECUTIVE SUMMARY ii LIST OF FIGURES vii LIST OF FABLES vix LIST OF ABBREVIATIONS x I INTRODUCTION 1 2. LOCALITY OF THE DAM 2 3. DESCRIPTION OF THE DAM 4 3.1. INTRODUCTION 4 3.2. Ownership and Classification of the dam 4 3.2. Ownership and Classification of the dam 4 3.3. Description of the Embankment 5 3.4. Details of the Outlet Works 7 3.6. Storage Capacity 8 4. AVAILABLE INFORMATION 9 4.1. Design Reports 9 4.3. Geological Reports 9 4.3. Geological Reports 9 4.4. Orshultinenance (O & M Manual 10 4.5. Operation And Maintenance (O & M Manual 10 4.6. Dam safety evaluation(DSE) reports 10 4.6. Asbuilt Drawings/Plans 11 5. GEOLOGY OF THE DAM SITE 12 5. GEOLOGY OF THE DAM SITE 12 5. Location of the Geology 12 5.1. Catchment Characteristics	Con Ackı	fidentiality Notice	i i
LIST OF FIGURES	EXE		ii
LIST OF ABBLES ix IST OF ABBREVIATIONS. ix 1. INTRODUCTION. 1 2. LOCALITY OF THE DAM 2 3. DESCRIPTION OF THE DAM 4 3. Ovenership and Classification of the dam. 4 3. Description of the Embankment 5 3. Description of the Embankment 5 3. Description of the Embankment 6 3. Description of the Embankment 6 3. Description of the Embankment 8 4. AVAILABLE INFORMATION 9 4. Construction Reports 9 4. Construction Reports 9 4. Hydrological Reports 9 4. Hydrological Reports 10 5. Operation And Maintenance (O & M) Manual 10 6. Dam safety evaluation(DSE) reports 10 7. Emergency Preparedness Plan (EPP) 11 1. Regional Geology 12 2. Site Geology and Foundation Conditions 12 2. Site Geology and Foundation Conditions 12 5. Selemicity 12 5. Leadult of the Geology 12 5. A Evaluation of the Geology 12	LIST	OF FIGURES	.vii
LIST OF ABBREVIATIONS. x 1. INTRODUCTION 1 2. LOCALITY OF THE DAM 2 3. DESCRIPTION OF THE DAM 4 1.1istoric Background of the Dam. 4 3.2 Ownership and Classification of the dam. 4 3.3 Description of the Embankment. 5 3.4. Details of the Spillway. 6 3.5. Details of the Outlet Works. 7 3.6. Storage Capacity. 8 4. AVAILABLE INFORMATION 9 4.1. Design Reports. 9 4.2. Construction Reports. 9 4.3. Geological Reports. 9 4.4. Hydrological Reports. 10 4.5. Deparatine And Maintenance (O & M) Manual 10 4.6. Dam sately evaluation(DSE) reports. 10 4.7. Emergency Preparedness Plan (EPP) 11 4.8. As-Built Drawings/Plans 12 5. GEOLOGY OF THE DAM SITE 12 5.1. Regional Geology 12 5.2. Steincity 12 5.3. Selemicity 12 5.4. Evaluation of the Geology 12 5.4. Evaluation of the Geology 12 5.4.1. Routing of	LIST	「 OF TABLES	. ix
1. INTRODUCTION 1 2. LOCALITY OF THE DAM 2 3. DESCRIPTION OF THE DAM 4 3. Historic Background of the Dam 4 3. Description of the Embankment 5 3. Description of the Embankment 5 3. Description of the Embankment 6 3. Description of the Embankment 8 4. Available InFORMATION 9 9. Construction Reports 9 2. Construction Reports 9 3. Description And Maintenance (O & M) Manual 10 4. Hydrological Reports 9 4. Evaluation(IDSE) reports 10 4. Evaluation (IDSE) reports 10 4. Baclogical Reports 10 5. Geology OF THE DAM SITE 12 5. Geology of Funct Dam SITE 12 5. Geology and Foundation Conditions 12 5. Selection of the Geology 12 5	LIST	FOF ABBREVIATIONS	X
2. LOCALITY OF THE DAM 2 3. DESCRIPTION OF THE DAM 4 3.1 Historic Background of the Dam 4 3.2 Ownership and Classification of the dam 4 3.2 Description of the Embankment 5 3.4 Details of the Spillway 6 3.5 Details of the Outle Works 7 3.6 Storage Capacity 8 4. AVAILABLE INFORMATION 9 4.1 Design Reports 9 2. Construction Reports 9 3. Geological Reports 9 4. Hydrological Reports 10 4.5 Operation And Maintenance (O & M) Manual 10 4.6 Dam safety evaluation(DSE) reports 10 7.1 Emergency Preparedness Plan (EPP) 11 4.8 As-Built Drawings/Plans 11 5. GEOLOGY OF THE DAM SITE 12 5.1 Regional Geology 12 5.2 Stele Gology and Foundation Conditions 12	1.	INTRODUCTION	1
3. DESCRIPTION OF THE DAM 4 3.1. Historic Background of the Dam. 4 3.2. Ownership and Classification of the dam 4 3.3. Description of the Embankment 5 3.4. Details of the Spillway 66 3.5. Details of the Spillway 66 3.5. Details of the Outlet Works. 7 3.6. Storage Capacity 8 4. AVAILABLE INFORMATION 9 4.1. Design Reports 9 4.2. Construction Reports 9 4.3. Geological Reports 9 4.4. Hydrological Reports 10 4.5. Operation And Maintenance (0 & M) Manual 10 4.6. Dam safety evaluation(DSE) reports 10 4.6. Dam safety evaluation(DSE) reports 12 5.1. Regional Geology 12 5.1. Regional Geology 12 5.2. Stie Geology and Foundation Conditions 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.2. Routing of Recommended Design Flood (RDF) <t< td=""><td>2.</td><td>LOCALITY OF THE DAM</td><td>2</td></t<>	2.	LOCALITY OF THE DAM	2
3.1 Historic Background of the Dam. 4 3.2 Ownership and Classification of the dam. 4 3.3 Description of the Embankment. 5 3.4 Details of the Spillway. 6 3.5 Details of the Spillway. 6 3.5 Details of the Outlet Works. 7 3.6 Storage Capacity. 8 4. AVAILABLE INFORMATION 9 4. Design Reports 9 4. Operation And Maintenance (O & M) Manual. 10 4.5 Operation And Maintenance (O & M) Manual. 10 4.6 Dam safety evaluation(DSE) reports. 10 4.7 Emergency Preparedness Plan (EPP) 11 4.8 As-Built Drawings/Plans. 11 5. GetoLOGY OF THE DAM SITE 12 5.1 Regional Geology. 12 5.2. Ster Geology and Foundation Conditions. 12 5.3 Seisnicity. 12 5.4 Evaluation of the Geology 12 6. HYDROLOGY 14 6. HYDROLOGY 15	3.	DESCRIPTION OF THE DAM	4
3.2 Ownership and Classification of the dam. 4 3.3 Description of the Embankment. 5 3.4 Details of the Outlet Works. 5 3.6 Storage Capacity. 8 4. AVAILABLE INFORMATION 9 4.1 Design Reports 9 4.2 Construction Reports 9 4.3 Geological Reports 9 4.4 Hydrological Reports 10 4.5 Operation And Maintenance (O & M) Manual 10 4.6 Desting exports 10 4.7 Emergency Preparedness Plan (EPP) 11 4.8 As-Built Drawings/Plans 11 5. GEOLOGY OF THE DAM SITE 12 5.1 Regional Geology 12 5.2 Site Geology and Foundation Conditions 12 5.3 Seismicity 12 5.4 Evaluation of the Geology 12 6. HYDROLOGY 14 6.1 Catchment Characteristics 14 6.4.2 Roouf Peaks 15 6.4.1 Routing of Reco	3.1.	Historic Background of the Dam	4
3.3. Description of the Embankment 5 3.4. Details of the Spillway 6 3.5. Details of the Outlet Works 7 3.6. Storage Capacity 8 4. AVAILABLE INFORMATION 9 4. Design Reports 9 4. Construction Reports 9 4. Gological Reports 9 4. Object and Maintenance (O & M) Manual 10 4. Depration And Maintenance (O & M) Manual 10 4. Depration And Maintenance (O & M) Manual 10 4. As-Built Drawings/Plans 11 5. GEOLOGY OF THE DAM SITE 12 5.1. Regional Geology 12 5.2. Stie Geology and Foundation Conditions 12 5.3. Selsinicity 12 5.4. Evaluation of the Geology 12 5.4. Evaluation of RDF and SEF 14 6. HYDROLOGY 14 6.3. Selection of RDF and SEF 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Recommended Design Flood (RDF) 15 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7. Freeboard Requirements 19<	3.2.	Ownership and Classification of the dam	4
3.4. Details of the Spillway. 6 3.5. Details of the Outlet Works. 7 3.6. Storage Capacity. 8 4. AVAILABLE INFORMATION 9 4.1. Design Reports 9 4.2. Construction Reports 9 4.3. Geological Reports 9 4.4. Hydrological Reports 9 4.4. Hydrological Reports 9 4.4. Hydrological Reports 10 4.6. Dam safety evaluation(DSE) reports 10 4.7. Emergency Preparedness Plan (EPP) 11 4.8. As-Built Drawings/Plans 12 5.1. Regional Geology 12 5.2. Site Geology and Foundation Conditions 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.2. Flood Peaks 14 6.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7. HYDRAULICS ANALYSIS 18 7. HYDRAULICS ANALYSIS 18 7. Available Floed and Requirements 1	3.3.	Description of the Embankment	5
3.5. Details of the Outlet Works. 7 3.6. Storage Capacity. 8 4. AVAILABLE INFORMATION 9 4.1. Design Reports. 9 4.2. Construction Reports. 9 4.3. Geological Reports. 9 4.4. Hydrological Reports. 9 4.5. Operation And Maintenance (O & M) Manual 10 4.6. Dam safety evaluation(DSE) reports. 10 4.7. Emergency Preparedness Plan (EPP) 11 5. GEOLOGY OF THE DAM SITE. 12 5.1. Regional Geology 12 5.2. Stie Geology and Foundation Conditions. 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.3. Selection of RDF and SEF 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing. 17 7. HYDRAULICS ANALYSIS 18 7.1. Spillway Capacity 18 7.2.2. Wind Wave run	3.4.	Details of the Spillway	6
3.6. Storage Capacity 8 4. AVAILABLE INFORMATION 9 4.1. Design Reports 9 4.2. Construction Reports 9 4.3. Geological Reports 9 4.4. Hydrological Reports 9 4.4. Hydrological Reports 10 4.5. Operation And Maintenance (O & M) Manual 10 4.6. Dam safety evaluation(DSE) reports 10 4.7. Emergency Preparedness Plan (EPP) 11 4.8. As-Built Drawings/Plans 11 5. GEOLOGY OF THE DAM SITE 12 2.1. Regional Geology 12 2.2. Site Geology and Foundation Conditions 12 2.3. Seisenicity 12 2.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6. HYDROLOGY 14 6. Hydrographs 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Recommended Design Flood (RDF) 15 6.4.3. Results of Flood Routing 17 7. HyDRAULICS ANALYSIS 18 7.1. Flood surcharge 19 7.2. Wind Wave run-up 19 7.2. Wind Wave run-u	3.5.	Details of the Outlet Works	7
4. AVAILABLE INFORMATION 9 4.1. Design Reports 9 4.2. Construction Reports 9 4.3. Geological Reports 9 4.4. Hydrological Reports 9 4.4. Hydrological Reports 10 4.5. Operation And Maintenance (O & M) Manual 10 4.6. Dam safety evaluation(DSE) reports 10 4.7. Emergency Preparedness Plan (EPP) 11 4.8. As-Built Drawings/Plans 11 5. GEOLOGY OF THE DAM SITE 12 5.1. Regional Geology 12 5.2. Site Geology and Foundation Conditions 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6. HYDROLOGY 14 6. HYdrographs 15 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 </td <td>3.6.</td> <td>Storage Capacity</td> <td>8</td>	3.6.	Storage Capacity	8
4. AVAILABLE INFORMATION 9 4.1. Design Reports 9 4.2. Construction Reports 9 4.3. Geological Reports 9 4.4. Hydrological Reports 10 4.5. Operation And Maintenance (O & M) Manual 10 4.6. Dam safety evaluation (DSE) reports 10 4.7. Emergency Preparedness Plan (EPP) 11 4.8. As-Built Drawings/Plans 11 5. GEOLOGY OF THE DAM SITE 12 5.1. Regional Geology 12 5.2. Site Geology and Foundation Conditions 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 5.4. Evaluation of the Geology 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Recommended Design Flood (RDF) 15 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Spillway Capacity 18 7.2. Wind Wave run-up 19			
4.1. Design Reports 9 4.2. Construction Reports 9 4.3. Geological Reports 9 4.4. Hydrological Reports 10 4.5. Operation And Maintenance (O & M) Manual 10 4.6. Dam safety evaluation(DSE) reports 10 4.7. Emergency Preparedness Plan (EPP) 11 4.8. As-Built Drawings/Plans 11 5. GEOLOGY OF THE DAM SITE 12 5.1. Regional Geology 12 5.2. Site Geology and Foundation Conditions 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.2. Flood Peaks 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Spillway Capacity 18 7.2. Wind Wave run-up 19 7.2.4. Surge and Seiches 19 7.2.5. Earthquake Wave 19 7.2.6. Land slide 19	4.	AVAILABLE INFORMATION	9
4.2. Construction Reports	4.1.	Design Reports	9
4.3. Geological Reports 10 4.5. Operation And Maintenance (O & M) Manual 10 4.5. Operation And Maintenance (O & M) Manual 10 4.5. Operation And Maintenance (O & M) Manual 10 4.5. Operation And Maintenance (O & M) Manual 10 4.5. Operation And Maintenance (O & M) Manual 10 4.5. Operation And Maintenance (O & M) Manual 10 4.6. Dam safety evaluation(DSE) reports 11 4.7. Emergency Preparedness Plan (EPP) 11 4.8. As-Built Drawings/Plans 11 5. GEOLOGY OF THE DAM SITE 12 5.1. Regional Geology 12 5.2. Site Geology and Foundation Conditions 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.3. Selection of RDF and SEF 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Flood surcharge 19 7.2.4. Surge and	4.Z.		9
4.4. Hydrological Reports 10 4.5. Operation And Maintenance (O & M) Manual 10 4.6. Dam safety evaluation(DSE) reports 10 4.7. Emergency Preparedness Plan (EPP) 11 4.8. As-Built Drawings/Plans 11 5. GEOLOGY OF THE DAM SITE 12 5.1. Regional Geology 12 5.2. Site Geology and Foundation Conditions 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.3. Selection of RDF and SEF 14 6.4.3. Selection of RDF and SEF 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Spillway Capacity 18 7.2.1. Flood surcharge 19 7.2.2. Wind Wave run-up 19 7.2.3. Wind set-up 19 7.2.4. Surge and Seiches 19 7.2.5. Earthquake Wave 19 7.2.6. Land slide 19	4.3.		9
4.5. Operation And Maintenance (O & M) Manual 10 4.6. Dam safety evaluation(DSE) reports. 10 4.7. Emergency Preparedness Plan (EPP) 11 4.8. As-Built Drawings/Plans 11 5. GEOLOGY OF THE DAM SITE 12 5.1. Regional Geology 12 5.2. Site Geology and Foundation Conditions 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.2. Flood Peaks 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Flood surcharge 19 7.2.1. Flood surcharge 19 7.2.2. Wind Wave run-up 19 7.2.3. Wind set-up 19 7.2.4. Surge and Seiches 19 7.2.5. Earthquake Wave 19 7.2.6. Land slide 19 7.2.7. Available Freeboard 20 7.8. Freeboard Combinations 20	4.4.		10
4.6. Dam Safety evaluation(DSE) reports 10 4.7. Emergency Preparedness Plan (EPP) 11 4.8. As-Built Drawings/Plans 11 5. GEOLOGY OF THE DAM SITE 12 5.1. Regional Geology 12 5.2. Site Geology and Foundation Conditions 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.3. Selection of RDF and SEF 14 6.3. Selection of RDF and SEF 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Flood surcharge 19 7.2.2. Wind Wave run-up 19 7.2.3. Wind set-up 19 7.2.4. Surge and Seiches 19 7.2.7. Available Freeboard 20 7.3. Traveloard Engline 20 7.3.1. Available Drawdown Rate 20	4.5.	Operation And Maintenance (O & M) Manual	10
4.7. Emergency Preparedness Plan (EPP) 11 4.8. As-Built Drawings/Plans 11 5. GEOLOGY OF THE DAM SITE 12 5.1. Regional Geology 12 5.2. Site Geology and Foundation Conditions 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.2. Flood Peaks 14 6.3. Selection of RDF and SEF 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Flood suriements 19 7.2.1. Flood Seiches 19 7.2.2. Wind Wave run-up 19 7.2.3. Wind set-up 19 7.2.4. Surge and Seiches 19 7.2.5. Earthquake Wave 19 7.2.6. Land slide 19 7.2.7. Available Freeboard 20 7.3.1. Available Drawdown Rate 20	4.6.	Dam safety evaluation(DSE) reports	10
4.8. As-Built Drawings/Plans 11 5. GEOLOGY OF THE DAM SITE 12 5.1. Regional Geology 12 5.2. Site Geology and Foundation Conditions 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.3. Selection of RDF and SEF 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Spillway Capacity 18 7.2.1. Flood sucharge 19 7.2.2. Wind Wave run-up 19 7.2.3. Wind set-up 19 7.2.4. Surge and Seiches 19 7.2.5. Earthquake Wave 19 7.2.6. Land slide 19 7.2.7. Available Freeboard 20 7.3. Drawdown Rate 20	4.7.	Emergency Preparedness Plan (EPP)	11
5. GEOLOGY OF THE DAM SITE 12 5.1. Regional Geology 12 5.2. Site Geology and Foundation Conditions 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.3. Selection of RDF and SEF 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Spillway Capacity 19 7.2.2. Wind Wave run-up 19 7.2.3. Wind set-up 19 7.2.4. Surge and Seiches 19 7.2.5. Earthquake Wave 19 7.2.6. Land slide 19 7.2.7. Available Freeboard 20 7.3. Drawdown Capacity 20	4.8.	AS-Built Drawings/Plans	11
5.1. Regional Geology 12 5.2. Site Geology and Foundation Conditions. 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.3. Selection of RDF and SEF 14 6.4.3. Selection of RDF and SEF 14 6.4.4. Hydrographs 15 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Spillway Capacity 19 7.2.1. Flood surcharge 19 7.2.2. Wind Wave run-up 19 7.2.3. Wind set-up 19 7.2.4. Surge and Seiches 19 7.2.5. Earthquake Wave 19 7.2.6. Land slide 19 7.2.7. Available Freeboard 20 7.3. Drawdown Capacity 20 7.3. Lawdown Rate 20	5.	GEOLOGY OF THE DAM SITE	12
5.2. Site Geology and Foundation Conditions. 12 5.3. Seismicity 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.2. Flood Peaks 14 6.3. Selection of RDF and SEF 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Flood surcharge 19 7.2.2. Wind Wave run-up 19 7.2.3. Wind set-up 19 7.2.4. Surge and Seiches 19 7.2.5. Earthquake Wave 19 7.2.6. Land slide 19 7.2.7. Available Freeboard 20 7.3. Drawdown Capacity 20	5.1.	Regional Geology	12
5.3. Seismicity 12 5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.2. Flood Peaks 14 6.3. Selection of RDF and SEF 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Spillway Capacity 18 7.2. Wind Wave run-up 19 7.2.3. Wind set-up 19 7.2.4. Surge and Seiches 19 7.2.5. Earthquake Wave 19 7.2.6. Land slide 19 7.2.7. Available Freeboard 20 7.3. Drawdown Capacity 20 7.3.1. Available Drawdown Rate 20	5.2.	Site Geology and Foundation Conditions	12
5.4. Evaluation of the Geology 12 6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.2. Flood Peaks 14 6.3. Selection of RDF and SEF 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Spillway Capacity 18 7.2. Freeboard Requirements 19 7.2.1. Flood surcharge 19 7.2.2. Wind Wave run-up 19 7.2.3. Wind set-up 19 7.2.4. Surge and Seiches 19 7.2.5. Earthquake Wave 19 7.2.6. Land slide 19 7.2.7. Available Freeboard 20 7.3.0. Trawdown Capacity 20 7.3.1. Available Drawdown Rate 20	5.3.	Seismicity	12
6. HYDROLOGY 14 6.1. Catchment Characteristics 14 6.2. Flood Peaks. 14 6.3. Selection of RDF and SEF 14 6.4. Hydrographs 15 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Spillway Capacity 18 7.2. Freeboard Requirements 19 7.2.1. Flood surcharge 19 7.2.2. Wind Wave run-up 19 7.2.3. Wind set-up 19 7.2.4. Surge and Seiches 19 7.2.5. Earthquake Wave 19 7.2.7. Available Freeboard 20 7.3. Drawdown Capacity 20 7.3.1. Available Drawdown Rate 20	5.4.	Evaluation of the Geology	12
6.1. Catchment Characteristics 14 6.2. Flood Peaks 14 6.3. Selection of RDF and SEF 14 6.4.3. Selection of RDF and SEF 14 6.4.1. Routing of Recommended Design Flood (RDF) 15 6.4.2. Routing of Safety Evaluation Flood (SEF) routing 16 6.4.3. Results of Flood Routing 17 7. HYDRAULICS ANALYSIS 18 7.1. Spillway Capacity 18 7.2. Freeboard Requirements 19 7.2.1. Flood surcharge 19 7.2.2. Wind Wave run-up 19 7.2.3. Wind set-up 19 7.2.4. Surge and Seiches 19 7.2.5. Earthquake Wave 19 7.2.6. Land slide 19 7.2.7. Available Freeboard Combinations 20 7.3. Drawdown Capacity 20	6	HYDROLOCY	11
0.1. Catchinent Characteristics146.2. Flood Peaks.146.3. Selection of RDF and SEF146.4. Hydrographs156.4.1. Routing of Recommended Design Flood (RDF)156.4.2. Routing of Safety Evaluation Flood (SEF) routing166.4.3. Results of Flood Routing177. HYDRAULICS ANALYSIS187. HYDRAULICS ANALYSIS187.1. Spillway Capacity187.2. Freeboard Requirements197.2.1. Flood surcharge197.2.2. Wind Wave run-up197.2.3. Wind set-up197.2.4. Surge and Seiches197.2.5. Earthquake Wave197.2.6. Land slide197.2.7. Available Freeboard207.3. Drawdown Capacity207.3.1. Available Drawdown Rate20	0.	Catchmant Characteristics	14
0.2. Flood Peaks.146.3. Selection of RDF and SEF146.4. Hydrographs156.4.1. Routing of Recommended Design Flood (RDF)156.4.2. Routing of Safety Evaluation Flood (SEF) routing166.4.3. Results of Flood Routing177. HYDRAULICS ANALYSIS187. HYDRAULICS ANALYSIS187. Freeboard Requirements197.2.1. Flood surcharge197.2.2. Wind Wave run-up197.2.3. Wind set-up197.2.4. Surge and Seiches197.2.5. Earthquake Wave197.2.6. Land slide197.2.7. Available Freeboard207.3. Drawdown Capacity207.3.1. Available Drawdown Rate20	0.1.		14
0.3. Selection of RDF and SEF146.4. Hydrographs156.4.1. Routing of Recommended Design Flood (RDF)156.4.2. Routing of Safety Evaluation Flood (SEF) routing166.4.3. Results of Flood Routing177. HYDRAULICS ANALYSIS187.1. Spillway Capacity187.2. Freeboard Requirements197.2.1. Flood surcharge197.2.2. Wind Wave run-up197.2.3. Wind set-up197.2.4. Surge and Seiches197.2.5. Earthquake Wave197.2.6. Land slide197.2.7. Available Freeboard207.3. Drawdown Capacity207.3.1. Available Drawdown Rate20	0.Z.	FIGUU PEaks	14
6.4. Hydrographs156.4.1. Routing of Recommended Design Flood (RDF)156.4.2. Routing of Safety Evaluation Flood (SEF) routing166.4.3. Results of Flood Routing177. HYDRAULICS ANALYSIS187.1. Spillway Capacity187.2. Freeboard Requirements197.2.1. Flood surcharge197.2.2. Wind Wave run-up197.2.3. Wind set-up197.2.4. Surge and Seiches197.2.5. Earthquake Wave197.2.6. Land slide197.2.7. Available Freeboard207.3. Drawdown Capacity207.3.1. Available Drawdown Rate20	0.3. C 4		14
6.4.1.Routing of Recommended Design Flood (RDF)156.4.2.Routing of Safety Evaluation Flood (SEF) routing166.4.3.Results of Flood Routing177.HYDRAULICS ANALYSIS187.1.Spillway Capacity187.2.Freeboard Requirements197.2.1.Flood surcharge197.2.2.Wind Wave run-up197.2.3.Wind set-up197.2.4.Surge and Seiches197.2.5.Earthquake Wave197.2.6.Land slide197.2.7.Available Freeboard207.3.8.Freeboard Combinations207.3.1.Available Drawdown Rate20	0.4. 6 1 ·	Tyulogiapiis	10
6.4.2.Routing of Safety Evaluation Flood (SEP) fouring166.4.3.Results of Flood Routing177.HYDRAULICS ANALYSIS187.1.Spillway Capacity187.2.Freeboard Requirements197.2.1.Flood surcharge197.2.2.Wind Vave run-up197.2.3.Wind set-up197.2.4.Surge and Seiches197.2.5.Earthquake Wave197.2.6.Land slide197.2.7.Available Freeboard207.3.8.Freeboard Combinations207.3.1.Available Drawdown Rate20	0.4. c 1 '	Routing of Refety Evoluction Flood (RDF)	10
7. HYDRAULICS ANALYSIS187.1. Spillway Capacity187.2. Freeboard Requirements197.2.1. Flood surcharge197.2.2. Wind Wave run-up197.2.3. Wind set-up197.2.4. Surge and Seiches197.2.5. Earthquake Wave197.2.6. Land slide197.2.7. Available Freeboard207.3. Drawdown Capacity207.3.1. Available Drawdown Rate20	6 / 1	2. Routing of Salety Evaluation Flood (SEF) routing	10
7. HYDRAULICS ANALYSIS187.1. Spillway Capacity187.2. Freeboard Requirements197.2.1. Flood surcharge197.2.2. Wind Wave run-up197.2.3. Wind set-up197.2.4. Surge and Seiches197.2.5. Earthquake Wave197.2.6. Land slide197.2.7. Available Freeboard207.3. Drawdown Capacity207.3.1. Available Drawdown Rate20	0.4.		17
7.1. Spillway Capacity187.2. Freeboard Requirements197.2.1. Flood surcharge197.2.2. Wind Wave run-up197.2.3. Wind set-up197.2.4. Surge and Seiches197.2.5. Earthquake Wave197.2.6. Land slide197.2.7. Available Freeboard207.3. Drawdown Capacity207.3.1. Available Drawdown Rate20	7.	HYDRAULICS ANALYSIS	18
7.2. Freeboard Requirements197.2.1. Flood surcharge197.2.2. Wind Wave run-up197.2.3. Wind set-up197.2.4. Surge and Seiches197.2.5. Earthquake Wave197.2.6. Land slide197.2.7. Available Freeboard207.2.8. Freeboard Combinations207.3. Drawdown Capacity207.3.1. Available Drawdown Rate20	7.1.	Spillway Capacity	18
7.2.1.Flood surcharge197.2.2.Wind Wave run-up197.2.3.Wind set-up197.2.4.Surge and Seiches197.2.5.Earthquake Wave197.2.6.Land slide197.2.7.Available Freeboard207.2.8.Freeboard Combinations207.3.Drawdown Capacity207.3.1.Available Drawdown Rate20	7.2.	Freeboard Requirements	19
7.2.2.Wind Wave run-up197.2.3.Wind set-up197.2.4.Surge and Seiches197.2.5.Earthquake Wave197.2.6.Land slide197.2.7.Available Freeboard207.2.8.Freeboard Combinations207.3.Drawdown Capacity207.3.1.Available Drawdown Rate20	7.2.	1. Flood surcharge	19
7.2.3.Wind set-up197.2.4.Surge and Seiches197.2.5.Earthquake Wave197.2.6.Land slide197.2.7.Available Freeboard207.2.8.Freeboard Combinations207.3.Drawdown Capacity207.3.1.Available Drawdown Rate20	7.2.2	2. Wind Wave run-up	19
7.2.4.Surge and Seiches197.2.5.Earthquake Wave197.2.6.Land slide197.2.7.Available Freeboard207.2.8.Freeboard Combinations207.3.Drawdown Capacity207.3.1.Available Drawdown Rate20	7.2.3	3. Wind set-up	19
7.2.5.Earthquake Wave	7.2.4	4. Surge and Seiches	19
7.2.6.Land slide197.2.7.Available Freeboard207.2.8.Freeboard Combinations207.3.Drawdown Capacity207.3.1.Available Drawdown Rate20	7.2.5	5. Earthquake Wave	19
7.2.7.Available Freeboard207.2.8.Freeboard Combinations207.3.Drawdown Capacity207.3.1.Available Drawdown Rate20	7.2.6	5. Land slide	19
7.2.8.Freeboard Combinations	7.2.7	7. Available Freeboard	20
7.3. Drawdown Capacity 20 7.3.1. Available Drawdown Rate 20	7.2.8	3. Freeboard Combinations	20
7.3.1. Available Drawdown Rate	7.3.	Drawdown Capacity	20
	7.3.	1. Available Drawdown Rate	20

7.3.2	. The Theoretical Drawdown Capacity	
7.3.2	.1. Hydraulic Gradient	22
7.3.2	.2. Hole Erosion Index (I _{HET})	23
7.3.3	. Drawdown Activation Time	23
7.3.3	.1. Telecommunication at the dam	
7.3.3	.2. Access Roads	
7.3.4	. Frequency of Surveillance	
7.3.5	. Evaluation criteria for drawdown capacity	
1.3.0	. Final evaluation of the installed drawdown capacity	
8		28
8.1	Seenage Monitoring	
82	Water Level Monitoring	
8.3	Spillway Discharge Monitoring	28
8.4.	Deformation Monitoring	
8.5.	Rainfall Monitoring	
8.6.	Draw-off from the Reservoir Monitoring	
8.7.	Stability of Left Flank	
9.	STRUCTURAL ANALYSIS	29
9.1.	Stability of the Embankment	29
9.1.1	. Properties of the Embankment	29
9.1.2	. Soil Properties of Embankment	
9.1.3	. Embankment Slope - Safety Factors	
9.2.	Stability of the Spillway	
9.2.1	. Assumptions	
9.2.2		
10	CHECKING OF REGISTRATION INFORMATION	32
10.1.	Dam Safety Office Record	
11.	EVALUATION OF HAZARD POTENTIAL	
11. 11.1.	EVALUATION OF HAZARD POTENTIAL Dam Classification	
11. 11.1. 11.2.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis	
11. 11.1. 11.2. 11.2.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis	
11. 11.1. 11.2. 11.2. 11.2.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability	
11. 11.1. 11.2. 11.2. 11.2. 11.2.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping	
11. 11.1. 11.2. 11.2. 11.2. 11.2.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping 2.2. Slope instability due to rainfall	
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2.	 EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis Internal Erosion Slope instability Slope instability due to Overtopping Slope instability due to rainfall Slope instability due to rainfall Embankment Slope instability due to rapid drawdown 	
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping 2.2. Slope instability due to rainfall 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading	
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping 2.2. Slope instability due to rainfall 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning	33 33 33 33 33 34 34 34 34 34 34 34
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping 2.2. Slope instability due to rainfall 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Sliding	
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping. 2.2. Slope instability due to rainfall. 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Sliding 3. Erosion	
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping. 2.2. Slope instability due to rainfall 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Sliding 3.1. Earthfill erosion due to rain and reservoir waves	
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping. 2.2. Slope instability due to rainfall 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Sliding 3.1. Earthfill erosion due to rain and reservoir waves 3.2. Earthfill Erosion due to Overtopping of NOC	
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping 2.2. Slope instability due to rainfall 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Sliding 3. Erosion 3.1. Earthfill erosion due to rain and reservoir waves 3.2. Earthfill Erosion due to Overtopping of NOC Dam Break Analysis Dam Break Analysis	
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping 2.2. Slope instability due to rainfall 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Sliding 3.1. Earthfill erosion due to rain and reservoir waves 3.2. Earthfill Erosion due to Overtopping of NOC Dam Break Analysis 1. Inundation	
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping. 2.2. Slope instability due to rainfall. 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Sliding 3.1. Earthfill erosion due to rain and reservoir waves 3.2. Earthfill Erosion due to Overtopping of NOC Dam Break Analysis 1. Inundation Consequences of Dam Failure 1. Economic Consequences	
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.3. 11.3. 11.3. 11.4.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping 2.2. Slope instability due to rainfall 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Sliding 3. Erosion 3.1. Earthfill erosion due to rain and reservoir waves 3.2. Earthfill Erosion due to Overtopping of NOC Dam Break Analysis 1. Inundation Consequences of Dam Failure 1. Economic Consequences	
11. 11.1. 11.2. 11.3. 11.3. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping 2.2. Slope instability due to rainfall 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Sliding 3. Erosion 3.1. Earthfill erosion due to rain and reservoir waves 3.2. Earthfill Erosion due to Overtopping of NOC Dam Break Analysis 1. Inundation Consequences of Dam Failure 1. Economic Consequences 2. Environmental Consequences 3. Loss of Life	
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.3. 11.4.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping 2.2. Slope instability due to rainfall 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Sliding 3.1. Earthfill erosion due to rain and reservoir waves 3.2. Earthfill Erosion due to Overtopping of NOC Dam Break Analysis 1. Inundation Consequences of Dam Failure 1. Economic Consequences 2. Environmental Consequences 3. Loss of Life 4. Social Consequences	
11. 11.1. 11.2. 11.3. 11.3. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping. 2.2. Slope instability due to rainfall. 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Sliding 3.1. Earthfill erosion due to rain and reservoir waves 3.2. Earthfill Erosion due to Overtopping of NOC Dam Break Analysis 1. Inundation Consequences of Dam Failure 1. Economic Consequences 2. Environmental Consequences 3. Loss of Life 4. Social Consequences	
11. 11.1. 11.2. 11.3. 11.3. 11.4.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping. 2.2. Slope instability due to rainfall. 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Sliding 3. Erosion 3.1. Earthfill erosion due to rain and reservoir waves 3.2. Earthfill Erosion due to Overtopping of NOC Dam Break Analysis 1. Inundation Consequences of Dam Failure 1. Economic Consequences 2. Environmental Consequences 3. Loss of Life 4. Social Consequences 5. Ecological Consequences 5. Ecological Consequences	
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.3. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.5. 11.6.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping. 2.2. Slope instability due to rainfall. 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Sliding 3.1. Earthfill erosion due to rain and reservoir waves 3.2. Earthfill erosion due to Overtopping of NOC Dam Break Analysis 1. Inundation Consequences of Dam Failure 1. Economic Consequences 2. Environmental Consequences 3. Loss of Life 4. Social Consequences 5. Ecological Consequences	
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.3. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.5. 11.6.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping. 2.2. Slope instability due to rainfall. 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Sliding 3.1. Earthfill erosion due to rain and reservoir waves 3.2. Earthfill Erosion due to Overtopping of NOC Dam Break Analysis Inundation Consequences of Dam Failure Consequences 2. Environmental Consequences 3. Loss of Life 4. Social Consequences 5. Ecological Consequences 5. <t< td=""><td></td></t<>	
11. 11.1. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.2. 11.3. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.5. 11.6. 12. 112.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping. 2.2. Slope instability due to rainfall. 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Overturning 2.7. Store instability due to rain and reservoir waves 3.8. Erosion 3.1. Earthfill erosion due to rain and reservoir waves 3.2. Earthfill Erosion due to Overtopping of NOC Dam Break Analysis Inundation Consequences of Dam Failure Economic Consequences 2. Environmental Consequences 3. Loss of Life 4. Social Consequences 5. Ecological Consequences 5. Ecological Consequences 6. Evaluation of Emergency Preparedness Plan Summary of Hazard Potential Summary of Hazard Potential	
11. 11.1. 11.2. 11.3. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.4. 11.5. 11.4. 11.4. 11.4. 11.4. 11.5. 11.4. 11.5. 11.5.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping. 2.2. Slope instability due to rainfall. 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Overturning 2.7. Spillway Sliding 3.8. Erosion 3.1. Earthfill erosion due to rain and reservoir waves 3.2. Earthfill Erosion due to Overtopping of NOC Dam Break Analysis Dam Break Analysis 1. Inundation Consequences of Dam Failure Consequences 2. Environmental Consequences 3. Loss of Life 4. Social Consequences 5. Ecological Consequences 5. Ecological Consequences 5. Evaluation of Emergency Preparedness Plan Summary of Hazard Potential	
11. 11.1. 11.2. 11.3. 11.4.	EVALUATION OF HAZARD POTENTIAL Dam Classification Failure Modes Analysis 1. Internal Erosion 2. Slope instability 2.1. Slope instability due to Overtopping. 2.2. Slope instability due to rainfall. 2.3. Embankment Slope instability due to rapid drawdown 2.4. Embankment Slope instability due to loading 2.5. Spillway Overturning 2.6. Spillway Overturning 2.7. Spillway Sliding 3.8. Erosion 3.1. Earthfill erosion due to rain and reservoir waves 3.2. Earthfill Erosion due to Overtopping of NOC Dam Break Analysis Dam Break Analysis 1. Inundation Consequences of Dam Failure Consequences 2. Environmental Consequences 3. Loss of Life 4. Social Consequences 5. Ecological Consequences 5. Ecological Consequences 5. Evaluation of Emergency Preparedness Plan Summary of Hazard Potential INSPECTION OF THE DAM	

12.3.1.	Surrounding Terrain	40
12.3.2.	Access to dam site and Lighting of dam wall	
12.3.3.	Access to the dam	
12.4.	Operational Health and Safety	
12.4.1.	The Safety Boom	
12.4.2.	Safety	
12.5	Evaluation of Dam Owner's Operation and Maintenance Pro	pramme 44
12.5.1	Dam Safety Logbook	ΔA
12.0.1.	Operation and Maintenance manual	ΔΔ
12.0.2.	Emergency Preparedness Plan (EPP)	ΔΛ
12.0.0.	Non Overspill Crest (NOC)	
12.0.	NOC Properties	
12.0.1.	Defects	
12.0.2.	Undesirable Elements and Activities	
12.0.3.	Unstream Slope of Dam Wall	
12.7.	Vegetation Crowth and Slong Protection	
12.7.1.	Defecto	
12.7.2.	Animal or Termite Activities and Festneth	
12.7.3.	Animal of Termite Activities and Footpath	
12.8.	Downstream slope of Dam wall	
12.8.1.	Vegetation growth	
12.8.2.	Slope protection	
12.8.3.	Defects	
12.9.	Downstream I oe and Flanks	
12.10.	Other observations	
12.11.	Spillway	51
12.11.1.	Spillway Approach Channel	
12.11.2.	Conditions of concrete	
12.11.3.	Defects on the Spillway	53
12.11.4.	Stability of the Walls	53
12.12.	Outlet Works	53
12.13.1.	New Infrastructure	54
12.13.2.	Contractual Arrangement	54
12.14.	General observations	54
12.15.	Mechanical Evaluation	55
13. CON		
14. REC		
14.1.	Outstanding from Previous Inspection	
14.2.	New recommendation from this inspection	
15. REF		
16. ADD		
16.1.	Addendum A: Access and Locality Map	
16.2.	Addendum B: As-Built Drawings	
16.3.	Addendum C: Geology	
16.4.	Addendum D: Hydrology Report	62
16.5.	Addendum E: Flood routing	62
16.6.	Addendum F: Freeboard Calculations	62
16.7.	Addendum G: Drawdown Capacity	62
16.8.	Addendum H: Monitoring Data	62
16.9.	Addendum I: Stability Analysis	62
16.10.	Addendum J: Registration Information	Error! Bookmark not defined.
16.11.	Addendum K: Mechanical Report	Error! Bookmark not defined.

LIST OF FIGURES

Figure 1: Geographic Map showing the locality of Roodefontein Dam	3
Figure 2: Typical cross-section of Roodefontein Dam – Embankment (Drw No. 150195/06)	5
Figure 3: Cross-section of the Ogee spillway	7
Figure 4: Regional geology of areas around Roodefontein Dam	13
Figure 5: The August 2006 observed inflow hydrograph	15
Figure 6: RDF hydrograph with reduced levels	16
Figure 7: SEF routing hydrograph with corresponding reduced levels.	16
Figure 8: Discharge Capacity of the Spillway determined using a dynamic discharge coefficient	18
Figure 9: Outlet works Rating curve	21
Figure 10: drawdown curve	22
Figure 11: CellC coverage map at Roodefontein Dam ((https://www.cellc.co.za/cellc/coverage-map: 13/02/2019))	р 24
Figure 12: Vodacom coverage map around Plattenberg Bay. (https://www.vodacom.co.za/vodacom/coverage-map: 13/02/2019)	25
Figure 13: MTN network coverage around Roodefontein Dam	
(https://www.mtn.co.za/Pages/Coverage_Map.aspx : 13/02/2019)	25
Figure 14: Cross-Section of the concrete spillway	30
Figure 15: Gauge Plate reading	40
Figure 16: Clear Weather at the dam on 25 September 2019	40
Figure 17: A densely vegetated hilly left side of the reservoir's surrounding	40
Figure 18: A densely vegetated hilly right side of the reservoir's surrounding	41
Figure 19: A valley downstream side of the dam with a newly built horse stables	41
Figure 20: Access Route to Roodefontein Dam.	42
Figure 21: Side view of the spillway showing a lack of safety Boom	43
Figure 22: Stairway leading to the gauge plate.	43
Figure 23: A copy of the 1990 O&M document	44
Figure 24: A copy of 2004 O&M document	44
Figure 25: A copy of 2005 EPP	45
Figure 26: 2015 copy of EPP	45
Figure 27: Non - Overspill crest of Roodefontein Dam.	45
Figure 28: Ants activities on the crest	46
Figure 29: Isolated vegetation on the upstream slope	46
Figure 30: Upstream slopes of the dam wall	47
Figure 31: Some vegetation on the downstream slope of the wall.	47
Figure 32: View of the dam wall showing some bushes on the downstream slope	48
Figure 33: View of the downstream slope from the toe	48
Figure 34: Grass protection on the downstream slope of the dam	48
Figure 35: Existing horizontal crack covered by grass on the downstream slope	49

Figure 36: Strong vegetation growth in the Toe-Channel.	49
Figure 37: Seepage from the right flank day lighting next to the outlet house	. 50
Figure 38: Seepage water channel to a Toe-Channel and discharge in the river	. 50
Figure 39: Lined Surface drain from the downstream property discharging into the Toe-Channel	51
Figure 40: Spillway approach channel.	51
Figure 41: material deposit due to a slip failure on the right flank	. 52
Figure 42: Side view of the spillway	. 52
Figure 43: Concrete conditions of the Staling Basing	. 52
Figure 44: Signs of minor concrete panel movement.	. 53
Figure 45: Damaged roof of the outlet house	. 53
Figure 46: A horse stable constructed on the downstream of the dam wall	54
Figure 47: View of the downstream taken from the NOC.	54

LIST OF TABLES

Table 1: Locality data of Roodefontein Dam.	2
Table 2: Historic data of Roodefontein Dam	4
Table 3: Ownership and classification of Roodefontein Dam	4
Table 4: Statistics of the embankment	6
Table 5: Details of the Spillway	7
Table 6: details of the Outlet Works (Hattingh, 2011)	8
Table 7: Storage capacity of Roodefontein Dam	8
Table 8: List of available design reports	9
Table 9: List of available construction reports	9
Table 10: List of available Geological Reports	. 10
Table 11: List of available hydrological studies reports	. 10
Table 12: List of available operations and maintenance manuals	. 10
Table 13: List of available Dam Safety Evaluation Reports	.11
Table 14: List of available Emergency Preparedness Plans	.11
Table 15: List of selected and available As-built drawings	.11
Table 16: Catchment Characteristics of Roodefontein Dam	.14
Table 17: Recommended flood peaks from the flood frequency report (Rademeyer, 2018:	i)
	.14
Table 18: Flood routing results for RDF and SEF cases.	. 17
Table 19: Discharge equations used to determine the spillway discharge capacity	. 18
Table 20: Freeboard input parameters	. 19
Table 21: Freeboard combinations	. 20
Table 22: Outlet works statistics for Roodefontein Dam.	. 20
Table 23: Capacity of installed low level outlet works	. 22
Table 24: Hydraulic gradient of the dam	.23
Table 25: Soil properties for the embankment	.23
Table 26: Drawdown activation parameters	.23
Table 27: Surveillance frequency at Roodefontein Dam	.26
Table 28: Drawdown capacity evaluation criteria	.26
Table 29: Soil properties used for stability analysis (Watermeyer, 2002:12)	. 29
Table 30: Factors of safety for the embankment slopes	. 30
Table 31: Assumed parameters for concrete stability analysis	.31
Table 32: Classification data of Roodefontein Dam	. 33
Table 34: Dam break results (Watermeyer, 2004:N.9)	.36
Table 35: South African Annual Inflation from 2011 to 2018 (Statistics South Africa)	. 37
Table 36: Risk analysis results of Roodefontein Dam	. 38
Table 37: Team members who conducted visual inspection of the dam	. 39
Table 38: Inspection data of Roodefontein Dam	. 39
Table 39: Recommendations not implemented from the previous Dam Safety evaluation	.58
Table 40: Dam safety related recommendations	. 58

LIST OF ABBREVIATIONS

ABBREVIATION	DEFINITION
APP	Approved Professional Person
DO	Dam Operator
BM	Bitou Municipality
D/S	Down Stream
DSS	Dam Safety Surveillance
DSI	Dam Safety Inspection
DSO	Dam Safety Office
DSE	Dam Safety Evaluation
DSER	Dam Safety Evaluation Report
DWS	Department of Water and Sanitation
EQ	Earth Quake
EPP	Emergency Preparedness Plan
FSL	Full Supply Level
FSC	Full Supply Capacity
LDDL	Lowest Draw Down Level
LFL	Lowest Foundation Level
MAP	Mean Annual Precipitation
MAR	Mean Annual Rainfall
NOC	Non-Overspill Crest
PE	Probability of Exceedance
Q _{1:200}	Flood Peak with probability of exceedance of 1 in 200
RBL	River Bed Level
RMF	Regional Rainfall Level
SEF	Safety Evaluation Flood
U/S	Upstream
WCO	Water Control Officer
Yrs.	Years
LF	Left flank
RF	Right flank

1. INTRODUCTION

The fourth dam safety evaluation of Roodefontein Dam conducted in order to comply with the prescripts of the Dam Safety Regulations, Notice R 139 of 24 February 2012.

The national government of the Republic of South Africa formulated Dam Safety Regulations to standardise the construction, monitoring and operation of dams in South Africa. These regulations aim at ensuring that the risk posed to the population and the environment is mitigated and managed. The formation of these Dam Safety Regulations is empowered by Section 123 (1) of the National Water Act: Act No. 36 of 1998.

The regulations compel all owners/operators of dams with a safety risk to conduct routine and major dam safety evaluations every 5 years and submit a report thereof, to the minister of Water and Sanitation.

This report presents the results of the fourth dam safety evaluation of Roodefontein Dam in partial fulfilment of the government notice R 139 of 24 February 2012.

The main objectives of this report are as follows:

- Discuss the state of conditions at Roodefontein Dam.
- Present the results of the performed evaluation of the dam.
- Present and discus the findings of the conducted physical inspection of the dam.
- Provide recommendations to address the identified shortcomings at the dam.

This report covers the fourth dam safety evaluation of Roodefontein Dam only and the evaluation report should be submitted to Dam Safety Office (DSO) no later than 31 March 2020.

The first part of this report focuses on the background and description of Roodefontein Dam. The second part discusses the hydrology, hydraulics, structural analysis, and risk analysis of the dam. The third part discusses the findings emanating from a physical inspection of the dam conducted on 25 September 2019. Thereafter, conclusion is drawn and recommendations presented.

2. LOCALITY OF THE DAM

Roodefontein Dam is situated on Piesang River, about 2 km east of Plettenberg Bay Town in Western Cape Province, Republic of South Africa. The dam can be located in block 3423AB in the geographic grid system. Figure 1 shows the locality map of the dam and Table 1 gives a summary of the locality data of the dam. Enlarged locality map is attached in Addendum A.

LOCALITY INFORMATION OF ROODEFONTEIN DAM		
Name of Dam	Roodefontein	
Locality Number	K602-02	
River	Piesang River	
Nearest Town	Plettenberg Bay	
Distance to nearest Town	2 km	
Province	Western Cape	
Latitude	34°4'0.141" S	
Longitude	23°20'6.004" E	

 Table 1: Locality data of Roodefontein Dam.



Figure 1: Geographic Map showing the locality of Roodefontein Dam

3. DESCRIPTION OF THE DAM

3.1. Historic Background of the Dam

Roodefontein Dam was originally design by Ninham Shand Consulting Engineers and constructed by Herbst Broers Civil Contractors, construction completed in 1989. In 1995, the grassed cascade downstream of the concrete spillway was replaced with concrete spillway chute. Hattingh reported that the full supply level was raised by 2 m in 2004 and the NOC was raised by 1.3 m. Furthermore, the outlet works were modified by adding a muilt level draw-off pipe stack in 2000 (Hattingh, 2011:1). The historic data of this dam is summarised in Table 2.

HISTORIC DAM OF THE DAM			
ltem	Description	Designer	Year
Original Dam structure	Contractor: Herbst Broers (Pty)	Ninham Shand (Cape) Inc.	1989
Betterment No.1	Provision of concrete chute.	Ninham Shand (Cape) Inc.	1995
Betterment No.2	Installation of Muilti-level outlet works	Stewart Scott inc.	2000
Betterment No.3	Raising of NOC and FSL	Stewart Scott inc.	2003/4

Table 2: Historic data of Roodefontein Dam

3.2. Ownership and Classification of the dam

Roodefontein Dam is owned by the Department of Water and Sanitation and operated by Bitou Municipality. Water from the dam is used primarily for irrigation, industrial and domestic consumption (Hattingh, 2009:1). The dam has been classified as a category III. Table 3 below gives a summary of the ownership and classification information of the dam.

Table 3: Ownership	and classification	of Roodefontein Dam
--------------------	--------------------	---------------------

CLASSIFICATION INFORMATION		
Owner	Dept. of Water and Sanitation	
Operator	Bitou and Plettenberg Bay Municipality	
Classification Category	III	
Hazard Rating	High	
Size	Medium	
Registration date	29 January 1990	
Classification date	2 September 1987	
Date of completion	1995	

3.3. Description of the Embankment

The dam comprises of a zoned earthfill embankment which is 315 m long, 3.91 m wide at the crest level and 19.5 m high when measured from the lowest river bed level (RL 26.5 m) to the NOC (RL 46.0 m). The upstream slope of the dam has a 1:3 (V: H) gradient and is protected by a layer of rip-rap against waves action and erosion. The downstream side of the embankment has 1:2 (V:H) gradient and it is protected by vegetation cover, see Figure 2. The statistics of the embankment is provided in Table 4.



Figure 2: Typical cross-section of Roodefontein Dam – Embankment (Drw No. 150195/06)

Table 4: Statistics of the embankment

STATISTICS OF THE EMBANKMENT			
Wall type	Zoned Earthfill		
Crest length	315 m		
Crest width	3.91 m		
Erosion protection for the crest	Gravel		
Downstream slope (V:H)	1:2 and 1:2.5		
Downstream slope protection	Grass		
Upstream slope (V:H)	1:3		
Upstream slope protection	Rip-Rap		
Wall height (LFL to NOC)	19.5 m		
Wall height (RBL to NOC)	18 m		
Full Supply Level (FSL)	RL 42.3 m		
Non-Overspill Crest (NOC) level	RL 46.0 m		
Gauge Plate Reading at FSL	27.01 m		
Freeboard	3.7 m		

3.4. Details of the Spillway

The dam has a 40 m long reinforced concrete ogee side channel spillway situated on the left flank. The spillway is 3.72 m high when measured from the river channel, see Figure 3.

On the downstream side, the spillway has a concrete lined stilling basin with underdrains. The side slopes of the reinforced concrete stilling basin are 1:2 (Vertical: Horizontal) and the total with is 35.44 m with a total length of 15.01 m. The end part of the stilling basin has a 1.6 m wide sloped concrete upstand (Watermeyer, 2004). Details of the spillway are summarised in Table 5.



Figure 3: Cross-section of the Ogee spillway

Table 5: Details of the Spillway

STATISTICS OF THE SPILLWAY		
Spillway Type	Concrete Ogee Spillway	
Crest level (FSL)	42.3 m	
Total Spillway width	40 m	
Height of NOC above Spillway	3.7 m	
Level of Gauge Plate Zero	33.84 m	
Energy Dissipation Structures	Concrete chute	

3.5. Details of the Outlet Works

The outlet works consist of a single 700 mm diameter pipe, situated on the right flank of the dam. The 700 mm pipe splits into a 500 \emptyset mm and 300 \emptyset mm pipes. The upstream side of the 700 mm dia. pipe is controlled by a plate flap valve while the downstream is controlled by a 500 \emptyset mm and 300 \emptyset mm gate valves. Details of the outlet works are summarised in Table 6. Detail layout of the outlet works is attached in Addendum B.

Table 6: details of the Outlet Works (Hattingh, 2011)

STATISTICS OF THE OUTLET WORKS		
Invert level	RL 32 m	
Number of outlet pipes	1	
Diameter	700 Ø mm	
Type of Outlet valve - Upstream	Plate flap Valve	
Type of Outlet valve - Downstream	Butterfly and Sleeve Valves	
Size of Outlet valve	500 mm and 300 mm	
Reported Discharge Capacity at FSL	1.2 m ³ /s	
Reported Time to lower reservoir from FSL to Lowest Draw Down Level	24 days	

3.6. Storage Capacity

The storage capacity data of Roodefontein Dam is summarised in Table 7 below. The gross volume of the dam is 2.063 million m^3 and if the inactive storage below the invert level of the outlet works in neglected, the net storage of the dam is 2.003 million m^3 .

Table 7: Storage capacity of Roodefontein Dam

STORAGE CAPACITY			
Gross storage capacity at FSL - V _{gross}	2.063 x 10 ⁶ m ³		
Inactive storage below Invert level of Outlet works - V _{inactive}	60 000 m ³		
Net Storage Capacity at FSL - V _{net}	2.003 x 10 ⁶ m ³		
Storage Capacity at NOC (RL _{noc} = 46 m) - V _{noc}	3 624 x 10 ⁶ m ³		
Water Surface Area at FSL - A _{FSL}	37.1 ha		
Water Surface Area at RL 40 m – A _{40m}	28.8 ha		
Water Surface Area at NOC - A _{NOC}	50.5 ha		
Length of Resevoir at FSL - L _{FSL}	1.25 km		

4. AVAILABLE INFORMATION

The authors evaluated the following reports as part of the fourth dam safety evaluation.

4.1. Design Reports

A list of design reports evaluated by the authors during this evaluation is provided in Table 8.

Table 8: List of available design reports

	DESIGN REPORTS			
ΤΙΤ	LE	AUTHOR	YEAR	
1.	Raising the FSL by 2 m by means of solid raising	Watermeyer CF	2002	
2.	Evaluation of dam raising option: Addendum	Pellsn HNF	2002	
3.	Evaluation of dam raising option, Revision 1	Pellsn HNF	2001	
4.	Rehabilitation of Spillway. Report No. 2214/4601	Pellsn HNF	1994	
5.	Rehabilitation of Spillway: Supplementary Report No. 2214A/4601	Pellsn HNF	1994	

4.2. Construction Reports

A list of construction reports evaluated by the authors during this evaluation is provided in Table 9.

Table 9: List of available construction reports

CONSTRUCTION REPORTS			
TITLE	AUTHOR	YEAR	
1. Construction Completion Report	Erwee H	2006	
2. Raising the Spillway & Embankment of Roodefontein Dam	Watermeyer CF	2004	
3. Construction Completion Report. Report No. 2465/4601	Pellsn HNF	1996	
4. Construction Completion Report. Report No. 1628/4601	Powrie WE	1990	

4.3. Geological Reports

A list of Geological reports evaluated by the authors during this evaluation is provided in Table 10.

Table 10: List of available Geological Reports

GEOLOGICAL/GEOTECHNICAL REPORTS			
TITLE	AUTHOR	YEAR	
1. Engineering Geological Report for Dam Safety Purposes	Davis GN	2006	
2. Rehabilitation of Spillway, Final Geology Report.	Van Der Merwer WJ	1996	
3. The effect of an Earthquake on the dam	Ninham Shand	1996	
4. Dam Safety Inspection Geological Report	Knight Hall Hendry	1993	
5. Preliminary Report on Geological Investigations	Van Der Merwer WJ	1987	

4.4. Hydrological Reports

A list of hydrological studies reports evaluated by the authors during this evaluation is provided in Table 11.

	HYDROLOGICAL REPORTS			
TITLE		AUTHOR	YEAR	
1.	Flood Frequency Analysis: Roodefontein Dam	Rademeyer P	2018	
2.	Flood Frequency Analysis: Roodefontein Dam	Roux M	2010	
3.	Flood Frequency Analysis: Roodefontein Dam	Tsehla MS	2001	

4.5. Operation And Maintenance (O & M) Manual

A list of operations and maintenance (O&M) manuals evaluated by the authors during this evolution is provided in Table *12*.

Table 12: List of available operations and maintenance manuals

O & M MANUALS			
TITLE		AUTHOR	YEAR
1.	Operation, Monitoring & Maintenance Manual: Vol. 2	Watermeyer	2004
2.	Operation & Maintenance Manual.	Ninham Shand	1990
3.	Operation & Maintenance Manual.	Ninham Shand	1998

4.6. Dam safety evaluation(DSE) reports

A list of Dam Safety Evaluation reports evaluated by the author is provided in Table 13 below. The reports were initially called Dam Safety Inspection (DSI) Reports.

Table 13: List of available Dam Safety Evaluation Reports

DAM SAFETY EVALUATION REPORTS			
TITLE AUTHOR		AUTHOR	YEAR
1.	Third Dam Safety Inspection Report	Hattingh LC	2011
2.	Second Dam Safety Inspection Report	Jan Brink	2006
3.	First Dam Safety Inspection Report	Watermeyer CF	2002

4.7. Emergency Preparedness Plan (EPP)

The EPP evaluated by the author are provided in Table 14 below.

	EMERGENCY PREPAREDNESS PLAN					
TIT	LE	AUTHOR	YEAR			
1.	Operations and Maintenance Manual & Emergency Preparedness Plan	Watermeyer CF	2005			
2.	Roodefontein Dam: Emergency Preparedness Plan	Weidemann EW & Horn H	2015			

4.8. As-Built Drawings/Plans

A list of select few As-built drawings of the dam is provided in Table 15 below and copies of these drawings have been attached in Addendum B.

1 able 15 : List of selected and available As-built drawing	Table 15:	: List of selecte	d and available	As-built drawing
--	-----------	-------------------	-----------------	------------------

AS-BUILT DRAWINGS/PLANS					
DESCRIPTION	Number				
1. Spillway Raising - Sections & Details	150193/06				
2. Alternative Embankment Raising	150195/06				
3. Embankment Section & Downstream Valve Chamber Details	150197/06				
4. Embankment Survey	150207/06				
5. Details of stilling basin	150199/06				
6. Outlet pipe details	150201/06				

5. GEOLOGY OF THE DAM SITE

The following geological data was extracted from the engineering geological report compiled by Davis in 20116 for dam safety purposes. The second source of the geological information used is the final geotechnical report conducted during the rehabilitation of the spillway in 1996. This report summarises the geology of the dam and its region, detailed information is contained in the above mentioned sources, refer to addendum C.

5.1. Regional Geology

The regional geology consists of sandstone and conglomerate of the Enon formation in the Uitenhage group as can be seen in Figure 4. It is reported that sedimentary strata of the Cape Super-group form part of the geology of this area.

5.2. Site Geology and Foundation Conditions

Davis, 2006 reports that the embankment of Roodefontein Dam is founded on a succession of alluvial material, comprising clayey to sandy silt material with gravel layers underlined by stiff clay and silt derived from weathering of the underlying Kirkwood Formation mudrock strata.

The spillway is founded on a very dense variably of grey, yellow, and orange silty-sand residual material derived from the in-situ weathered Kirkwood sandstone strata interbeded with residual silty-clay.

During construction major slope instability were witnessed on the northern slope flanking the spillway excavation. It is reported that this slope instability is expected to continue since a detail stability analysis revealed that the slope have a safety factor of unity (1).

5.3. Seismicity

Roodefontein Dam is located in a region with low natural earthquake hazard. The dam is in an area with a predicted horizontal acceleration of 0.05 g with a 10% probability of being exceeded in a 1:50 year return period.

5.4. Evaluation of the Geology

On the downstream slope of the embankment, Davis noted with concern sub-parallel horizontal cracks near the crest. North of the spillway, there is a longitudinal crack at the break in slope. Either than this, the geology of the site is satisfactory. These findings have been adopted in this report since no new findings were made during this fifth dam safety evaluation.



Figure 4: Regional geology of areas around Roodefontein Dam.

6. HYDROLOGY

The hydrology information was extracted from the flood frequency analysis report of February 2018 compiled by Rademeyer under the supervision of Van der Spuy (refer to addendum D). The following sub-sections cover different aspects of the hydrology of the dam.

6.1. Catchment Characteristics

The dam is located on Piesang River in Francou-Rodier region 5.2 and with 3.5 hours as a total time of concentration. The catchment for Roodefontein Dam is 28 km^2 in size and has a mean steepness of 16%. The longest water course is 14.8 km in length with a mean slope of 0.011683. The Mean Annual Precipitation (MAP) is 930 mm. Key characteristics of the catchment are listed in Table 16 below.

CATCHMENT CHARACTERISTICS						
A (km ²)	L (km)	L _c (km)	T _c (h)	S _L (m/m)	S _A (%)	MAP (mm)
28	14.8	8.25	3.5	0.011683	16	930

Table 16: Catchment Characteristics of Roodefontein Dam.

6.2. Flood Peaks

The recommended design flood (RDF: Q_{RDF}) which is $Q_{1:200}$ for this category III dam has a peak flow of 95 m³/s and the Safety Evaluation Flood (SEF) is 530 m³/s. The flood frequency analysis report recommends that the Regional Maximum Flood (RMF) should be treated as the SEF and this recommendation is in-line with the 2011 SANCOLD guidelines. A list of recommended flood peaks is provided in Table 17.

Table 17: Recommended flood peaks from the flood frequency report (Rademeyer, 2018: i)

Probability of expediency (%)						
20	10	5	2	1	0.5	0.01
Return Period (Years)						
1:5	1:10	1:20	1:50	1:100	1:200	1:10 000
Flood Peak (m ³ /s)						
20	30	45	65	80	95	530

6.3. Selection of RDF and SEF

The 2011 SANCOLD guidelines on Freeboard state that for a medium size dam (12 m \leq Dam height \leq 30 m) the Recommended Design Discharge (RDD) should be based on flood peak with 1:200 return period. Therefore, the recommended design flood for Roodefontein Dam is Q_{1:200} (95 m³/s).

The same guidelines further recommend that the Regional Maximum Flood (RMF) should be considered as a Safety Evaluation Flood (SEF). In the case of Roodefontein Dam, the SEF is $530 \text{ m}^3/\text{s}$.

6.4. Hydrographs

The 2018 flood frequency report recommends that the observed hydrograph should be used for flood routing purposes. The author of this report selected the August 2006 flood which peaked at 34.4 m^3 /s. This hydrograph is shown in Figure 5 below.



Figure 5: The August 2006 observed inflow hydrograph.

6.4.1. Routing of Recommended Design Flood (RDF)

The observed inflow hydrograph was adjusted using the RDF peaks ($Q = 95 \text{ m}^3/\text{s}$) in Table 17. The resultant hydrograph was then routed through the spillway using basic principles of flood routing following Newton-Ralpson's Method. The results of the RDF routing are graphical shown in Figure 6.



Figure 6: RDF hydrograph with reduced levels

6.4.2. Routing of Safety Evaluation Flood (SEF) routing

The observed inflow hydrograph was adjusted using the SEF value provided in Table 17 and routed through the spillway of the dam. The resulting hydrograph is shown in Figure 7 below. Refer to addendum E for detailed calculations.



Figure 7: SEF routing hydrograph with corresponding reduced levels.

6.4.3. Results of Flood Routing

In the case of RDF routing, the NOC of the dam is not overtopped. The maximum discharge obtained is 76.1 m³/s and this corresponds to a 1.18 m stage which has a reduced level of 43.48 m. This implies that the available freeboard under RDF conditions is 2.52 m. The attenuation in the case of RDF is 19.9% and the total translation for this case is 1 hour which is the same as that of the SEF routing.

In the case of SEF routing, the NOC is also not overtopped and the maximum discharge is 518.06 m^3 /s. The corresponding stage is 3.36 m stage with a reduced level of 45.66 m above mean seal level. The available freeboard under this condition is 0.34 m, the attenuation is 2.3% and the translation is 1 hour. The routing results are summarised in Table 18 below.

FLOOD ROUTING RESULTS					
PARAMETER	RDF ROUTING	SEF ROUTING			
Maximum Discharge (m ³ /s)	76.1	518.06			
Height above Spillway Crest (m)	1.18	3.36			
Available Freeboard (m)	2.52	0.34			
Attenuation (%)	19.9	2.3			
Translation (hours)	1	1			

 Table 18: Flood routing results for RDF and SEF cases.

7. HYDRAULICS ANALYSIS

7.1. Spillway Capacity

The uncontrolled ogee spillway has a maximum discharge capacity of 620.6 m³/s before overtopping the NOC. The quoted discharge capacity is based on using a dynamic discharge coefficient which was derived using the DWS equation as shown in Table 19. The use of a constant value of a discharge coefficient (C = 2.2) results in a total Spillway discharge capacity of 626.3 m³/s. The discharge capacity curve based on a dynamic C is shown in Figure 8 below and it is recommended for use.

Table 19: Discharge equations used to determine the spillway discharge capacity





Figure 8: Discharge Capacity of the Spillway determined using a dynamic discharge coefficient

7.2. Freeboard Requirements

It was revealed in the preceding chapters that Roodefontein Dam is a category III dam with significant hazard potential. The 2011 SANCOLD guidelines on Freeboards dictate that the total freeboard of the dam should comprise of the influence of the following components; RDD surcharge, Wind wave run-up; Wind set-up; Surge and Seiches; Earthquake wave and Flood outlets.

The selected Freeboard input parameters are shown in Table 20 below. Detailed calculation of the freeboard requirements are presented in Addendum F.

Table 20: Freeboard	input parameters
---------------------	------------------

FREEBOARD INPUT PARAMETERS				
PARAMETER	VALUE			
Wind speed (m/s) (Fig 2.3-4 SANCOLD)	24			
Fetch (m)	1110			

7.2.1. Flood surcharge

The results of RDF routing reveal that the maximum discharge has a stage of 1.18 m. The reduced level is 43.48 m above mean see level as discussed in the preceding chapters.

7.2.2. Wind Wave run-up

The wind wave run-up (R) = H_s × A × $\xi_p \times \gamma_r \times \gamma_b \times \gamma_h \times \gamma_\beta$ = **0.690** m. Values of the parameters A, γ_r , γ_b , γ_h and γ_β are 1.6, 1, 1, 1 and 0.85 respectively.

7.2.3. Wind set-up

The wind setup for the dam (n_w) = $0.5 \times (\rho_{\alpha_{10}} / \rho_{\omega}) \times C_D \times (U_{10})^2 / (g \times h_{ave}) \times F = 3.508$ m.

7.2.4. Surge and Seiches

The component of surge and seiches is taken as 0 m.

7.2.5. Earthquake Wave

The earthquake component in case of Roodefontein is taken as 0 m.

7.2.6. Land slide

The surrounding slopes of the reservoir are relatively flat and therefore the probability of a land slide is negligible and therefore the freeboard component of this condition is 0 m.

7.2.7. Available Freeboard

In Table 5 it was established that the available freeboard is 3.7 m.

7.2.8. Freeboard Combinations

Freeboard combinations for category III dams are given in table 3.1 of the SANCOLD guidelines on freeboard and it has been reproduced in Table 21 of this report for the convenience of the reader. Combination number 2 and 5 are the severe cases with freeboard requirement of 5.068 m. Based on the available freeboard and the calculated value (5.1 m) it can be concluded that the dam does not have enough freeboard. An additional 1.37 m is required to ensure that the dam satisfy minimum freeboard requirements.

Combination number	RDD Surchage	Wind wave and run- up 100-year event	Wind set-up	Surges and seiches	Earth-quake wave	Land-slide wave	Flood outlets	TOTAL (m)
1	1.18	0.38						1.6
2	1.18	0.38	3.508	0				5.1
3					0			0.0
4						0		0.0
5	1.18	0.38	3.508	0			0	5.1

Table 21: Freeboard combinations

7.3. Drawdown Capacity

7.3.1. Available Drawdown Rate

Roodefontein Dam has 7000 mm steel pipe which branches into a 5000 mm and a 6500 mm outlets. The invert level of the 7000 mm pipe is at RL 32.0 m. The upstream side of the outlet pipe is controlled by a plate flap valve while the downstream is controlled by a butterfly valve and a sleeve valve. The outlet works statistics is summarised in Table 22, below.

Table 22: Outlet works statistics for Roodefontein Dar	n.
--	----

Lowest invert level	RL 32.0 m
Size of outlet pipe	700Ø mm NB encased steel pipe
Downstream control	500 NB isolating valve and 300 NB sleeve valve
Upstream control	Plate flap valve

Volume - Elevation data contained in the operation, monitoring and maintenance manual was used to estimate the outlet capacity. The orifice condition has given an average discharge capacity of 3.26 m^3 /s at FSL meanwhile the pipe condition has an average discharge capacity of 2.11 m^3 /s. Refer to the rating curve as shown in Figure 9, below. The pipe condition should be used in assessing the outlet capacity, since it is more conservative than the orifice condition. Refer to Addendum G for detailed calculations of drawdown.



Figure 9: Outlet works Rating curve

To empty the active storage of the dam (that is lowering the reservoir level from full supply level to the lowest invert level) it will take 16 days. Eight (8) days are required to evacuate the top third of the reservoir as shown in Figure 10 and Table 23. The top third of the reservoir normally contain 50% or more of the total active volume in a v - shaped reservoir. As a rule of thumb, lowering the top third of the reservoir should halve the hydrostatic load on the dam wall and results in slowing down of a progressing failure mode, (Courtnadge, 2017).



Figure 10: drawdown curve

Table 23: Capacity of installed low level outlet works

DRAWDOWN CAPACITY					
Installed drawdown rate (m ³ /s)	$Q_{\rm D} = 2.1 {\rm m}^3/{\rm s}$				
Installed drawdown rate (%H/day)	4.8 %				
Installed drawdown rate (mm/day)	491 mm/day				
T _{33%} of the reservoir (m)	3.4 m				
RL of T _{33%}	38.9 m				
Time to clear T _{33%}	7.79 days				
Time to evacuate the active volume	16 days				

7.3.2. The Theoretical Drawdown Capacity

Literature on drawdown capacity indicates that the main function of the facility is to lower the reservoir in order to arrest a detected failure mode. The relevant failure mode for drawdown facility is internal erosion in the case of Roodefontein Dam.

7.3.2.1. Hydraulic Gradient

The height of water level at FSL is 14.3 m above river bed and the width of the embankment's base is calculated to total 94 m. These two parameters lead to a hydraulic gradient equal to 0.15, see Table 24.
Table 24: Hydraulic gradient of the dam

HYDRAULIC GRADIENT		
Height of reservoir - H (m)	14.3 m	
Width of the embankment's base - L (m)	94.0 m	
Hydraulic gradient – I (H/L)	0.15	

7.3.2.2. Hole Erosion Index (I_{HET})

Internal erosion is driven by the erodebility of construction material which is assessed using the erosion rate index (I_{HET}). The detection of the erosion is a function of the frequency of surveillance.

The core of the dam is made of Sandy Clay material with 15% plasticity and classified as a low plasticity clay material (Mayer, 200:20) as shown in Table 25. This material used for the construction of the clay core has an erosion rate index of 3.5 as read from the Erosion Rate Index figure, see addendum F.

Table 25: Soil properties for the embankment

	SOIL PROPERTIES
Soil properties for clay core	Sandy Clay; PI = 15%; LL = 27% Classified as CL
Erosion rate index - I _{HET}	3.5

From the theoretical drawdown rate curves, the erosion rate index of 3.5 and hydraulic gradient of 0.15 do not intercept. This might suggest that the used material does not have the ability to form a roof support, meaning the failure mode might not progress to breach. This in essence suggests that the construction material has a self-healing ability.

7.3.3. Drawdown Activation Time

The dam uses a manual activation system for the rapid drawdown. The emergency preparedness plan is silent on the time it takes the operator to travel from his/her base to the dam parking area and then walk into the intake tower to activate drawdown procedure. It is assumed that the activation process will take 3 hours and this assumption will be validated at a later stage. Refer to Table 26 for the used activation parameters for Roodefontein Dam.

ACTIVATION TIME			
Type of drawdown activation method	Manual		
Distance from Dam Operator's base to the dam	Not know		
Time to activate the drawdown process	3 hours		

Table 26: Drawdown activation parameters

7.3.3.1. Telecommunication at the dam

The ability of the operator to communicate with the supervisor/authorised person to activate drawdown procedure within reasonable time plays a vital role in the evaluation of drawdown capacity. Dams located in remote areas with limited network coverage prove to be problematic in the event of emergencies.

At the time of writing this report, major telecommunication companies in South Africa were Telkom SA, Vodacom, MTN and CellC.

The CellC website as accessed on 13 February 2019 showed that there is 3G coverage on the right side of the dam and most parts of the left side of the dam, see Figure 11.



Figure 11: CellC coverage map at Roodefontein Dam ((https://www.cellc.co.za/cellc/coverage-map :13/02/2019))

Vodacom website showed that the dam and the surrounding areas have at least 3G coverage as shown in Figure 12.



Figure 12: Vodacom coverage map around Plattenberg Bay. (https://www.vodacom.co.za/vodacom/coverage-map: 13/02/2019)

MTN on the other hand, has very limited network coverage at the dam and the surrounding area as shown in Figure 13. At the time of writing this report, the Department of Water and Sanitation had a contract with Vodacom SA to provide telecommunication devices to qualifying employees. It was therefore assumed that the operator of the dam has a Vodacom device at the time of writing this report.



Figure 13: MTN network coverage around Roodefontein Dam (https://www.mtn.co.za/Pages/Coverage_Map.aspx : 13/02/2019)

7.3.3.2. Access Roads

The dam can be access from the right side of the spillway through a gravel road. This gravel road has been constructed from good material and drainage seems to be working fine. The Operator should not have difficulties accessing the dam to activate the drawdown procedure.

7.3.4. Frequency of Surveillance

The operating and maintenance manual indicates that the dam is inspected every five (5) years, three (3) months, and randomly in-between. In section VI (4) of the manual, it is stated that in the event of strong overflow on the spillway, the dam should be inspected daily. In section VI (5) of the same manual, the operator is encouraged to inspect the dam on weekly basis. However, in section V (2), the operator is directed to record reservoir water level on daily basis while the reservoir is higher or equal to RL 43.0 m. it was noticed in the manual that section IV emphasises the 3 month intermediate inspections and too silent on the weekly/daily routine inspections. The inspection frequency is summarised in Table 27.

FREQUENCY OF SURVEILLANCE		
Major inspection	5 Yearly	
Intermediate inspection	3 monthly	
Routine inspection	Weekly	
Special inspection - A	Daily – When there is a strong overspill	
Special inspection - B	Daily – When Water Level is above RL 43.0 m	

Table 27: Surveillance frequency at Roodefontein Dam

7.3.5. Evaluation criteria for drawdown capacity

The criteria used to evaluate the adequacy of the installed drawdown capacity are based on USBR guide and the Environmental Agency. The criteria is summarised in Table 28 for the convenience of the reader.

Table 28: Drawdown capacity evaluation criteria

Evaluation Criteria			
Reference	Criteria		
EA, Table 6.2 ¹	Minimum rate of 5%H/day and a maximum of 1m/day	515 mm ≤ H ≤ 1000 mm	
USBR	Evacuate 75% of Height in 10 to 20 days		

¹Guide to drawdown capacity for resevior safety and emergency planning, Volume 1 . A Courtnadge etl (date not known).

7.3.6. Final evaluation of the installed drawdown capacity

The installed drawdown facility has a rate of 491 mm/day which is smaller than the required 515 mm/day. However, the facility is able to lower the top third of the dam in 8 days (7.8 days) which is quicker than the USBR recommended minimum of 10 days.

The used construction material for the core seem to not have the ability to form a roof support and therefore should internal erosion progresses, it will not reach the breach stage, that is; the material will collapse and heal itself. However, the collapsed pipe might lead to the localised settlement of the crest/NOC which intern will reduce the registered height of the freeboard.

The network coverage is fairly ok; the operator should be able to communicate with authorities to seek permission to activate drawdown procedure in the event of an emergency after getting to the site.

The access road to the site as discussed previously is in fairly good condition and it should not hinder the operator under emergency or during the performance of surveillance.

The documented weekly inspection could be problematic should a failure mode start a day after inspection. This means that the failure mode has 6 days to continue undetected.

The drawdown capacity at Roodefontein seems to be adequate.

8. MONITORING AND INSTRUMENTATION

In section – V of the Operation, Monitoring and Maintenance Manual it is directed that leakage flow, reservoir water level, Spillway discharge, deformation (Levelling), Rainfall, Draw-off from the reservoir and stability of the left flank above the spillway should be monitored. The Operation, Monitoring and Maintenance Manual will be referred to in this report as *The Manual*. All monitoring records are attached in addendum H.

8.1. Seepage Monitoring

It is stated in section V (1) of The Manual that leakage flow should be estimated and recorded. Records of seepage measurements were not available, however there is extensive seepage emanating from the right flank.

8.2. Water Level Monitoring

Section V (2) of *The manual* states that the reservoir water level should be recorded on weekly basis under normal operation. In the event where the reservoir water level exceeds reduced level 43.0 m, the record should be taken on daily basis. The operator of the dam did not have this information.

8.3. Spillway Discharge Monitoring

In section V (3) of The Manual, it is prescribed that periodic flows over the spillway and high reservoir water level reached should be recorded. The operator of the dam did not have this information.

8.4. Deformation Monitoring

A topographic survey of the dam showed that the crest experienced a maximum settlement of 420 mm between Chainage 76 and 93. Along the non-overspill crest, there are uneven settlements. Refer to Addendum H for survey data.

8.5. Rainfall Monitoring

Section V (5) of The Manual prescribes that rainfall recorded should be taken on daily basis. The operator of the dam did not have this information.

8.6. Draw-off from the Reservoir Monitoring

In section V (6) of *The Manual*, it is stated that draw-off volumes from the reservoir should be recorded on weekly basis. Records were not available.

8.7. Stability of Left Flank

Colour photographs of the left flank at and above the spillway should be taken every August of each year as stated in section V (7) of *The Manual*. These photographs should be taken standing 150 m from the spillway. The owner and the operator of the dam were unable to provide the evaluators with evidence supporting execution of this requirement.

9. STRUCTURAL ANALYSIS

9.1. Stability of the Embankment

9.1.1. Properties of the Embankment

The details of the embankment were discussed in details in the previous chapters. The relevant properties of the embankment for stability analysis are the upstream slope of the dam, which has a gradient of 1 v: 3 h on average and the downstream has 1v:2 h. The upstream slopes are protected by Rip-rap against erosion and the downstream slopes are protected by normal Rockfill.

9.1.2. Soil Properties of Embankment

The used soil properties for determination of stability analysis were obtained from the design report: *Raising the full supply level of the dam by 2.0 m* and are listed in Table 29. The author could not locate a document which has in-situ soil properties of the used material during the raising and therefore simply used the worst case soil properties as defined by Watermeyer.

SOIL PROPERTIES USED FOR STABILITY ANALYSS				
	Unit Weight		Cohesion	Angle of Friction
	Ysaturated	YunSaturated	С	φ
Core Material 1	22	20	5	24
Core Material 2	22	20	5	24
General Fill	22	20	2	24
Rockfill/Gravel Toe	22	20	0	40
Sand Filter	22	20	0	35
Foundation Material	18	16	0	30

Table 29: Soil properties used for stability analysis (Watermeyer, 2002:12)

9.1.3. Embankment Slope - Safety Factors

The calculated safety factors of embankment stability are provided in Table 30. There is a 6% difference between the new values and the old values determined by Watermeyer on load case 5. No comparison was done for load cases 2, 3 and 4 since Watermeyer did not present his outcomes for these load cases. The 2006 and the 2011 (Second and Third) dam safety evaluations did not produce new calculations; rather they cited values from Watermeyer.

The calculated values are lower than those of the stability criteria and Watermeyer recommended that after the raising of the dam, in-situ material properties should be determined to evaluate the final stability of the dam. The results of such a study were not available at the time of compilation of this report. Detailed calculations of safety factors are attached in addendum I.

EMBANKMENT SAFETY FACTORS					
Sido	Load Condition		Safety Factors		Limit
Side	Luau Cunu	luon	Watermeyer	Siwelani	
Downstream	FSL	Load case 1	1.3	1.30	1.5
Downstream	FSL, EQ	Load case 2	-	0.99	1.2
Upstream	FSL	Load case 3	-	1.76	1.5
Upstream	FSL, EQ	Load case 4	-	1.05	1.2
Upstream	RDD	Load case 5	1.0	1.07	1.2

Table 30: Factors of safety for the embankment slopes

9.2. Stability of the Spillway

The Ogee concrete spillway at the dam is 3.72 m height measured from the downstream side of the dam. The total bottom width that has an influence in stability determination is 5.84 m. Detailed dimensions of the raised spillway are contained in drawing number 150193/06: Spillway Sections and Details. Figure 14 is a simplified sketch of the spillway cross-section.



Figure 14: Cross-Section of the concrete spillway

9.2.1. Assumptions

The assumptions made in determining concrete stability of the spillway are shown in Table 31 below. It was further assumed that the tail water level is at zero height in order to neglect the positive influence of this component. The iffluence of ice has not been considered since the area where the dam is located does not experience ice with 25 mm thickness. Detailed calculations have been attached in addendum I.

ASSUMED PARAMETERS FOR CONCRETE STABILITY ANALYSIS			
Parameter	Value		
Unit weight of water	9.81 KN/m ³		
Unit weight of concrete	24 KN/m ³		
Area reduction factor	1		
Submerged unit weight of sediments	18KN/m ³		
Angle of friction for sediments	30°		
Cohesion of foundation	1500 KN/m ²		
Angle of friction for foundation	59.53°		

Table 31: Assumed parameters for concrete stability analysis

9.2.2. Stability Evaluation

Watermeyer performed a comprehensive stability analysis in 2002 during the raising of the full supply level for Roodefontein Dam. The results were evaluated for the purposes of this evaluation and remain valid. Details of his estimates are covered in Annexure D of a report titled *Raising the full Supply Level (FSL) of the Dam by 2.0 m by means of solid raising: Design Report.*

10. CHECKING OF REGISTRATION INFORMATION

10.1.Dam Safety Office Record

The registration information as captured by Dam Safety Office was evaluated and found to be valid and accurate. There are no revisions required. A copy of the information is attached in Addendum J.

11. EVALUATION OF HAZARD POTENTIAL

11.1.Dam Classification

Roodefontein Dam is classified as a category three (3) dam with a higher hazard potential. The summary of the categorising information is provided in Table 32.

Table 32: Classification data of Roodefontein Dan

CATEGORIZATION OF THE DAM			
Size class:	Medium		
Hazard potential rating as classified:	High		
Category	III		
Do you agree with the rating?	Yes		

11.2. Failure Modes Analysis

The following sub-sections of the report will briefly discuss identified potential failure modes relevant to Roodefontein Dam.

11.2.1. Internal Erosion

Roodefontein Dam like any other embankment dam is susceptible to internal erosion. One of the threats or initiators of internal erosion could be high floods increasing the loading on the earthfill embankment. Alternatively, deterioration of construction material could lead to internal erosion under normal operation conditions. The dam has a clay core, vertical chimney, horizontal blanket and a Toe drain. This indicates that modern dam engineering philosophy was followed during the design and construction of the dam.

In the event where the core initiates internal erosion, the vertical chimney constructed from Beacon Beach Sand should stop the clay material from washing out and prevent internal erosion from progressing. The newly raised section of the core is constructed from sandy clay with low plasticity and it does not have the ability to form a roof support, therefore internal erosion should not progress to breach stage.

The contact area between newly constructed sandy clay core and the old clay core is concerning in broad terms. This area can lead to cracking consequently contact internal erosion. However, in the case of Roodefontein Dam, the vertical chimney drain should prevent the clay material from escaping as mentioned above.

Internal erosion failure mode for Roodefontein Sam is credible and significant, therefore should be analysed in details under dam break analysis. The Environmental Agency, stipulated that probability of dam failure due to internal erosion ranges between 1×10^{-10} .

11.2.2. Slope instability

Slope instability can be initiated by reservoir loading, rapid drawdown or saturation as results of either overtopping or heavy rain.

11.2.2.1. Slope instability due to Overtopping

The calculated freeboard of the dam seems to be insufficient as discussed in the previous sections. This increases the probability of dam failure due to downstream slope saturation as a result of overtopping. The estimated probability of dam failure due to slope instability as a consequence of saturation is 1.03×10^{-06} .

11.2.2.2. Slope instability due to rainfall

Plattenberg Town has an average annual rainfall of 930 mm. The probability of dam failure due to saturation of downstream slopes by rainfall is relatively low. This failure mode is credible but not significant.

11.2.2.3. Embankment Slope instability due to rapid drawdown

The calculated factor of safety for rapid drawdown condition is 1.1 which is lower than the modern limit of 1.2. The dam under this condition satisfies the laws of equilibrium and therefore instability of upstream slope due to rapid drawdown is not expected. It should be noted that this failure mode is credible but not significant.

11.2.2.4. Embankment Slope instability due to loading

The calculated safety factor for normal operation loading is 1.3 and 1.76 for downstream and upstream slopes, respectively. Modern dams have a minimum safety factor of 1.5 (Jansen 1988) for both the downstream and upstream slopes under normal loading. The downstream slope of this dam is below the required 1.5. Since the loading conditions satisfy equilibrium condition in favour of stability, the failure mode is credible but not significant under normal loading.

Under extreme conditions with earthquake loading, the upstream slope has a 1.05 safety factor. Under these conditions, the dam satisfies the laws of equilibrium and therefore, the failure mode is credible yet insignificant.

11.2.2.5. Spillway Overturning

The hydrostatic force, uplift, silt load, ice and wave loading could result in the spillway overturning should they exceed the counter weight and tail water loading of the spillway. The calculated factor of safety against overturning for the spillway is found to be 3.05 and the probability of the structure overturning is 2.8×10^{-05} .

11.2.2.6. Spillway Sliding

The same loading as discussed above could result in sliding of the spillway. The calculated factor of safety against sliding is 1.87 and its probability is 1.03×10^{-06} .

11.2.3. Erosion

Embankment dams are susceptible to erosion; hence a form of protection is required. Erosion can be caused by heavy rain, reservoir wave and flood waves as a result of overtopping of the NOC.

11.2.3.1. Earthfill erosion due to rain and reservoir waves

It was discussed in the previous chapters that the upstream slope is protected by means of 550 mm thick layer of riprap comprising of boulders ranging from 350 mm to 550 mm. The riprap is constructed on a 400 mm thick bedding layer comprising of 250 mm to 150 mm material. A 300 mm secondary bedding layer was constructed to prevent the earthfill from eroding through the 400 mm layer.

The downstream slope is protected by means of 250 mm thick layer of rockfill. The probability of earthfill erosion due to rainfall is too low, therefore, making the failure mode credible but insignificant.

The upstream slope protection seems to be thick enough and well graded. The probability of earthfill erosion due to reservoir waves is 1×10^{-4} .

11.2.3.2. Earthfill Erosion due to Overtopping of NOC

The flood waves are powerful enough to erode the downstream rockfill slope protection and the earthfill should overtopping occurs. In the event of overtopping of the NOC, the crest will experience backward erosion and create a passage for the reservoir water to evacuate uncontrolled.

These flood waves and the escaped reservoir water will transport earthfill material, this process should it continue, the embankment dam will breach at some point. Roodefontein Dam does not have enough freeboard as calculated in this report and therefore the probability of failure due to this failure mode is high, credible and significant. The probability of the dam failing due to overtopping is 1.4×10^{-06} .

11.3. Dam Break Analysis

During this fourth dam safety evaluation, dam break modelling was not conducted. The risk analysis of the inundated area is based on the 2002 dam break model that was performed by Watermeyer and presented in his design report for the raising of the fully supply level by 2.0 m by means of solid raising.

11.3.1. Inundation

The flood wave converges into the 1:100 flood plains 4.2 km downstream of the dam. The estimated time for the flood wave to reach 4.2 km is 38 minutes, meaning that this wave has an average speed of 1.8 m/s to inundate the section.

The area after this convergence point should not be affected in terms of socioeconomic disadvantages or suffers any fatalities since municipal by-laws prohibits construction of buildings within 1:100 flood plains. Watermeyer's results of a dam break flood analysis are shown in Table 33.

DAM BREAK RESULTS				
Distance Downstream of the Dam	Peak Flood Flow Surface Level above Mean sea Level	Time to reach the Location		
(km)	(m)	(minutes)		
0.7	30.7	22		
1.0	25.3	23		
1.2	22.3	24		
1.5	18.0	25		
1.75	14.6	26		
2.1	10.1	27		
3.0	9.0	32		
3.4	7.2	34		
3.6	8.6	35		
4.2	8.5	38		

Table 33: Dam break results (Watermeyer, 2004:N.9)

11.4. Consequences of Dam Failure

In the third dam safety evaluation, Hattingh suggested that the population at risk in 2011 ranged between 376 and 750 people. Direct monetary losses were estimated between R300 and R350 million. Socio-economic impact was selected as high and ecological status was class C. The current impact analysis of a dam failure on economy, environment, health of people and ecology is covered in the following subsections.

11.4.1. Economic Consequences

To estimate the economic consequences of dam failure the author analysed the landscape within the flood plains. One structure (Horse stable) was added to the inundated area since 2004. Therefore, the only varying parameter becomes inflation and the cost of this structure. It is estimated that the horse stable will cost about R 2 million to replace.

Since 2011, annual national inflation fluctuated between 5.0 and 4.5 and the average inflation value is 5.3 as shown in Table 34. To quantify the current economic costs associated with failure of Roodefontein Dam the average inflation value and the economic costs reported by Hattingh in his 2011 report were used. This resulted in revised economic cost ranging between R 458 million and R 533 million.

South African Inflation (2011 - 2018)				
Year	Annual Inflation (%)	Economic Cost (million)		
2011	5.0	300	350	
2012	5.6	317	370	
2013	5.7	335	391	
2014	6.1	355	414	
2015	4.6	372	434	
2016	6.4	395	461	
2017	5.3	416	486	
2018	4.7	436	509	
2019 (March)	4.5	456	531	

Table 34: South African Annual Inflation from 2011 to 2018 (Statistics South Africa)

11.4.2. Environmental Consequences

In general, dam failures have high environmental consequences and Roodefontein Dam is not exceptional to this concept. The expected level of erosion and destruction of the vegetation downstream of the dam and well a loss of aquatic life is expected to be of higher order.

11.4.3. Loss of Life

Due to the tourism status of this area, there number of lives that can be lost in the event of a dame failure is estimated be between 15 and 30.

11.4.4. Social Consequences

The social impact caused by failure of Roodefontein Dam remains high since Plattenberg and the surrounding areas are tourist's locations.

11.4.5. Ecological Consequences

The ecological state has not been review, therefore remains as class C as stated in the third dam safety evaluation report.

11.5. Evaluation of Emergency Preparedness Plan

The first Emergency Preparedness Plan (EPP) compiled by Watermeyer in 2004 has a hybrid format, that is; it combines the internal and external protocol to be followed in

the unfortunate case of an emergency. In the EPP, a map showing access roads is attached so is a contour map showing potential areas which will be affected by flooding. Contact details of different authorised personnel and external organisations that handle emergency situations have been provided in page N.6 to N.8.

The recent Emergency Preparedness Plan was compile by Weidemann and Horn in 2015. This copy has updated contact details of downstream dwellers that will be affected by a dam failure and contact details of emergency services have also been included.

Precise action to be taken by the operator has been stated clearly and in a simplified format. The internal protocol has been well covered in this copy of the EPP.

11.6. Summary of Hazard Potential

Table 35 gives a summary of impact associated with failure of Roodefontein Dam. Most of the information in Table 35 was extracted from the previous dam safety evaluation report. The previously estimated 24 number of people who might lose their lives due to dam failure has been retained in this report because of the newly built horse stable immediately downstream of the dam wall.

RISK ANALYSIS RESULTS				
Risk analysis level:		Level 0		
Trigger event of failure:		Sunny Day Failure		
Probability of failure:		5 x 10 ⁻⁴ and 5 x 10 ⁻⁵		
Analysis method:		Dam Break Analysis		
Population at risk:		750		
Estimated loss of life:		Between 15 and 30		
Financial Loss	Directly:	R 458 million to R 533 million		
	Indirectly:	R 4.6 million to R 5.3 million		
Economic Losses		High		
Environmental Losses		High		
Social Impact		High		
Ecological Loses		Class C		

Table 35: Risk analysis results of Roodefontein Dam

12. INSPECTION OF THE DAM

12.1. Dates and Details of Evaluators

The fourth dam safety inspection of Roodefontein Dam took place on 25 September 2019. The author, the Approved Professional Person, and other officials as listed in Table 36 conducted the inspection.

DETAILS OF PERSONNEL				
NAME	ROLE & RANK	COMPONENT / ORGANIZATION		
Mr Siwelani, RW	Author, Candidate Engineer	DSS*		
Mr Mahlabela, CN	APP, Chief Engineer	DSS		
Mr Kgopiso, JM	Evaluator, Pr.Technician	DSS		
Mr Mabale, TI	Evaluator, Pr Technologist	DSS	WS	
Mr Mothlagomang, LW	Evaluator, Pr Technician	DSS		
Mr Desai, T	Evaluator, Candidate Engineer	DWSRO**		
Mr Mouton, D	Evaluator, Candidate Engineer	DWSRO		
Mr Janse Van Rensburg, L	Evaluator, Pr Technician	DWSRO		
Mr Weidemann	Evaluator, Area Manager	DWSRO		
Ms Samuel, FL	Evaluator, Pr Eng	BM***		
Mr Tarentaal, R	Evaluator, Pr Eng	BM		
*DSS - Dam Safety Surveillance. **DWSRO - Dept. of Water & Sanitation Regional Office. *** BM - Bitou Municipality				

Table 36: Team members who conducted visual inspection of the dam

12.2. Weather and Water Level

On 25 September 2019, the skies were clear (Figure 16) around the dam with temperatures below 30 °C. On the inspection date, the gauge plate was at 9.8 m (Figure 15). Weather records revealed that on 24 September 2019 there was 10 - 50 mm rain in Plattenberg Bay. A summary of the weather data and Inspection dates is provided in Table 37 below.

Table 37: Inspection data of Roodefontein Dam

VISUAL INSPECTION DATA			
Date:	25 September 2019		
Gauge Plate reading:	About 9.8 m (Figure 15)		
Had it recently rained?	Yes, on 24 September 2019. Rain Intensity: 10 - 50 mm		
Describe weather:	The skies were clear		



Figure 15: Gauge Plate reading



Figure 16: Clear Weather at the dam on 25 September 2019

- 12.3. Dam Site
- 12.3.1. Surrounding Terrain

The dam site is located in a mini-valley, with both the right and left sides having densely vegetated steep slopes as shown in Figure 17 and Figure 18, below.



Figure 17: A densely vegetated hilly left side of the reservoir's surrounding



Figure 18: A densely vegetated hilly right side of the reservoir's surrounding

The valley opens up on the downstream side of the dam. This side of the dam has recreational facilities comprising of a golf course, and a newly built horse stables, refer to Figure 19 below.



Figure 19: A valley downstream side of the dam with a newly built horse stables

12.3.2. Access to dam site and Lighting of dam wall

The dam site is accessible through Piesang Valley Road which connects to the National Route - N2. On Piesang Valley Road, 1.9 km off N2, there is a local gravel road on the right, leading to the dam site. Distance from Piesang Valley Road to the Dam site is estimated at 2.4 km. Refer to Figure 20 below.

The inspection team did not locate any form of lighting installations on the dam wall



Figure 20: Access Route to Roodefontein Dam.

12.3.3. Access to the dam

The dam is within a cluster of private properties and a security-controlled gate is utilised through one of the private properties to access the dam wall. However, members of these private properties have uncontrolled access to the dam site and wall.

12.4. Operational Health and Safety

12.4.1. The Safety Boom

There is no safety boom installed at the dam, see Figure 21.



Figure 21: Side view of the spillway showing a lack of safety Boom

12.4.2. Safety

The stairway on the upstream slope leading to the gauge plate is relatively steep and it does not have railing, see Figure 22. This setup might expose officials working at the dam to a danger of falling. The evaluation team did not observe any unsafe practice on the day of inspection nor find evidence proving that there is unsafe practice at the dam.



Figure 22: Stairway leading to the gauge plate.

12.5. Evaluation of Dam Owner's Operation and Maintenance Programme

12.5.1. Dam Safety Logbook

Officials at the dam did not have a copy of a Civil Logbook on the day of the inspection. However, a generic copy of the logbook is available in Pretoria and it will be made available.

It was stated that the operator of the dam, Mr R Tarentaal has not attended the *Water Control Officer Course* which would assist him in executing his operational duties more efficiently.

12.5.2. Operation and Maintenance manual

The owner of the dam has a copy of the operations and Maintenance (O&M) manual in place. The first O&M Manual was produced in 1998, an update was approved in 1990 and the latest copy was approved in 2005, see Figure 24 & Figure 23. On the day of the inspection, copies of these documents were in Pretoria offices of the Owner and on - site. Officials from Bitou Municipality did not have copies of these documents, however a disk with electronic copies of the documents was provided to them during the site inspection.



12.5.3. Emergency Preparedness Plan (EPP)

The dam owner has an Emergency Preparedness Plan (EPP) in place. The lasted copy was approved in 2015 and the older copy was approved in 2005, see Figure 25 & Figure 26. On the day of inspection, officials at the dam had a copy of the 2015 EPP. The 2015 EPP is valid and the contact details are valid.



12.6. Non Overspill Crest (NOC)

12.6.1. NOC Properties

As-Built drawing No. 150195/06 (WA166401/020) indicates that a 20 mm layer of gravel protects the non-overspill crest. During the inspection it was realised that grass has been incorporated and it performed satisfactory in protecting the NOC, see Figure 27.



Figure 27: Non - Overspill crest of Roodefontein Dam.

12.6.2. Defects

The visual inspection revealed that there is no settlement, cracks or ponding on the crest and the cross fall was not visible.

12.6.3. Undesirable Elements and Activities

There is evidence of ratting caused by vehicle wheels on the crest, see Figure 27 above. The only found evidence concerning animals is the presence of ants at their early stage as shown in Figure 28; however, at this stage these activities are not critical to an extent of causing a dam failure.



Figure 28: Ants activities on the crest

12.7. Upstream Slope of Dam Wall

12.7.1. Vegetation Growth and Slope Protection

On the upstream slope, a 500 mm layer of Rip-Rap provides protection to the slopes. This layer is built on a 400 mm bedding layer consisting of 150 - 250 mm crusher. Both layers are in good condition and the material quality is excellent.

On the day of inspection, the slopes had some isolated vegetation as can be seen in Figure 29 and Figure 30 below. The quantity and height of this vegetation should not cause any failure of the dam. However, the Owner of the dam should clear this vegetation regularly.



Figure 29: Isolated vegetation on the upstream slope.



Figure 30: Upstream slopes of the dam wall.

12.7.2. Defects

On the upstream slope, the evaluators did not find any evidence consistent with bulging, sliding, cracking, or erosion.

12.7.3. Animal or Termite Activities and Footpath

The evaluators did not find any evidence concerning animal or termite activities nor vehicles and footpaths.

12.8. Downstream slope of Dam wall

12.8.1. Vegetation growth

The area downstream of the outlet works has been kept well with grass trimmed correctly. The area close to the spillway has a few bushes, see Figure 31 and Figure 32. Despite the bushes, the overall condition of the downstream slope as far as vegetation growth is concerned is satisfactory.



Figure 31: Some vegetation on the downstream slope of the wall.



Figure 32: View of the dam wall showing some bushes on the downstream slope.

12.8.2. Slope protection

A layer of crimping grass protects the downstream slopes, see Figure 33 and Figure 34 below. As mentioned in the previous sub-section, the grass layer was well taken care off and it was performing satisfactory.



Figure 33: View of the downstream slope from the toe.



Figure 34: Grass protection on the downstream slope of the dam.

12.8.3. Defects

The team could not satisfactorily evaluate the existing horizontal crack due to the grass cover see Figure 35.

The evaluation team did not find any evidence to prove the existence of erosion, bulging, wet patches, and seepage leaks. Furthermore, there were no signs of animal activities, vehicle pathways, or footpaths.



Figure 35: Existing horizontal crack covered by grass on the downstream slope.

12.9. Downstream Toe and Flanks

The dam does not have a conventional toe drain system. The study of existing as-built drawings, existing reports, and the physical inspection of the dam confirmed the nonexistence of the toe drain. On the toe there is surface water drain in a form of unlined channel, see Figure 36.



Figure 36: Strong vegetation growth in the Toe-Channel.

On the day of inspection the unlined channel had overgrown vegetation, see Figure 36 above. The vegetation was consistent with the presence of water.

Downstream of the right flank, a sizeable amount of seepage was observed, see Figure 37. The seepage water collects behind the outlet house and is channelled through a small channel which connects to the toe-channel, see Figure 38.



Figure 37: Seepage from the right flank day lighting next to the outlet house



Figure 38: Seepage water channel to a Toe-Channel and discharge in the river

12.10. Other observations

A lined-channel from the downstream property discharges into the toe-channel of the dam and therefore, the amount of water ponding downstream of the dam increases due to this new structure, see Figure 39.



Figure 39: Lined Surface drain from the downstream property discharging into the Toe-Channel

12.11. Spillway

12.11.1. Spillway Approach Channel

Previous reports indicate that the left flank experienced a slip failure in the past. Material from this failure was deposited in the approach channel, see Figure 40 and Figure 41 below. The influence of these deposits on the dam should be investigated.



Figure 40: Spillway approach channel.

Other than the material deposits from the slip failure, there is no additional loose material in the approach channel.



Figure 41: material deposit due to a slip failure on the right flank

12.11.2. Conditions of concrete

On the day of inspection water level was below the full supply level, allowing the team to closely inspect the spillway, see Figure 42 and Figure 43 below. The concrete used on the spillway is intact with no signs of major cracks or seepage.



Figure 42: Side view of the spillway



Figure 43: Concrete conditions of the Staling Basing

12.11.3. Defects on the Spillway

On the downstream left side of the spillway, one of the concrete panels exhibits signs of minor movement as can be seen in Figure 44.

Other than these minor movements, there are no signs of significant cracking, significant movement or settlement on the spillway.



Figure 44: Signs of minor concrete panel movement.

12.11.4. Stability of the Walls

All the walls around the dam looked stable with no signs of elements which could result in instability.

12.12. Outlet Works

Detailed inspection of the outlet works is covered in the appended Electro-Mechanical Report. The roof of the outlet house has been damaged and it requires repair work, see Figure 45.



Figure 45: Damaged roof of the outlet house

12.13. Other Observation

12.13.1. New Infrastructure

A new horse stable has been constructed on the downstream side of the dam. This new structure is located less than 100 m from the toe of the dam, see Figure 46 and Figure 47.



Figure 46: A horse stable constructed on the downstream of the dam wall



Figure 47: View of the downstream taken from the NOC.

12.13.2. Contractual Arrangement

During the inspection, it was indicated that there is no formal contractual arrangement between the Department and the Operator (Bitou Municipality). This lack thereof, negatively affects the safe operation of the dam.

12.14. General observations

In general, the physical conditions of Roodefontein Dam are satisfactory. However, the evaluation revealed that certain components of the dam do not meet the requirements of Dam Safety Regulations, Regulation 139 of 24 February 2012.

12.15. Mechanical Evaluation

A physical inspection of mechanical and electrical components was conducted on 11 February 2020. The mechanical report reveals that conditions of outlet works are reasonable and the outlet works are functioning satisfactorily. However, the required maintenance work was not performed due to a lack of maintenance contractor (Kolorovic, 2020). The electro-mechanical report makes the following:

- The shaft on the isolating gate valve is bent and it is difficult to operate, therefore, it must be repaired or replaced as soon as possible.
- The upstream valve must be repaired since it is not sealing.
- The indication on the wheel is missing and must be rectified.
- The front seal rubber on the sleeve valve is damaged and must be replaced.
- The sleeve valve must be refurbished since is in poor conditions.
- Open and close indicator must be installed since the original ones are missing.
- Repair the corrosion protection on the underwater manifold.
- Investigate alternatives for the manifold outlet works.
- Introduce a mechanical logbook to ensure good maintenance programme.
- Drawings of the new outlet works must be submitted to Strategic Asset Management as soon as possible for record keeping.

13. CONCLUSION

13.1. Contractual arrangement

The lack of a formal contractual arrangement between the Owner of the dam (Department of Water and Sanitation) and the Operator (Bitou), Municipality negatively affects the safe operation of the dam.

13.2. Freeboard

The dam does not have sufficient freeboard to safely pass the recommended design flood of 95 m^3/s .

13.3. Outlet House

The outlet house has been damaged and repair work is required.

13.4. Toe Drain

The current unlined Toe-Channel is performing satisfactorily in conveying seepage water, however, it create saturation on the toe of the dam.

13.5. Private drainage channel

The newly constructed private drainage channel discharges into the unlined Toe-Channel of the dam and therefore contributes into saturation of the toe of the dam.

13.6. The newly constructed horse stable

The newly constructed horse stable, few meters downstream of the toe of the dam affects the risk profile of the dam. The Department might be exposed to financial claim should the dam fails.

13.7. Crack on the earthfill embankment

The horizontal crack on the earthfill embankment seem to have stabilised/stopped, however, the cause root for the cracks is still unknown.

13.8. Embankment stability

The calculated downstream safety factor is 1.3 under full supply level - loading and therefore does not satisfy the required minimum of 1.5.

13.9. Concrete panel on the spillway channel

The movement of concrete panel on the left side, downstream of the spillway could be an indication of earth movement.

13.10. Safety Boom

The lack of a safety boom could result in a public safety noncompliance if boats are allowed at the dam.

13.11. The Civil Logbook

The absence of the Civil Logbook prevents the efficient operation of the dam.

13.12. Water Control Officer Course

The operator of the dam conducts his duties without the required training provided through the Water Control Officer Course. This lack of training has a potential to limit the officer from effectively discharging his duties.

14. RECOMMENDATIONS

14.1. Outstanding from Previous Inspection

There are few outstanding recommendations from the previous evaluation report and these are summaries in *Table 38* below.

Table 38: Recommendations not implemented from the previous Dam Safety evaluation.

UN PF	I-ATTENDED RECOMMENDATIONS FROM THE REVIOUS INSPECTION REPORT (S)	RESPONSIBLE OFFICE	TIME FRAME
1.	Survey of the slope failure on the left bank, upstream of the spillway.	SAM	ASAP
2.	The drainage canal upstream at the toe of the dam should be cleaned and kept clean as part of the routine maintenance at the dam.	BM	Regularly
3.	Investigate the rehabilitation of natural slope failure behind the outlet house.	SAM	ASAP

14.2. New recommendation from this Inspection

Table 39 gives a breakdown of dam safety related recommendations stemming from this evaluation. The times indicated in column three (3) of *Table 39* should be taken from the date at which the Dam Safety Office approves this report. Recommendations having substantial financial implications have been given a minimum of 3 year for completion. Column three (3) of *Table 39*, titled time means the maximum time recommended to conclude the activity. The authors have noted that at the time of writing this report, the owner was in a process of appointing a service provider to rehabilitate the dam.

Table 3	39: Dam	safetv	related	recommendations

DA	M SAFETY RECOMMENDATION	RESPONSIBLE OFFICE	TIME
1.	All recommendations from the mechanical report should be implement as indicated in the report.	See Report	SR
2.	Complete the outstanding recommendations from the previous evaluation as repeated in Table 38 of this report.	See Table 38	12 months
3.	Formalise the contractual arrangement between the Owner (Department of Water and Sanitation) and the Operator of the Dam (Bitou Municipality) to allow for legal delegation of powers and efficient operation of the dam.	DDG: IBOM	12 months
4.	Increase the freeboard of the dam to ensure compliance with 2011 <i>Guidelines on Freeboard for Dams.</i>	SAM	3 Years
5.	Repair the damaged roof of the outlet house.	BM & SO	12 months
6.	Install a proper toe drain system to manage seepage on the downstream of the dam.	SAM	3 Years
7.	Install a lined - channel on the toe of the dam to collect run- off water from the toe of the dam and discharge in the river.	SAM	3 Years
-----	---	---------	-------------
8.	Install guardrails on the stair-way leading to the gauge plate to improve safety of personnel working at the dam.	SO	3 Year
9.	Request owners of the property immediate downstream of the dam to re-rout the newly installed surface drain away from the dam to avoid saturating the toe of the dam which might trigger slip failure of the earthfill embankment.	SO & BM	immediately
10.	Department should determine an appropriate action concerning the newly built horse stable downstream of the earthfill embankment.	DG	12 months
11.	Rehabilitate the earthfill embankment in order to address the horizontal crack on the embankment and the slope instability.	SAM	3 Year
12.	Monitor survey beacon F13 on the downstream left side of the spillway channel for a possible movement of the support material.	SO & BM	Quarterly
13.	Install a safety boom upstream of the spillway	SO & BM	1 Year
14.	Provide a Civil Logbook	SAM	3 Months
15.	Provide training to the Operator of the dam	SAM	1 Year

BM - Bitou Municipality | SO - Department of Water and Sanitation: Southern Operation SAM - Strategic Asset Management | DDG:IBOM – Deputy Director General: Infrastructure Branch

15. REFERENCES

Bosman, D.E., Basson, J., Tente, T. and Basson, G.R. (2011) Guidelines on Freeboard for Dams Volume 2, South African Water Research Commission, Gezina.

Brink, J.A. (2006) *Roodefontein Dam: Second Dam Safety Inspection Report*, Department of Water and Sanitation, Pretoria.

Chadwick, A., Morfett, J. and Borthwick, M. (2004). *Hydraulic in Civil and Environmental Engineering, Fourth edition*. London.

Davis, G.N. (2006) Roodefontein Dam: Engineering Geology Report for Dam Safety Purposes, Department of Water and Sanitation, Pretoria.

Department of Water and Sanitation, (2012) *Dam Safety Regulations – Notice R139 of 24 February 2012*, Pretoria.

Environmental Agency (2017) *Guide to drawdown capacity for reservoir safety and emergency planning:* Volume 1 & 2, Bristol.

Environmental Agency (2013) *Guide to risk assessment for reservoir safety management:* Volume 1 & 2 (RARS), Bristol.

ICOLD (2017) Bulletin 164: Internal Erosion of Existing Dams, Levees and Dikes, and their Foundations, Paris.

Jansen, R.B (1988) Advanced Dam Engineering for Design, Construction, and Rehabilitation, Van Nostrand Reinhold, New York.

Kantey and Templer, (1996) *Roodefontein Dam: Rehabilitation of Spillway - Final Geotechnical Report*, Ninham Shand, Cape Town.

Kantey and Templer, (1995) *Roodefontein Dam: Rehabilitation of Spillway - Preliminary Geotechnical Report*, Ninham Shand, Cape Town.

Knappett, J.A. and Craig, R.F. (2012) *Craig's Soil Mechanics* 8th edition, Spon Press, London and New York.

Hattingh, L.C. (2011) *Third Dam Safety Evaluation Report*, Department of Water and Sanitation, Pretoria.

Pells, H.N.F. (1996) Roodefontein Dam: The Effect of an Earthquake on the Dam, Department of Water and Sanitation, Cape Town.

Powrie, W.E. (1987) *Roodefontein Dam: Design Report*, Department of Water and Sanitation, Pretoria.

Rademeyer, P. (2018) Roodefontein Dam: Flood Frequency Analysis – Estimates of Flood Peaks for Required Probability, Department of Water and Sanitation.

USBR (2014) Appurtenant Structures for Dams (Spillway and Outlet Works), Design Standard 14, Denver.

USBR 2014, Embankment Dams - Design Standard No. 13, Denver.

USBR (2014) Appurtenant Structures for Dams (Spillway and Outlet Works), Design Standard 14, Denver.

USBR (1990) Criteria and Guidelines for Evacuating Storage Reservoirs and Sizing Low-Level Outlet Works, Denver.

Watermeyer, C.F. (2004) Construction Completion Report: Raising the Spillway and Embankment of Roodefontein Dam, Department of Water and Sanitation, Pretoria.

Watermeyer, C.F. (2004) *Operation, Monitoring and Maintenance Manual and Emergency Preparedness Plan*, Department of Water and Sanitation, Pretoria.

Watermeyer, C.F. (2002) *Raising the Full Supply Level (FSL) of the Dam by 2.0 m by Means of Solid Raising*, Department of Water and Sanitation, Pretoria.

Watermeyer, C.F. (2000) Completion Report – Contract No. PB/SS/200, Department of Water and Sanitation, Pretoria.

Watermeyer, C.F. (1994) *Dam Safety Inspection Report*, Department of Water and Sanitation, Pretoria.

Weidemann, E.W. and Horn, H. (2015) *Roodefontein Dam: Emergency Preparedness Plan,* Department of Water and Sanitation, Pretoria.

https://www.cellc.co.za/cellc/coverage-map :13/02/2019

https://www.vodacom.co.za/vodacom/coverage-map: 13/02/2019

https://www.mtn.co.za/Pages/Coverage_Map.aspx: 13/02/2019

16. **ADDENDA**

- 16.1. Addendum A: Access and Locality Map
- 16.2. Addendum B: As-Built Drawings
- 16.3. Addendum C: Geology
- 16.4. Addendum D: Hydrology Report
- 16.5. Addendum E: Flood routing
- 16.6. Addendum F: Freeboard Calculations
- 16.7. Addendum G: Drawdown Capacity
- 16.8. Addendum H: Monitoring Data
- 16.9. Addendum I: Stability Analysis

Addendum A: Access and Locality Map



DATE: 2017/08/31

TOWN: PLETTENBERG BAY

COORDINATES: 23°20'5.7"E 34°3'59.3"S



Addendum B: As-Built Drawings

RAISED ROODEFONTEIN DAM

1502021	SYSTEM	WG.23 Y	Х	Stud Level 06.01.2005	;]		DRG. No.	REFERENCE	DRAWINGS	
	DAM1	-30786.129	11324.100	46.194		1	NATE	R LEVEL =	39,80	m
	DAM2	-30798.369	11333.898	44.674			ON O	5.01.2005	*	
	LF1	-30967.717	10946.632	46.038		(G	AUGE	PLATE READ	NG = 7,	51 m)
	LF3	-30984.223	10963.457	41.992		- V	ALVE	CHAMBER	DATUN	1
V	OD1	-30980.885	10970.344	39.434			EVEL	= 30,637 m	(Stud in F	=100r)
	·0D2	-30975.255	10981.848	39.438						
	OD3	-30967.533	10998.591	39.390						
	RF1	-30942.766	11003.789	44.252						
	RF2	-30952.848	11008.488	44.226						
	RF3	-30961.570	11012.549	44.252						
	RF4	-30944.950	11009.883	46.005						
	STNLNN	-30993.741	10945.983	45.472						
	STNRNN	-30716.297	11277.904	52.307						
	SV4.4	-30941.475	11008.515	45.907						
	SV60	-30905.823	11051.168	46.104						
	SV120	-30867.335	11097.214	46.133						
	SV180	-30828.857	11143.250	46.144						
	SV240	-30790.378	11189.285	46.158		NO ⁻	<u>TE:</u>			
438/30	SV300	-30751.892	11235.321	46.169		1. U	BTAINE	OF EARTH EME D FROM KANTE	ANKMEN Y & TEMF	I PLER/
	L1	-30955.493	10974.403	42.323					G NO. 460	J1 L1 32
	L3	-30960.363	10964.046	42.335		2. v	EADING	EVEL: 39.80m; 7.51m (6 JANU	ARY 2005	5)
	R2	-30950.544	10985.329	42.347		Z	RE	CORD DRAWING	OCT. 2004	•
	R3	-30945.517	10996.024	42.341		1	ISEUED			2
	WTL	-30739.168	11224.808	39.798		REV	ISLUED	DESCRIPTION	DATE	CHKD APPRV
				+ 10800	X	DES	SIGNED	CW		













					DESIGNED	кт
					DRAWN	FB
					CHECKED	HE
					PROJ. ENG.	HE
					PROJ. MANAGER	AT
DRG. No.	REFERENCE DRAWINGS	REV	DESCRIPTION	DATE		
	REFERENCE DRAWNGS		REVISIONS		 APPROVED :	

ji i

.

•

, ji

•

• *

•

. ~

•

.

ø

•

(**•** 1

•

and and in south the sec





1 1 **\$**

· · · · · · .





** ** *******

	95. tif /03/14
	DRG. No. REFERENCE DRAWINGS WA166401/015 SPILLWAY RAISING LAYOUT WA166401/016 SPILLWAY ELEVATION & LONG. SECTION WA166401/017 SPILLWAY SECTIONS & DETAILS WA166401/018 SPILLWAY SECTIONS & DETAILS
· · · · · · · · · · · · · · · · · · ·	
	NOTE: DETAILS OF EARTH EMBANKMENT OBTAINED FROM KANTEY & TEMPLER/ NINHAM SHAND DRAWING No. 4601 CT 3Z
	0 ISSUED FOR CONSTRUCTION APR. 2002 REV DESCRIPTION DATE CHKD APPRV DESIGNED CW 01/10/2004 DRAWN NJ 01/10/2004 CHECKED JK 01/10/2004
	PROJ. MANAGER KT 01/10/2004
GRAVEL ROAD SURFACING (ZONE8) TO LEVEL 44.0 AND REPLACED T3 DISPERSIVE SANDY CLAYEY SILT FILI OF SAND CHIMNEY WITH TOPSOIL N RIGHT OF CHIMNEY	PO BOX 1480 KNYSNA, SOUTH AFRICA 6570 Tel: (044) 382 5293 Fax: (044) 382 6577 Email: ssikny@mweb.co.za APPROVED: DATE
CHIMNEY ZONE 3 ND BETWEEN .0 AND 44.0 TOPSOIL OR A MIXTURE OF BOTH THICK LAYERS ALTERNATING WITH GRAVEL (ZONE 7).	SCALES RELATE TO A SIZE A1 DRAWING 1.7. Watermayer / APP. OCTOBER 2004
42.00	PROJECT/DRAWING TITLE ROODEFONTEN DAM PLETTENBERG BAY
THU////////////////////////////////////	EMBANKMENT RAISING, ROCK RIP-RAP REVETMENT
	SCALE SHT. No. 1 OF 1 CONTRACT No. PROJECT No. WA166401 DRAWING No. REV
DDAWING SIZE . A1 DI OT SCALE .	WA166401/020

Addendum C: Geology



Council for Geoscience

Private Bag X112 Pretoria 0001 SOUTH AFRICA 280 Pretoria Street Silverton Pretoria Reception: +27 (0)12 841 1911 Internet: http://www.geoscience.org.za

 Reference: K602/02

 Enquiries: GN Davis

 Tel: 012 336 7519

 Fax: 012 336 8050

 E-mail: gdavis@geoscience.org.za

24 March 2006

DEPARTMENT OF WATER AFFAIRS AND FORESTRY P/BAG X313 PRETORIA 0001

Chief Engineer: Civil Design Directorate (Attention: Dr A Bester)

Roodefontein Dam: Engineering Geological Report for Dam Safety Purposes

The latest list of dams for which engineering geological reports for dam safety purposes are required, as received from the Civil Design Directorate, Department of Water Affairs and Forestry, refers.

A dam safety report entitled "Roodefontein Dam. Plettenberg Bay. Dam Safety Inspection. Geotechnical Report" by Knight Hall Hendry and Associates (Reference SSI 95 G), dated 11 August 1993, has been submitted previously.

The main findings of this report, as well as other reports as listed below, may be summarized as follows:

- The geological conditions at the Roodefontein Dam appear well documented. Geological investigations were conducted prior to construction and this geological report was finalized after completion. A construction completion report was also compiled.
- * The embankment is founded on a succession of alluvial materials, comprising clayey to sandy silt material with gravel layers, underlain by stiff clay and silt derived from weathering of the underlying Kirkwood Formation mudrock strata (*Note, however, the available geological maps indicate the strata as belonging to the Enon Formation*). The core contact is reportedly founded on siltstone across the full width of the valley.

Note also the alluvium contained peat layers up to 4 m in thickness. While the exposed peat layers were reportedly removed and replaced with selected fill, doubts have been expressed that some of this compressible material could have remained beneath the embankment (Knight Hall Hendry, 1993).

 Major slope instability had occurred during construction on the northern slope flanking the spillway excavation, and failures were expected to continue. Detailed analysis concluded the slope is marginally stable with a minimum FOS of 1 (Kantey & Templer, 1996). * Two areas of seepage were noted, namely 1) an area of stagnant water at the downstream toe, and 2) wet conditions at the base of the cut slope behind the valve chamber.

ő.

Additional geological / geotechnical information which has become available since the abovementioned dam safety report includes the following;

- A final geotechnical report was compiled after repairs and rehabilitation of the spillway following erosion damage (Kantey & Templer, 1996¹)
- Results of an investigation into the seismic risk and the effects of a possible earthquake on the dam (Ninham Shand, 1996²). For the analysis a MCE was assumed to equal a peak ground acceleration of 0.07g. The report concluded the overall stability of the structure was unlikely to be affected, although minor settlement could occur.
- Recently published seismic hazard maps³, however, indicate a Peak Ground Acceleration (PGA) of approximately 0.05g, with a 10% probability of being exceeded in a 50-year period. This might be considered a low level of seismic hazard.

Roodefontein Dam was visited by the undersigned, in the company of Mr Muvhuso Musetsho of DWAF, on 16th March 2006. At the time the reservoir level was very low (gauge plate reading 0.95 m). Observations from this site inspection, conducted in intermittent rain, include the following:

- A longitudinal crack is present at the break in slope immediately to the north of the spillway (Plate 1). It is not certain whether this is a new phenomenon, or is that referred to by Kantey & Templer (1996). Minor scarps just visible in the heavily wooded northern slopes do not appear to be new features and are considered to represent earlier slope movements. It is not known whether the installed inclinometer is still operational.
- Reed growth along the embankment toe indicates a measure of seepage, although there was no visible flow. The previously-noted area of seepage behind the valve chamber is still present; this in spite of the low reservoir level. It might be concluded that the seepage is not derived from the reservoir itself but rather from the right flank.
- Although trees growing on the embankment have been felled in the past, dense infestations of Port Jackson are again springing up – along the crest as well as on the downstream face near the spillway.
- There is no evidence of any erosion downstream of the concrete-lined chute. However, it is not known whether the dam has spilled since rehabilitation of the spillway.
- Of concern are a number of sub-parallel horizontal cracks near the crest of the downstream face of the embankment (Plate 2). Although partly obscured by the dense growth of Kikuyu grass, these cracks are up to 100 mm wide at surface and

² Ninham Shand (Cape). March 1996. Roodefontein Dam: The Effect of an Earthquake on the Dam. Report to Provincial Administration Western Cape. Community Services Branch. Report No 2488/4601.

¹ Kantey & Templer. 1996. Roodefontein Dam: Rehabilitation of Spillway. Final Geotechnical Report. Report No G5335 to Provincial Administration Western Cape. Community Services Branch.

³ Kijko, A, Graham, G, Bejaichund, M, Roblin, D & Brandt, MBC. 2003. Probabilistic Seismic Hazard Maps for South Africa. Council for Geoscience.

might be traced for a significant length along the face (Plate 3). It is surmised that the origin of these cracks is linked to material placement and / or compaction during construction. These cracks suggest there has been some degree of downslope movement. At present the cracks provide for enhanced water ingress into the downstream face of the embankment. Note that the thick grass cover precluded detailed observation of the depth of these cracks, and it is not certain to what extent there has been any associated downslope movement. It might also be noted that the slope of the downstream face is estimated at approximately 30° (1:1.7), while available sections indicate a flatter gradient of approximately 22° (1:2.5).



Plate 1: The longitudinal crack (indicated by the red lines) at the break in slope immediately to the north of the spillway, indicating some movement in the slope.



Plate 2: A general view of the downstream face of the embankment. Immediately apparent are the horizontal lines visible near the crest which closer inspection reveals to be prominent cracking.



Plate 3: A closer view of the prominent cracking. Although largely hidden by the dense grass cover, at surface these cracks are almost 100 mm in width.

It is recommended that the longitudinal cracks on the downstream face be investigated more closely, including the embankment geometry and confirmation whether downslope movement is occurring. This would necessitate that the grass be cut short so as to enable detailed observation and surveying.

GN Davis Manager: Engineering Geosciences

Addendum D: Hydrology Report





FLOOD FREQUENCY ANALYSIS ESTIMATION OF FLOOD PEAKS FOR REQUIRED PROBABILITIES



Piesang river at Roodefontein dam February 2018



DEPARTMENT: WATER AND SANITATION

PROBABILISTIC, DETERMINISTIC AND EMPIRICAL EVALUATION OF THE CATCHMENT, RAINFALL AND FLOW DATA FOR THE ESTIMATION OF FLOOD PEAK PROBABILITIES, FOR ROODEFONTEIN DAM

REPORT DETAILS

Title:	Flood Frequency Analysis for Roodefontein Dam
DWS no.:	K602/02
Report no.:	K600-R001-2018.02
Report status:	Final
Date:	February 2018
Prepared by:	Directorate: Surface and Ground Water Information Component: Flood Studies
Prepared for:	Directorate: Strategic Asset Management Sub-directorate: Dam Safety Surveillance

ENDORSEMENT

Flood Studies team:

P Rademeyer Analyst and Reporter Professional Scientist

D van der Spuy Report Supervisor (APP) Specialist Engineer

BACKGROUND

The Sub-Directorate: Dam Safety Surveillance requested the Component: Flood Studies to do a flood frequency analysis on Roodefontein dam (K602/02) for dam safety purposes.

Roodefontein dam is situated in the Piesang river about 2.5 km west (as the crow flies) of the town Plettenberg Bay in the Western Cape Province. The dam was mainly constructed for domestic and industrial use.

THE CATCHMENT

Roodefontein dam has a total catchment area of 28 km². The catchment receives rainfall throughout the year and the mean annual precipitation was estimated at 930 mm.

The surface hydrology of the catchment consists of various streams of which the longest stream originates \approx 280 m.a.s.l. in the most western part of the catchment. The longest stream measures \approx 14.80 km in length and the time of concentration for the catchment was estimated at 3.5 hours.

The basic vegetation cover consists mainly of dense- and thin bush with some cultivated land areas. The catchment soils are largely deemed to be very permeable to semi-permeable.

THE DAM

Roodefontein dam was completed in 1989 and raised in 2004. The dam is an earthfill dam with an ogee spillway on the left hand side. The total crest width is 315 m. The dam has a wall height of approximately 18 m and a capacity of 2.069×10^6 m³ at full supply level 43.91 m RL / 10.07 m GP. The surface area of the lake formed by the dam at FSL is ±37 hectares.

Roodefontein dam is classified as a category 3 dam of medium size with high hazard potential.

RECOMMENDED FLOOD FREQUENCIES

		Exceed	ance probabi	ity (%)		
50	20	10	5	2	1	0.5
S		Flo	od peaks (m ^a	/s)	a na an	
8	20	30	45	65	80	95

SEF

In accordance with the SANCOLD guidelines, following this site specific analysis, it is recommended that a safety evaluation flood (SEF) equal to 530 m^3 /s be considered for this catchment.

INDEX

INDEX OF TABLES AND FIGURES

LIST OF SYMBOLS AND ABBREVIATIONS

REPORT

1.	INT	RODUCTION	1
1 1 1	.1. .2. .3.	BACKGROUND THE CATCHMENT THE DAM	1 1 1
2.	AVA	AILABLE INFORMATION	2
2 2	.1. .2.	RESULTS FROM PREVIOUS ANALYSES	2 2
3.	FLO	OD FREQUENCY ANALYSIS	3
3 3 3	.1. .2. .3.	INTRODUCTION CATCHMENT RAINFALL DETERMINISTIC METHODS	3334
3. 3. 3. 3.	.5. .6. .7. .8.	STATISTICAL METHODS	1 1 5 5
4.	RM	F AND SEF	5
4. 4.	1. 2.	ASSESSMENT	5
5.	BIBI	LIOGRAPHY	1

APPENDICES

Α.	ROODEFONTEIN	DAM AND	CATCHMENT
----	--------------	---------	-----------

- B. CATCHMENT RAINFALL
- C. DETERMINISTIC METHODS
- D. EMPIRICAL METHODS
- E. STATISTICAL METHODS
- F. HYDROGRAPHS

J

iii-iv

V

INDEX OF TABLES AND FIGURES

REPORT

į

Tables	
Table 2-1: Results from previous analyses	2
Table 2-2: Flood peaks on record (> 25 m ³ /s)	2
Table 3-1: Catchment rainfall	3
Table 3-2: Estimated flood peaks – Deterministic methods	3
Table 3-3: Estimated flood peaks – Empirical methods	4
Table 3-4: Estimated flood peaks - Statistical methods	4
Table 3-5: Recommended flood peaks	5
Table 4-1: RMF	6
Table 4-2: Properties of coastal dams in the K drainage region	6

the second s

INDEX OF TABLES AND FIGURES

APPENDIX

n

Tables
Table A-1: Catchment characteristics and informationA-3
Table B-1: Rainfall stations usedB-2
Table B-2: Catchment rainfall (ARF not applied)B-3
Table B-3: Catchment rainfall (ARF applied)B-3
Table B-4: Catchment rainfallB-3
Table C-1: Rainfall parameters for ½tc C-1
Table C-2: Rainfall parameters for tc C-1
Table C-3: Rainfall parameters for 2tc C-1
Table C-4: Runoff coefficients for the Rational method C-2
Table C-5: Parameters for the SCS method C-2
Table C-5: Estimated flood peaks Rational method C-2
Table C-6: Estimated flood peaks – DRH method C-2
Table C-7: Estimated flood peaks – SUH method C-3
Table C-9: Estimated flood peaks – SCS method C-3
Table D-1: Estimated flood peaks – Empirical methods D-1
Table D-2: RMFD-1
Table E-1: Compiled inflow flood peak record for Roodefontein damE-1
Table E-2: Estimated flood peaks – Statistical methodsE-2
Table E-3: Information about available recordE-3
Table E-4: Statistical propertiesE-3
Table E-5: Results of fitted distributionsE-3
Table F-1: Recommended flood peaks – Roodefontein damF-1
Table F-2: DRH method volumesF-2
Table F-3: SUH method volumesF-3
Table F-4: Coordinates of the August 2006 hydrographF-7
Table F-5: Coordinates of the November 2007 hydrographF-8
Table F-6: Coordinates of the July 2012 hydrographF-9
Table F-7: Coordinates of the September 2015 hydrographF-10

Figures

þ

Figure A-1: Catchment location and layout	. A-2
Figure E-1: Graphical comparison of data points and distributions	E-2
Figure F-1: DRH hydrographs	F-2
Figure F-2: SUH hydrographs	F-3
Figure F-3: Flood hydrograph of August 2006	F-4
Figure F-4: Flood hydrograph of November 2007	F-4
Figure F-5: Flood hydrograph of July 2012	F-5
Figure F-6: Flood hydrograph of September 2015	F-5
Figure F-7: DRH vs observed hydrographs	F-6
Figure F-8: SUH vs observed hydrographs	F-6

LIST OF SYMBOLS AND ABBREVIATIONS

А	-	Catchment area (km²)
ARF	-	Areal reduction factor
CAPA	-	Catchment parameter (2002) method
D	-	Storm duration
DRH	-	Direct Runoff Hydrograph method
DWS	-	Department of Water and Sanitation
EP	-	Exceedance Probability (%)
FSL	-	Full Supply Level (m)
GP	-	Gauge Plate level (m)
HG	-	Hydrograph
HRU 1/71	-	Midgley and Pitman (1971) method
i	-	Rainfall intensity (mm/hour)
К	-	RMF region
Ke	-	Effective Francou-Rodier value
k	-	Storm runoff factor
L	-	Longest watercourse (km)
MAP	-	Mean annual precipitation (mm)
MASL	-	Meters above sea level
MIPI	-	Midgley and Pitman (1972) method
Р	-	Catchment rainfall (mm)
Pe	-	Effective catchment rainfall (mm)
Q	-	Flow (m ³ /s)
RL	-	Relative Level (m)
RMF	-	Regional Maximum Flood (Kovacs, 1988)
S _A		Mean catchment slope
SL	-	Average slope of longest watercourse
SANCOLD	-	South African National Committee on Large Dams
SAWS	-	South African Weather Services
SCS	-	Soil Conservation Service hydrograph generating technique
SEF	-	Safety Evaluation Flood (SANCOLD)
SRR	-	Smithers Regional Rainfall
SUH	-	Synthetic Unit Hydrograph method
tc	-	Time of concentration (hours)
TR	-	Technical Report (DWS)
WR2005	-	Water Resources of South Africa, 2005 Study
WRC	-	Water Research Commission

v

1. INTRODUCTION

1.1. BACKGROUND

The Sub-Directorate: Dam Safety Surveillance requested the Component: Flood Studies to do a flood frequency analysis on Roodefontein dam (K602/02) for dam safety purposes.

Roodefontein dam is situated in the Piesang river about 2.5 km west (as the crow flies) of the town Plettenberg Bay in the Western Cape Province. The dam was mainly constructed for domestic and industrial use.

1.2. THE CATCHMENT

Roodefontein dam has a total catchment area of 28 km². The catchment receives rainfall throughout the year and the mean annual precipitation was estimated at 930 mm.

The surface hydrology of the catchment consists of various streams of which the longest stream originates \approx 280 m.a.s.l. in the most western part of the catchment. The longest stream measures \approx 14.80 km in length and the time of concentration for the catchment was estimated at 3.5 hours.

The basic vegetation cover consists mainly of dense- and thin bush with some cultivated land areas. The catchment soils are largely deemed to be very permeable to semi-permeable.

Appendix A contains more information on the catchment characteristics.

1.3. THE DAM

Roodefontein dam was completed in 1989 and raised in 2004. The dam is an earthfill dam with an ogee spillway on the left hand side. The total crest width is 315 m. The dam has a wall height of approximately 18 m and a capacity of 2.069×10^6 m³ at full supply level 43.91 m RL / 10.07 m GP. The surface area of the lake formed by the dam at FSL is ±37 hectares.

Roodefontein dam is classified as a category 3 dam of medium size with high hazard potential.

2. AVAILABLE INFORMATION

2.1. RESULTS FROM PREVIOUS ANALYSES

To facilitate comparison the results of this study are also shown in the table below.

Table 2-1	: Results	from	previous	analyses
-----------	-----------	------	----------	----------

			Exceeda	nce probal	bility (%)	A Star	
Report	50	20	10	5	2	1	0.5
Same State State			Floo	d peaks (r	n³/s) -		
Tshehla (2001) 75	15	25	40	50	70	90	105
Roux (2010)	10	25	35	50	70	90	105
Rademeyer (2018)	8	20	30	45	65	80	95

2.2. EXTREME FLOODS

ł

For the period October 1995 to present, the following flood peaks were recorded.

Table 2-2: Flood pe	aks on record	$(> 25 \text{ m}^3/\text{s})$
---------------------	---------------	-------------------------------

Catchment	Catchment Area (km ²)	Inflow peak (m³/s)	Outflow peak (m ³ /s)	Date
		34	25	02/08/2006
Roodefontein	28	35	33	23/11/2007
		27	24	01/09/2015

3. FLOOD FREQUENCY ANALYSIS

3.1. INTRODUCTION

Deterministic, empirical and statistical methods were used in the flood frequency analysis of the Roodefontein dam catchment.

3.2. CATCHMENT RAINFALL

The catchment rainfall was estimated for different storm durations and exceedance probabilities by using site specific (MSR and DCR) and regional (SRR) approaches.

The catchment rainfall results of the DCR approach were used as input for the Rational, DRH, SUH and SCS methods. The results for tc and 1-day are shown below.

Table 3-1: Catchment rainfall

Duration	50	20	10	5	2	1	0.5
	n stadensi A		Re	infall (m	n)	ч и - 1	
ic	43	59	71	83	101	114	129
1-day	60	83	100	117	141	160	181

Appendix B contains more information on the catchment rainfall.

3.3. DETERMINISTIC METHODS

The Rational, DRH, SUH and SCS methods were used to estimate flood peaks for different exceedance probabilities.

$\frac{2}{2}$ (6 $-\frac{1}{2}$			Exceeda	nce probab	oility (%)		4
Method	50	20	10	5	2	1	0.5
	Flood peaks (m ³ /s)						
Rational	11	24	35	48	68	85	104
DRH	14	22	29	37	51	62	75
SUH	3	5	7	9	13	15	19
SCS	7	17	28	40	60	77	97

 Table 3-2: Estimated flood peaks – Deterministic methods

Appendix C contains more information on the deterministic methods.

3.4. EMPIRICAL METHODS

The MIPI, HRU 1/71 and CAPA methods were used to estimate flood peaks for different exceedance probabilities.

			Exceeda	nce probab	ility (%)		
Method	50	20	10	5	2	1	0.5
Set a			Floo	d peaks (m	1 ³ /s)		
MIPI	23	56	87	126	187	241	302
HRU1/71	6	14	21	28	39	49	61
САРА	19	35	49	66	94	115	135

Fable 3-3: Estimated flo	od peaks – Empirical methods
--------------------------	------------------------------

Appendix D contains more information on the empirical methods.

3.5. STATISTICAL METHODS

Inflow flood peaks were estimated for Roodefontein dam, for the period 1995 to 2016, by using a level-pool-routing technique.

The LN, LP3 and GEV_{MM} distributions were considered in the statistical analysis of the compiled inflow flood peak record to estimate the flood peaks for the required probabilities.

Table 3-4: Estimated flood r	beaks – Statistical methods
------------------------------	-----------------------------

	Exceedance probability (%)						
Method	50	20	10	5	2	1	0.5
			Floo	d peaks (m	³ /s)		
STATS	8	20	31	44	62	77	94

Appendix E contains more information on the statistical methods.

3.6. Assessment of results

The data record used in the statistical analysis is 22 years in length and the quality of the data used seems good. The estimates produced by the statistical analysis should therefore be fairly accurate keeping in mind that the data are an observation of the actual stream-flow response of the catchment. Thus, the flood peak estimates produced by the statistical analysis (STATS) were used as the benchmark to compare the results of the deterministic and empirical methods with.

An overall assessment of the results shows that the STATS results compare very well and well with that of the SCS and Rational methods respectively, in the whole exceedance probability range. Both the SCS and Rational methods were specifically developed to estimate flood peaks in small catchments and when used correctly (given reliable input) the methods perform very well in catchments less than 30 km².

4

3.7. RECOMMENDED FLOOD PEAKS

The results of the statistical analysis are proposed for the recommended flood peaks for the Roodefontein dam catchment.



Exceedance probability (%)							
50	20	10	5	2	1	0.5	
			od peaks (m	/s)			
8	20	30	45	65	80	95	

3.8. RECOMMENDED FLOOD VOLUMES

J

The observed hydrographs are recommended for routing purposes.

Appendix F contains more information on the hydrographs and volumes.

4. RMF and SEF

4.1. ASSESSMENT

The regional maximum flood (RMF) was estimated by applying the methodology described in TR137 and is shown in **Table 4-1**.

Table 4-1: RMF

	Catchment Area	Region	Francou-Rodier	Flood peak (m³/s)
RIVIE	28	5.2	5.2	650

Observations from numerous site-specific analyses, taking into account the suggested screening criteria from the SANCOLD guidelines, led Flood Studies to adopt the following approach in order to evaluate the site-specific K-values for the regional maximum flood (RMF) and safety evaluation flood (SEF), respectively labeled as K_e and K_{SEF} :

- Determine the rounded K-value (one decimal) for the forecasted 0.01% (10 000 year) flood peak (K_{0.01%}).
- Analytically evaluate K_{0.01%} also considering the regional K-value (K_{TR137}), observed flood peaks and any other relevant information. Subsequently determine a 'site-specific' K-value (K_e) that is sound and consistent with the site specific analysis.
- The site-specific probable maximum flood is determined by using K_e and the proposed SEF by using K_{SEF} = K_e+ δ (0.1 $\leq \delta \leq$ 0.2)

In the statistical analysis the estimate for the 10 000 year flood peak ($Q_{0.01\%}$) is used as an indicator for the maximum flood that is expected in a catchment. By applying Flood Studies adopted approach the forecasted $Q_{0.01\%}$ estimate of 210 m³/s has a K_{0.01\%} value of 4.0.

The properties of five dams situated in the K drainage region and near the coast were evaluated and are shown in **Table 4-2**.

Dam	Area (km²)	Q _{0.01%} (m ³ /s)	K0.01%	KTR137
Hartebeeskuil	100	885	4.9	5.2
Klipheuwel	11	130	3.8	5.2
Wolwedans	123	1590	5.2	5.2
Ernest Robertson	17	380	4.9	5.2
Garden Route	36	635	5.1	5.2

Table 4-2: Properties of coastal dams in the K drainage region

After careful consideration and taking into account all of the above information, a sight specific K_e value of 4.8 is suggested for Roodefontein dam.

4.2. RECOMMENDATION

After applying the Flood Studies adopted approach (section 4.1) and in accordance with the SANCOLD guidelines, following this site specific analysis, it is recommended that a SEF value of $530 \text{ m}^3/\text{s}$ (K_{SEF} = 5.0) be considered for this catchment.

6
5. **BIBLIOGRAPHY**

Alexander WRJ (1990)

Flood Hydrology for Southern Africa. SANCOLD, Pretoria.

Kovacs ZP (1988)

Regional Maximum Flood peaks in South Africa Technical Report 137, Department of Water and Sanitation, Pretoria.

Middleton BJ & Bailey AK (2005)

Water Resources of South Africa, 2005 Study. WRC Report No. TT 382/08 March 2009, Water Research Commission, South Africa.

Roux MP (2010)

Flood Frequency Analysis Roodefontein Dam Report K600-R001-2010.09, Directorate Surface and Ground Water Information: Component Flood Studies, Department of Water and Sanitation, Pretoria.

Smithers JC & Schulze RE (2002)

Design Rainfall and Flood Estimation in South Africa WRC Report No. K5/1060, 01/12/2002, Water Research Commission, South Africa.

Van Der Spuy D and Rademeyer P (2016)

Flood Frequency Estimation Methods as applied in the DWS Directorate: Surface and Ground Water Information, Component: Flood Studies, Department of Water and Sanitation, Pretoria.

A.1. CATCHMENT LOCATION

Roodefontein dam is situated in the Piesang river about 2.5 km west (as the crow flies) of the town Plettenberg Bay in the Western Cape Province. The dam was mainly constructed for domestic and industrial use.

See Figure A-1 for the catchment location and layout.

A.2. THE CATCHMENT

Roodefontein dam has a total catchment area of 28 km². The catchment receives rainfall throughout the year and the mean annual precipitation was estimated at 930 mm.

The surface hydrology of the catchment consists of various streams of which the longest stream originates \approx 280 m.a.s.l. in the most western part of the catchment. The longest stream measures \approx 14.80 km in length and the time of concentration for the catchment was estimated at 3.5 hours.

The basic vegetation cover consists mainly of dense- and thin bush with some cultivated land areas. The catchment soils are largely deemed to be very permeable to semi-permeable.

The most important catchment characteristics are given in.

A.3. THE DAM

Roodefontein dam was completed in 1989 and raised in 2004. The dam is an earthfill dam with an ogee spillway on the left hand side. The total crest width is 315 m. The dam has a wall height of approximately 18 m and a capacity of 2.069×10^6 m³ at full supply level 43.91 m RL / 10.07 m GP. The surface area of the lake formed by the dam at FSL is ±37 hectares.

Roodefontein dam is classified as a category 3 dam of medium size with high hazard potential.



Figure A-1: Catchment location and layout

Ô

Table A-1: Catchment characteristics and information

)

Place: Roode	ontein dam		Drain	age Region:	K6()G	Latitudo	-34 066670
Watercourse: Piesan	g river		DWS	no.:	K602	2/02	Latitude.	04.00007
Nearest town: Pletter	berg Bay		Hydro	o no.:	K6R	001	Longitude:	23.334370
	-	_						
		CAT	CHMENT	CHARACT	TERISTIC	S		
Catchment Area and	d Slope:							_
Total:	Α	= 28	km ²	Dolomitic	areas in ef	fective catc	nment:	
Ineffective:	A i :	= 0.0	km ²	Part of <i>I</i>	A _e conside	red as dolor	nitic: A _d =	: 0.0 km
Effective:	A _e =	= 28	km²	Reductio	on factor		k =	0.43
Mean steepness of A_e	S _A :	16.60	%	Flood pe	eak reduct	ion coefficie	nt f _d =	1.00
Watercourse proper	ties:							
Longest Watercourse:				Mean S	ope:			
Natural channel	L ₁ =	14.80	km	Mea	n slope o	f L ₁	S ₁ =	0.011683
Overland flow	L ₂ =	0.00	km	Mea	n slope o	f L ₂	\$ ₂ =	0.000000
Total length	L =	14.80	14.80 km Mean slope of L_{total} $S_L = 0$.			0.011683		
Distance to centre of A	L _c =	8.25	km	(distance, a	long chann	el, to a point	closest to the c	entre of catchmen
imo of concontratio								
	_			a. 11. 3		where		
TYPE OF FLOW		TME OF CO	NCENTRATI	ON (nours)		A _e =	28	to calculate 🏾 🏹
Natural channel	$t_{c1} = \tau_{[0.8]}$	7*L1 ² /(10	00*S1)] ^{0.385}	5 3.74		_τ =	1.3	correction accordir to size of A
Overland	t _{c2} = 0,6 *	r * L ₂ / (S ₂) ^{0.5}] ^{0.467}	0.00	3.5	r =	0.20	roughness factor
Artificial channel	t _{c1a} = 0.27	B * Σ (I_i/r	v,)			$I_i = v_i = v_i$	ength of a un velocity in a un	niform reach niform reach
ypical r values Payeme	ent 0,02	Bare soil	0,1 Poorgr	ass 0,3	Average gra	ss & Cultivated	land 0,4	Dense grass 0,8
ainfall-Runoff prop	erties:			c	atchment	coverage a	s required fo	r Rational meth
/eld type zones	HRU 1/72 fig.F1)	1			Rural		Urban	Lakes
Relative Weight (%)		100%			100%		0%	0%
Soil Permeability:	%A	Land-Cov	er:		%A	Rair	ıfall:	(HRU 1/72 fig.C3)
ery Permeable (A)	30%	Forest. De	nse bush &	wood	81%	Mean Ann	ual Rainfall (r	nm) 930
ermeable (B)	30%	Thin Bush	Cultivated	and	16%	Extreme po	int rainfall re	gion * 2
emi-Permeable (C)	39%	Grassland			2%	Coastal (C) or inland	(1) C
mnermeable (D)	0%	Bare surfa	се		0%	Winter (W) or Summer	(5) 6
inpermetable (b)	0,0	bare sunta			070	To area (to	y or ournalier	
	ADDITIO	NAL INFO	ORMATIC	N FOR E	VIPIRICA	AL METHO	DDS	
IIPL Flood regions	HRU 1/72 fig.B.1	3			[RMF region) (1	(R137) 5.2
								5.2

APPENDIX B CATCHMENT RAINFALL

B.1. BACKGROUND

The Flood Studies component utilises four methods in calculating the rainfall for a specified catchment area. These include the maximum station-rainfall approach using catchment statistics (MSRcs), the maximum station-rainfall approach using station statistics (MSRss), daily catchment-rainfall approach (DCR) and the Smithers regional-rainfall approach (SRR). The methodology is summarised below.

B.2. RAINFALL ANALYSIS METHODOLOGY

Maximum Station-Rainfall approach (MSR)

Input:

- Point rainfall record at each available station
- Weighted representative catchment area of each rainfall station (Thiessen polygons)

MSR_{cs} (CS – <u>Statistical analysis on Catchment Rainfall</u>)

Note: Applicable only for patched data

Determine:

- The highest 1-day, 2-day, 3-day ... n-day point rainfall per annum, for each station
- The highest 1-day, 2-day, 3-day ... n-day weighted representative catchment rainfall per annum (Thiessen polygons)
- The highest ½tc, tc and 2tc (storm durations) catchment rainfall per annum
- The estimated storm duration events catchment rainfall, for all exceedance probabilities (statistical analyses)

The ARF-factor applicable to this approach will most probably differ from the existing ARF factor applicable to the next approach.

MSRss (SS - Statistical Analysis on Station Rainfall)

Note: Applicable for either patched or unpatched data

Determine:

- The highest 1-day, 2-day, 3-day ... n-day point rainfall per annum, for each station
- The highest ½tc, tc and 2tc (storm durations) point rainfall per annum, for each station
- The estimated storm duration events point rainfall per annum, for each station, for all exceedance probabilities (statistical analyses)
- The estimated storm duration events catchment rainfall, for all exceedance probabilities (Thiessen polygons)

Apply a suitable ARF-factor to determine the estimated effective catchment rainfall, for all considered storm events and appropriate exceedance probabilities.

Daily Catchment-Rainfall approach (DCR)

Note: Applicable only for patched data

input:

- Point rainfall record at each available station
- Weighted representative catchment area of each rainfall station (Thiessen polygons)

Determine:

- For every day, in each year, the weighted representative catchment rainfall (Thiessen polygons)
- The highest 1-day, 2-day, 3-day ... n-day catchment rainfall per annum
- The highest ½tc, tc and 2tc (storm durations) catchment rainfall per annum
- The estimated storm duration events catchment rainfall, for all exceedance probabilities (statistical analyses)

As this method constitutes an analysis of the catchment rainfall for each day, there is no need to apply an ARF-factor.

Smithers Regional-Rainfall approach (SRR)

The Smithers regional-rainfall approach is a regional scale-invariance model developed for South Africa at the University of KwaZulu Natal. The model is applied through a software package which extrapolates n-day regional rainfall from a database of rainfall stations across South Africa, and provides n-day catchment rainfall frequencies specific to the limits of a defined rainfall area.

In implementing the model, the user defines the area over which the regional rainfall is required. The software generates a raster grid, from which it will then extrapolate n-day point rainfall data from within the specified area to provide point rainfall data for each point of the stipulated raster grid. The user is then able to calculate the average n-day regional catchment rainfall from the raster data obtained from the model.

B.3. RAINFALL ANALYSIS

After a thorough evaluation of the data of the rainfall stations situated in and outside the catchment area of Roodefontein dam, two rainfall stations were used in the site specific (MSR and DCR) rainfall analysis. A regional analysis (SRR) was also done.

Station, number	Data Record	MAP (mm)	Thiessen Polygon (km ²)	Station number	Data Record	MAP (mm)	Thiessen Polygon (km ²)
0014633	1900-2011	1005	22	0014393	1900-2011	645	6

Table B-1: Rainfall stations used

The annual maximums of the downloaded rainfall data were converted to 24-hour depths and thereafter to ½tc, tc and 2tc rainfall depths according to the algorithm described in TR102.

The catchment rainfall was estimated for different storm durations and exceedance probabilities for both the site specific and regional approach. For ease of use only the estimates for tc are shown in **Table B-2** and **Table B-3**.

Method 50	Exceedance probability (%)									
	50	20	10	5	2	1	0.5			
	Rainfall (mm)									
MSR _{ss}	46	64	77	91	109	124	140			
MSRcs	46	63	76	88	106	121	136			
DCR	43	59	71	83	101	114	129			
SRR	30	45	57	69	88	105	124			

 Table B-2: Catchment rainfall (ARF not applied)

For both the MSR and SRR analyses, the appropriate factors for reduction in area (ARF) were applied. The ARF applicable for this catchment and storm duration tc is 0.915.

			Exceed	ance probabi	lity (%)		
Method	50	20	10	5	2	1	0.5
				Rainfall (mm)		
MSR _{ss}	42	59	70	83	100	113	128
MSR _{cs}	42	58	70	81	97	111	124
DCR	43	59	71	83	101	114	129
SRR	28	41	52	63	81	96	113

Table B-3: Catchment rainfall (ARF applied)

From **Table B-3** it is clear that the results from the SRR approach (regional analysis) estimated lower results in the whole range of exceedance probabilities. The results for the MSR and DCR approaches (site specific analysis) compare well.

The rainfall estimates from the DCR approach (site specific analysis) was used as input for the deterministic methods (Table B-4).

		Exceedance probability (%)							
Duration	50	20	10	5	2	1	0.5		
				Rainfall (mm)	1.5.7			
2 ½tc	34	47	56	66	80	91	102		
tc	43	59	71	83	101	114	129		
2tc	51	72	86	101	122	138	156		
1-day	60	83	100	117	141	160	181		

Table B-4: Catchment rainfall

C.1. DETERMINISTIC METHODS

The Rational, DRH, SUH and SCS methods were used to estimate flood peaks for different exceedance probabilities.

C.2. RATIONAL, DRH AND SUH PARAMETERS

The ½tc, tc and 2tc rainfall estimates from the DCR approach (site specific analysis) were used as input for the Rational, DRH and SUH methods and parameters were calculated.

	STATE:		i 🔶 Exceeda	nce probabl	lity (%)		
Parameter	50	20	10	5	2	1	0.5
			Pa	rameter val	ue 🖂 👘		
⁴	34	47	56	66	80	91	102
ARE	1.000	1.000	1.000	1.000	1.000	1.000	1.000
State Sale	0.118	0.146	0.159	0.174	0.194	0.210	0.224
Per se	4.0	6.8	8.9	11.5	15.5	19.1	22.9
	19.429	26.857	32.000	37.714	45.714	52.000	58.286

Table C-1: Rainfall parameters for ½tc

Table C-2: Rainfall parameters for tc

		Exceedance probability (%)										
Parameter	50	20	10	5	2	1	0.5					
	Parameter value											
P (DCR) >	43	59	71	83	101	114	129					
ARF	1.000	1.000	1.000	1.000	1.000	1.000	1.000					
STARK F.S.	0.139	0.164	0.181	0.199	0.223	0.240	0.259					
Per V	6.0	9.7	12.9	16.5	22.5	27.4	33.4					
	12.286	16.857	20.286	23.714	28.857	32.571	36.857					

Table C-3: Rainfall parameters for 2tc

Ĵ

			Exceedance probability (%)					
Parameter.	50	20	10	5	2	1	0.5	
	article and	•	Ra	irameter val	ue			
P, (DCR)	51	72	86	101	122	138	156	
ARF	1.000	1.000	1.000	1.000	1.000	1.000	1.000	
k	0.152	0.183	0.203	0.223	0.250	0.270	0.290	
Pe	7.7	13.2	17.4	22.5	30.5	37.2	45.3	
i	7.286	10.286	12.286	14.429	17.429	19.714	22.286	

Table C-4: Runoff coefficients for the Rational method

	Exceedance probability (%)									
Parameter	50	20	10	5	2	1	0.5			
	-14A 1-		Pa	rameter va	lue					
C	0.116	0.182	0.222	0.258	0.302	0.334	0.363			

C.3. SCS PARAMETERS

The 1-day rainfall estimates from the DCR approach (site specific analysis) were used as input for the SCS method. The following parameters were also used as input:

Table C-5: Parameters	for the	SCS method
-----------------------	---------	------------

Parameter. name	Storm intensity distribution type	Hydrological response zone	Hydrological soll group	Catchment Le mean altitude (m)	MAP (mm)	Lag Time (Hours)	Curve number (final)
Parameter:	2	119	В	180	930	2.10	53.7

C.4. RESULTS

J

Flood peaks were calculated for different exceedance probabilities and storm durations.

Table C-6: E	Estimated	flood	peaks –	Rational	method
--------------	-----------	-------	---------	----------	--------

		Exceedance probability (%)								
duration	50	20	10	5	2	1	0.5			
		Flood peaks (m³/s)								
%tc	9	19	28	38	54	68	82			
te .	11	24	35	48	68	85	104			
2tc	7	15	21	29	41	51	63			

Table C-7: Estimated flood peaks – DRH method

			Exceeda	ince probab	ility (%)	11 A	*
Storm	50	20	10	5	2	1	0.5
GUIGLIVII			Floc	od peaks (m	³ /s)		
½tc	11	19	25	33	44	54	65
tc	14	22	29	37	51	62	75
2tc	12	20	26	34	46	56	68

Table C-8: Estimated flood peaks - SUH method

0

Storm			Exceeda	ince probab	oility (%)		
	50	20	10	5	2	1	0.5
		<u>.</u>	Flog	d peaks (m	1 ³ /s)		
<u> </u>	3	5	6	8	10	13	15
Sin to	3	5	7	9	13	15	19
2tc	4	7	9	11	15	19	23

Table C-9: Estimated flood peaks - SCS method

		Maria Sec.	• Exceeda	ince probab	llity (%)		
duration	50	20	10	5	2	1	0.5
telefisie S.	and the second		Floo	d peaks (m	³ /s)		
tc .	7	17	28	40	60	77	97

D.1. EMPIRICAL METHODS

The MIPI, HRU 1/71 and CAPA methods were used to estimate flood peaks for different exceedance probabilities.

Technically speaking the storm duration for the flood peaks estimated by the empirical methods are unknown, but it is generally accepted that it coincide with storm duration tc.

			Exceeda	ince probab	ility (%)		
Method #	50	20	10	5	2	1	0.5
			Floo	od peaks (m	³/s)		
MIPI	23	56	87	126	187	241	302
HRU 1/71 -	6	14	21	28	39	49	61
CAPA	19	35	49	66	94	115	135

Table D-1: Estimated flood peaks – Empirical methods

D.2. RMF

J

The RMF in **Table D-2** was estimated by applying the methodology described in TR137.

Table D-2: RMF

RMF	Catchment Area (km ²)	Region	Francou-Rodier K	Flood peak (m³/s)
	28	5.2	5.2	650

E.1. DATA

Roodefontein dam has a data record from October 1995 to present. The data of the dam (that include reservoir level data, capacity data, and rating data) were used to compile an inflow flood peak record for the period 1995 to 2016 by using a level-pool-routing technique.

E.2. FLOOD PEAK RECORD

Hydro year	Date	• K6R001	K6R001	Q _{in} data used in analysis
1995/1996	30/11/1995	11	-	11
1996/1997	22/11/1996	20	5.4	20
1997/1998				-99
1998/1999				-99
1999/2000				-99
2000/2001				-99
2001/2002	10/09/2002	4.8	-	4.8
2002/2003	14/11/2002	3.2	-	3.2
2003/2004	24/07/2004	0.7	-	0.7
2004/2005	22/12/2004	23	-	23
2005/2006	02/08/2006	34	25	34
2006/2007	05/03/2007	2.6	-	2.6
2007/2008	23/11/2007	35	33	35
2008/2009	14/11/2008	6.2	-	6.2
2009/2010	15/07/2010	2.2	-	2.2
2010/2011	05/07/2011	14	12	14
2011/2012	14/07/2012	23	15	23
2012/2013	21/10/2012	5.1	3.8	5.1
2013/2014	01/11/2013	5.4	4.3	5.4
2014/2015	01/09/2015	27	24	27
2015/2016	01/11/2015	9.4	7.0	9.4
2016/2017	16/10/2016	1.8	1.1	1.8

Table E-1: Compiled inflow flood peak record for Roodefontein dam

-99 indicates permanent gap in data record

E.3. ESTIMATED FLOOD PEAKS

The combined data record used in the statistical analysis is 22 years in length and the quality of the data used seems to be good. The LN, LP3 and GEV_{MM} distributions were considered in the statistical analysis (STATS) of the compiled inflow flood peak record to estimate the flood peaks for the required probabilities (see **Figure E-1**).

The LP3 distribution was used for the statistical estimates.



Figure E-1: Graphical comparison of data points and distributions

Table E-2: Estimated f	flood peaks –	Statistical	methods
------------------------	---------------	-------------	---------

(C)

Ĵ

Method		Exceedance probability (%)								
	50	20	10	5	2	1	0.5			
		Flood peaks (m ³ /s)								
STATS	8	20	31	44	62	77	94			

Table E-3: Information about available record

		Continuous
Record Length (years)		22
Additional Record Length (years)		
Equivalent Record Length (years)		
Peaks higher than threshold _{max}	(outliers)	-
Valid peaks between thresholds		18
Peaks lower than threshold _{min}	(outliers)	-
Zero flows		-
Missing data (gaps in record)		4
Data not used in analysis (high; low;	zero; missing)	4

Table E-4: Statistical properties

	Untransformed data	Log-transformed data		
Median	7.8			
Mean	12.7	0.8871		
S	11.4	0.4924		
g	0.8273	-0.3919		

AED	154		LN		LPIII		GE\	/ _{MM}	Proposed
AEP	RF.	WT	Q (m ³ /s)	WT	Q (m ³ /s)	WT	Par.	Q (m ³ /s)	Q (m ³ /s)
0.50	2	0.00	8	0.07	8	0.36		11	8
0.20	5	0.84	20	0.85	20	1.44	k	21	20
0.10	10	1.26	33	1.23	31	2.11	0.058	28	31
0,05	20	1.64	50	1.53	44	2.73	1	34	44
0.02	60	2.05	79	1.84	62	3.49	1	41	62
0.01	'D O	2.33	108	2.04	77	4.03	E (y)	46	77
0.005	200	2.58	143	2.21	94	4.56	0.970	51	94
0.002	500	2.88	201	2.41	118	5.21	1	57	118
0.001	1000	3.09	256	2.54	138	5.69		62	1 <mark>38</mark>
0.0005	2000	3.29	322	2.67	158	6.14	var(y)	66	158
0.0002	5000	3.54	427	2.81	187	6.71	0.005	72	187
0.0001	10000	3.72	523	2.91	210	7.13		76	210

Table E-5: Results of fitted distributions

J

F.1. HYDROGRAPH PEAKS

The recommended flood peaks are based on storm duration tc. Hydrograph peaks were also calculated for storm durations ½tc and 2tc. The variation of flood peaks (*var*) with storm duration was taken into account in the following way:

- Calculate the variance (*var*) between the flood peaks of the storm durations ½tc and 2tc and tc respectively using the Rational method. The maximum value should be taken as *var* = 1.000.
- Correct var to obtain var* = (var + 1) / 2. This is necessary to take into account the fact that the representative storm durations for the flood peaks estimated by the statistical and empirical methods are unknown.
- Multiply the recommended flood peaks for tc, and each exceedance probability, by the representative values of var* to get the proposed flood peaks for ½tc and 2tc.

	Philenseniel (Exceedance probability (%)										
Storm	50	20	10	5	2	1	0.5	RMF				
		مىرىغۇرىيە مەربىيە يەك بىرىيەتلەر مەربىيە مەربىيە	مناصوبة المتداشية	Flood pea	<u>ks (m³/s)</u>							
½tc	7	18	27	40	58	72	85	582				
tc	8	.20	30	45	65	80	95	650				
2tc	6	16	24	36	52	64	76	522				

 Table F-1: Recommended flood peaks – Roodefontein dam

F.2. HYDROGRAPH VOLUMES

Stream flow data are available in the Roodefontein dam catchment and therefore the corresponding peaks and volumes of the observed hydrographs were compared with that estimated by the DRH and SUH methods.

F.2.1 DRH HYDROGRAPHS

The 1% exceedance probability hydrographs, as estimated by the DRH method, are shown below. The DRH hydrograph shapes (for each of the storm durations) will stay the same for the other exceedance probabilities. The ratio, of another exceedance probability flood peak and the 1% exceedance probability flood peak, must be applied to the 1% exceedance probability hydrograph coordinates.



Figure F-1: DRH hydrographs

Hydrographs volumes, calculated for different exceedance probabilities and storm durations by using the DRH method, are shown in the table below.

	Exceedance probability (%)										
Storm duration	50	20	10	5	2	1	0.5	RMF			
	Volumes (10 ⁶ m ³)										
½tc	0.069	0.174	0.260	0.392	0.565	0.698	0.825	5.644			
tc	0.098	0.245	0.368	0.551	0.796	0.980	1.164	7.964			
2tc	0.117	0.297	0.444	0.667	0.961	1.183	1.405	9.610			

	Table	F-2:	DRH	method	volumes
--	-------	------	-----	--------	---------

F.2.2 SUH HYDROGRAPHS

The 1% exceedance probability hydrographs, as estimated by the SUH method, are shown below. The SUH hydrograph shapes (for each of the storm durations) will stay the same for the other exceedance probabilities. The ratio, of another exceedance probability flood peak and the 1% exceedance probability flood peak, must be applied to the 1% exceedance probability hydrograph coordinates.



Figure F-2: SUH hydrographs

Hydrographs volumes, calculated for different exceedance probabilities and storm durations by using the SUH method, are shown in the table below.

	Exceedance probability (%)										
Storm duration	50	20	10	5	2	1	0.5	RMF			
uuracion	Volumes (10 ⁶ m ³)										
½tc	0.345	0.864	1.291	1.943	2.802	3.461	4.092	28.000			
tc	0.397	0.993	1.490	2.235	3.228	3.973	4.717	32.277			
2tc	0.359	0.906	1.355	2.036	2.933	3.613	4.289	29.345			

Table	F-3:	SUH	method	volumes
IaNIC	1-3-	3011	methou	volunica

F.2.3 OBSERVED HYDROGRAPHS

The hydrographs of the biggest flood events (biggest peak volume ratios) that occurred in the catchment, and recorded at the dam, are displayed below. The dashed lines indicate the boundaries for the volume calculations.



Figure F-3: Flood hydrograph of August 2006



Figure F-4: Flood hydrograph of November 2007



Figure F-5: Flood hydrograph of July 2012



Figure F-6: Flood hydrograph of September 2015

F.2.4 HYDROGRAPH DATA COMPARED

The observed (recorded) hydrographs peak/volume pairs were plotted against that estimated by the DRH and SUH methods (see **Figure F-7** and **Figure F-8**).



Figure F-7: DRH vs observed hydrographs



Figure F-8: SUH vs observed hydrographs

From Figure F-7 and Figure F-8 above it is clear that the hydrographs estimated by the SUH method compare better with the observed hydrograph than that of the DRH method.

F.2.5 RECOMMENDED HYDROGRAPHS

The observed hydrographs are recommended for routing purposes.

F.2.6 HYDROGRAPH COORDINATES

6

J

Time (hrs)	Flow (m ³ /s)	Time (hrs)	Flow (m ³ /s)	Time (hrs)	Flow (m ³ /s)
0	1.6	38	6.2	76	3.1
1	1.8	39	6.6	77	3.1
2	2.1	40	5.3	78	3.1
3	2.8	41	5.3	79	2.9
4	3.4	42	4.8	80	2.8
5	5.8	43	4.5	81	2.8
6	9.0	44	4.2	82	2.8
7	11.9	45	4.0	83	2.6
8	12.5	46	4.1	84	2.5
9	15.3	47	3.6	85	2.5
10	16.3	48	3.8	86	2.5
11	14.8	49	3.6	87	2.4
12	14.1	50	3.5	88	2.4
13	12.9	51	3.8	89	2.3
14	16.5	52	3.4	90	2.4
15	24.0	53	3.2	91	2.2
16	32.1	54	3.6	92	2.3
17	32.1	55	3.8	93	2.1
18	34.4	56	3.4	94	2.2
19	33.8	57	3.4	95	2.0
20	28.9	58	3.7	96	2.1
21	27.6	59	3.3	97	2.0
22	27.3	60	3.6	98	1.9
23	23.4	61	3.6	99	2.0
24	19.8	62	4.1	100	1.9
25	16.6	63	4.0	101	1.9
26	13.3	64	4.2	102	1.8
27	11.1	65	4.7	103	1.9
28	9.2	66	4.6	104	1.9
29	8.2	67	4.8	105	1.8
30	7.7	68	4.8	106	1.7
31	6.6	69	4.5	107	1.8
32	7.0	70	4.4	108	1.7
33	6.7	71	4.2	109	1.7
34	7.3	72	3.9	110	1.7
35	7.1	73	3.6	111	1.7
36	7.4	74	3.5	112	1.6
37	6.5	75	3.4	113	1.6

Table F-4: Coordinates of the August 2006 hydrograph

Time (hrs)	Flow (m ³ /s)	Time (hrs)	Flow (m ³ /s)	Time (hrs)	Flow (m ³ /s)
0	0.6	38	6.3	76	3.0
1	1.4	39	5.9	77	3.1
2	5.2	40	5.8	78	2.9
3	7.5	41	5.6	79	3.0
4	11.7	42	5.4	80	2.9
5	21.5	43	5.2	81	2.8
6	24.4	44	5.2	82	3.1
7	27.9	45	4.9	83	2.8
8	32.4	46	4.8	84	2.7
9	35.0	47	4.8	85	2.7
10	33.8	48	4.5	86	2.9
11	30.5	49	4.5	87	2.9
12	28.8	50	4.4	88	2.8
13	26.9	51	4.2	89	3.1
14	25.2	52	4.3	90	2.6
15	25.6	53	4.1	91	2.6
16	28.1	54	4.0	92	2.7
17	31.0	55	4.1	93	2.7
18	31.4	56	3.8	94	2.7
19	31.0	57	3.9	95	2.8
20	29.2	58	3.8	96	2.7
21	27.1	59	3.8	97	2.7
22	24.6	60	3.6	98	2.7
23	21.8	61	3.7	99	2.7
24	18.8	62	3.6	100	2.5
25	16.6	63	3.5	101	2.3
26	14.6	64	3.6		
27	13.0	65	3.4		
28	11.8	66	3.4		
29	10.4	67	3.6		
30	9.3	68	3.4		
31	8.3	69	3.2		
32	7.5	70	3.3		
33	7.0	71	3.4		
34	6.4	72	3.1		
35	5.9	73	3.2		
36	5.7	74	3.0		
37	6.0	75	31		

 Table F-5: Coordinates of the November 2007 hydrograph

0

Į.

Time (hrs)	Flow (m ³ /s)						
0	1.6	46	6.0	91	2.6	136	1.7
1	2.1	47	5.6	92	2.3	137	2.1
2	4.2	48	5.5	93	2.7	138	2.3
3	5.4	49	5.1	94	2.2	139	1.5
4	6.6	50	4.8	95	2.3	140	2.0
5	8.2	51	4.5	96	2.5	141	2.0
6	10.0	52	4.5	97	2.4	142	2.0
7	16.2	53	4.4	98	2.3	143	2.0
8	28.0	54	4.2	99	2.4	144	2.0
9	18.2	55	4.1	100	2.3	145	1.8
10	17.0	56	4.1	101	2.7	146	1.9
11	15.8	57	4.0	102	1.3	147	1.9
12	15.4	58	3.9	103	2.7	148	1.9
13	15.2	59	3.5	104	2.5	149	2.0
14	13.6	60	3.9	105	1.8	150	1.6
15	11.7	61	3.4	106	2.3	151	1.6
16	10.1	62	3.4	107	2.4	152	2.0
17	8.9	63	3.5	108	1.8	153	2.0
18	7.8	64	3.4	109	2.3	154	1.9
19	7.1	65	3.3	110	2.5	155	1.9
20	6.3	66	3.4	111	2.3	156	1.9
21	6.0	67	2.6	112	2.1	157	1.9
22	5.8	68	3.7	113	2.6	158	1.7
23	5.2	69	2.7	114	1.9	159	2.0
24	5.0	70	3.2	115	2.4	160	1.7
25	5.5	71	3.0	116	1.9	161	2.1
26	5.2	72	2.7	117	2.2	162	1.5
27	5.1	73	2.8	118	2.2	163	1.9
28	5.2	74	2.9	119	2.0	164	1.8
29	4.6	75	3.0	120	2.2	165	1.4
30	4.2	76	2.6	121	2.2	166	1.9
31	5.7	77	2.8	122	2.0	167	2.5
32	4.1	78	2.7	123	2.1	168	1.8
33	4.1	79	2.7	124	2.2	169	1.1
34	3.8	80	2.5	125	2.0	170	2.0
35	4.6	81	2.9	126	1.7	171	1.8
36	4.9	82	2.8	127	2.3	172	1.8
37	5.1	83	2.3	128	2.0	173	2.1
38	5.6	84	2.8	129	2.3	174	1.3
39	5.9	85	2.4	130	1.7	175	1.8
40	5.8	86	2.8	131	2.1	176	1.8
41	6.2	87	2.5	132	2.0	177	1.8
42	6.5	88	2.8	133	2.0	178	1.8
43	6.4	89	2.1	134	2.0	179	1.8
44	6.4	90	2.6	135	2.0	180	1.6
45	6.6						

Table F-6: Coordinates of the July 2012 hydrograph

 \cap

Ĵ,

Time (hrs)	Flow (m ³ /s)						
0	1.6	41	5.1	82	3.0	123	2.1
1	3.1	42	5.0	83	3.2	124	2.6
2	2.5	43	5.1	84	2.6	125	2.3
3	3.5	44	4.8	85	2.8	126	2.6
4	3.2	45	4.7	86	2.9	127	2.3
5	4.8	46	4.5	87	2.7	128	2.4
6	5.3	47	4.4	88	3.1	129	2.4
7	6.5	48	4.7	89	2.7	130	2.6
8	8.6	49	4.2	90	2.5	131	1.8
9	11.5	50	4.3	91	2.8	132	2.6
10	11.8	51	4.1	92	3.0	133	2.6
11	12.2	52	4.2	93	2.7	134	2.4
12	12.9	53	3.8	94	2.6	135	1.7
13	13.1	54	3.9	95	2.6	136	2.4
14	14.5	55	3.9	96	2.6	137	2.7
15	13.8	56	3.9	97	2.7	138	2.2
16	12.7	57	3.9	98	2.9	139	2.6
17	12.6	58	3.5	99	2.8	140	2.3
18	14.5	59	3.7	100	2.4	141	2.3
19	15.1	60	3.8	101	2.9	142	2.3
20	18.1	61	3.5	102	2.5	143	2.1
21	23.2	62	3.6	103	2.9	144	2.5
22	27.1	63	3.5	104	2.7	145	2.3
23	23.4	64	3.5	105	2.5	146	2.3
24	19.3	65	3.5	106	2.5	147	3.0
25	16.6	66	3.5	107	2.7	148	1.2
26	14.1	67	3.4	108	2.4	149	2.2
27	12.2	68	3.4	109	2.6	150	2.0
28	10.6	69	3.5	110	2.6	151	2.2
29	9.1	70	3.3	111	2.6	152	2.4
30	8.5	71	3.3	112	2.2	153	2.0
31	7.5	72	3.4	113	2.7	154	2.6
32	7.2	73	3.2	114	2.6	155	1.9
33	6.5	74	3.4	115	2.4	156	2.6
34	6.4	75	3.0	116	2.5	157	2.3
35	6.3	76	3.1	117	2.7	158	2.1
36	5.8	77	2.8	118	2.2	159	2.0
37	5.7	78	3.2	119	2.7	160	2.2
38	5.5	79	2.7	120	2.5	161	2.0
39	5.3	80	2.9	121	2.3	162	1.7
40	5.2	81	2.8	122	2.5		

ř.

Table F-7: Coordinates of the September 2015 hydrograph

Addendum E: Flood routing

Addendum F: Freeboard Calculations

		Project Title:	ROODEF EVALUA	ONTEIN TION	DAM:	FOURTH D	AM SAFETY	Sheet No.
water & sanitation Structure: SPILLWAY								1
	Department: Water and Sanitation REPUBLIC OF SOUTH AFRICA	Calculation Title	e: FREEB(DARD DE	TERMIN	NATION		-
		Calc: RW SIW	ELANI	Check:K K	Khomo		Approval: CN Mah	labela
FREEBOARD CALCULATIONS								
1. ME	THODOLOGY							
a) Select wind speeed from fig 2.3 -4 of SANCOLD freeboard guidelines or a suitable source								

- b) Determine fetch (Km). Either use the SANCOLD recommendations or the USBR approach
- c) Calculate the Significant Height (H_s), use Saville Method or the Donelan et al method.
- d) Calculate Wave Period and Length.
- e) Calculate Wave Runup.
- f) Calculate Wind Setup.
- g) Determine miximum stage corrosponding to maximum discharge of RDD through flood routing
- h) Calculate Surge and Seich
- i) Calculate Earthquake Wave
- j) Calculate land slide wave height
- k) Calculate the influence of 25% inoperation of the outlet works
- I) Use table 3.1 of SANCOLD Guidelines on Freeboard to calculate required freeboard.
- m) Compare the obtained freeboard value with values given in table 3.3 of the SANCOLD guidelines and the existing freeboard at the dam of interest.

2. DESIGN STANDARDS:

- a) USBR Design Standard No.13: Freeboard, 2012. (USBR DS No.13:FB)
- b) South African National Committee On Large Dam: Freeboard Guidelines, 2011 (SANCOLD:FB)
- c) The Rock Manual

3. PROPERTIES OF THE DAM

Input parameters (variables)

Fetch; F = 1110 m
Wind Speed; $U_{10} = 24 \text{ m/s}$
Upstream Slope Angle $\ldots \ldots :; \alpha = 18.4^{\circ}$
Density of air; $\rho_{\alpha\iota\rho} = 1.2 \text{ kg/m}^3$
Density of water; $\rho_{\omega} = 1000 \text{ kg/m}^3$
Volume of basin at FSL; $A_{FSL} = 37010000 \text{ m}^2$
Area of basin at FSL; $V_{FSL} = 2063000 \text{ m}^3$
Air/Water drag coefficient; $C_D = 0.005$
Gravitational acceleration; $g = 9.81 \text{ m/s}^2$
Wave direction; $\theta = 0^{\circ}$
Wind direction; $\phi_w = 0^\circ$
RL of Spillway Crest; RL _{Spillway Crest} = 42.3 m
RL of NOC; RL _{NOC} = 46 m



4. CALCULATIONS

4.1. Minimum duration (t_{min})



; $t_{min} = (30.1 / g) \times U_{10} \times Cos(\theta - \phi_w) \times (g \times F / (U_{10} \times Cos(\theta - \phi_w))^2)^{0.77} = 708.055 s$

4.2. Wave Height (Significant Wave Height: H_s)

$$\frac{gH_s}{\left(U_{10}\cos\left(\theta-\phi_w\right)\right)^2} = 0.00366 \left(\frac{gF_{\theta}}{\left(U_{10}\cos\left(\theta-\phi_w\right)\right)^2}\right)^{0.38}$$
Rock Manual

$$H_{s} = (0.000366 \text{ m}^{-0.38} / \text{g}) \times (U_{10} \times \text{Cos}(\theta - \phi_{w}))^{2} \times (\text{g} \times \text{F} / (U_{10} \times \text{Cos}(\theta - \phi_{w})))^{0.38} = 0.220 \text{ m}$$

4.3. Wave Period (T)

 $\frac{gT_p}{U_{10}\cos(\theta-\phi_w)} = 0.542 \left(\frac{gF_{\theta}}{\left(U_{10}\cos(\theta-\phi_w)\right)^2}\right)^{0.23}$Rock Manual

 $T = (0.542 / g) \times U_{10} \times Cos(\theta - \phi_w) \times (g \times F / (U_{10} \times Cos(\theta - \phi_w))^2)^{0.23} = 2.607 s$

4.4. Wave Length (L)

 $L = 1.56 \text{ m/s}^2 \times \text{T}^2 = 10.603 \text{ m}$

4.5. Wave Run-up (R)

a) Steepness of the peak wave (S_p)

$$S_p = H_s/L = 0.021$$

b) Surf Similarity Factor (ξ_p)

 $\xi_{\rm p} = \tan(\alpha) / \sqrt{(H_{\rm s}/L)} = 2.311$

Year & sanitationTouchard SplittWAYConclusion Title: FREEBOARD DETERMINATIONCalculation Title: FREEBOARD DETERMINATIONSupport SplittWAYCalculation Title: FREEBOARD DETERMINATIONCalculation Title: FREEBOARD DETERMINATIONSupport SplittWAYCalculation Title: FREEBOARD DETERMINATIONSupport SplittWAYSupport SplittWAYCalculation Title: FREEBOARD DETERMINATIONSupport SplittWAY Total SplittWAYSupport SplittWAY Total SplittWAYSupport SplittWAYSupport SplittWAYSupport SplittWAYCalculation Title: FREEBOARD DETERMINATIONType of slope sufface Type SplittWAYSupport SplittWAYSupport SplittWAYSplittWAYSupport SplittWAYSplittWAYSplittWAYSplittWAYSplittWAYSplittWAYSplittWAYSplittWAYSplittWAY <th></th> <th></th> <th></th> <th>Project Title:</th> <th>ROODEF</th> <th>ONTEIN DAM: FOURTH</th> <th>I DAM SAFETY</th> <th>Sheet No.</th>				Project Title:	ROODEF	ONTEIN DAM: FOURTH	I DAM SAFETY	Sheet No.			
Number of the second	5	🌽 🛛 water 8	& sanitation	Structure: SPI	LLWAY	-		3			
Revelue of south AFRICA Calculation The: FREEBOARD DETERMINATION $atc: RW SIWELANI Cabe:KK Khomp Anonvai: CN Mahlabela \overline{y_{po}} of slope surface \overline{y_{1}} Smooth. block:revelment 1 Smooth. block:revelment 1 Smooth. block:revelment 1 Smooth. block:revelment 1 Smooth. block:revelment 0.80 - 10 One tayer ofrock, dimeter (JHD = 1.5 - 6.0) 0.80 - 10 Determine tayers ofrock, (HSD = 1.5 - 6.0) 0.80 - 0.65 Two or more tayers ofrock, (HSD = 1.5 - 6.0) 0.80 - 0.65 Type 1: Surface roughness reduction factors (USBR Table B-3:2011) Ege: 2: 5 < 1 & 1.6$	10	Department: Water and Sa	nitation								
$\label{eq:constraint} \begin{array}{ c c c } \hline C_{16}ck,KKhomo & Androval: CN Mahlabela \\ \hline \hline Type of stope surface & Yr \\ \hline Smooth, concrete, sphalt & 1 \\ \hline Smooth, concrete, sphalt & 1 \\ \hline Smooth, bodk rewdment & 1 \\ \hline I \\ \hline Smooth, bodk rewdment & (HoD = 1.5 - 3.0) & 0.50 - 0.50 \\ \hline \hline Two or more layers of rock, dameter D_{(HoD = 1.5 - 0.0) & 0.50 - 0.50} \\ \hline \hline Two or more layers of rock, dameter D_{(HoD = 1.5 - 0.0) & 0.50 - 0.50} \\ \hline \hline Two or more layers of rock, dameter D_{(HoD = 1.5 - 0.0) & 0.50 - 0.50 \\ \hline \hline Two or more layers of rock, dameter D_{(HoD = 1.5 - 0.0) & 0.50 - 0.50 \\ \hline \hline \hline Two or more layers of rock, dameter D_{(HOD = 1.5 - 0.0) & 0.50 - 0.50 \\ \hline \hline \hline \ Two or more layers of rock, dameter D_{(HOD = 1.5 - 0.0) & 0.50 - 0.50 \\ \hline \hline \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$	Contra Co	REPUBLIC	F SOUTH AFRICA	Calculation Tit	le: FREEBC	DARD DETERMINATION					
$\label{eq:results} \begin{split} \hline \mathbf{\overline{ype}} & \text{of aloge surface} & \mathbf{\overline{yr}} \\ \hline \mathbf{\overline{Smooth}}, & \text{concrete, sphalt} & 1 \\ \hline \mathbf{\overline{Srass}}, & \mathbf{\overline{Scorthinders}}, & \text{inlegth}, & 0.90-1.0 \\ \hline \mathbf{\overline{Ore}} & \text{isyer of rock}, & (\text{HID} = 1.53.0) & 0.55-0.6 \\ \hline \mathbf{\overline{Ore}} & \text{isyer of rock}, & (\text{HID} = 1.53.0) & 0.55-0.6 \\ \hline \mathbf{\overline{Ore}} & \text{isyer of rock}, & (\text{HID} = 1.56.0) & 0.50-0.65 \\ \hline \mathbf{\overline{So}} & \text{isyen of rock}, & (\text{HID} = 1.53.0) & 0.55-0.6 \\ \hline \hline \mathbf{\overline{Vo}} & \text{or or relayers of rock}, & (\text{HID} = 1.56.0) & 0.50-0.65 \\ \hline \hline \mathbf{\overline{Vo}} & \text{or or relayers of rock}, & (\text{HID} = 1.56.0) & 0.50-0.65 \\ \hline \hline \mathbf{\overline{Vo}} & \text{or or relayers of rock}, & (\text{HID} = 1.56.0) & 0.50-0.65 \\ \hline \hline \mathbf{\overline{Vo}} & \text{or or relayers of rock}, & (\text{HID} = 1.56.0) & 0.50-0.65 \\ \hline \hline \hline \mathbf{\overline{Vo}} & \text{isot} & \mathbf{\overline{Vo}} & \text{isot} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \hline \mathbf{\overline{Vo}} & \text{isot} & \mathbf{\overline{Vo}} & \text{isot} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \hline \mathbf{\overline{Vo}} & \text{isot} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \hline \hline \mathbf{\overline{Vo}} & \text{isot} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \hline \hline \mathbf{\overline{Vo}} & \text{isot} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \hline \mathbf{\overline{Vo}} & \text{isot} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}} & \text{isot} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}} & \text{isot} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}} & \text{isot} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}} & \text{isot} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} & \mathbf{\overline{Vo}} \\ \hline \mathbf{\overline{Vo}}$				Calc: RW SIW	ELANI	Check:K Khomo	Approval: CN Mat	nlabela			
$\begin{split} \hline \underline{Smooth}_{noncete, asphal} & \underline{1} & \underline{1} \\ \hline \underline{Smooth}_{noncete, asphal} & \underline{1} & \underline{1} \\ \hline \underline{Smooth}_{noncetey entered} & \underline{1} \\ \hline \underline{Smooth}_{noncetey entered} & \underline{1} \\ \hline \underline{Smooth}_{noncetey entered} & \underline{Smooth}_{noncetey entered} & \underline{Smooth}_{noncetey entered} & \underline{Smooth}_{noncetey entered} \\ \hline \underline{Smooth}_{noncetey entered} & \underline{Smooth}_{noncetey entered} & \underline{Smooth}_{noncetey entered} \\ \hline \underline{Smooth}_{noncetey entered} & \underline{Smooth}_{noncetey entered} & \underline{Smooth}_{noncetey entered} \\ \hline \underline{Smooth}_{noncetey entered} & \underline{Smooth}_{noncetey entered} & \underline{Smooth}_{noncetey entered} \\ \hline \underline{Smooth}_{noncetey entered} & \underline{Smooth}_{noncete$	ſ	Тур	e of slope surfa	æ	Yr						
$\begin{split} & \boxed{\text{Smooth blocktreatment}} & 1 \\ \hline \text{Ore layer of rock, diameter D_{(145D = 15 - 6.0)}} \\ \hline \text{Ore layer of rock, diameter D_{(145D = 15 - 6.0)}} \\ \hline \text{Spin or more layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or more layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or more layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or more layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or more layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or more layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or more layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or more layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or more layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or more layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or more layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or more layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or layers of rock, (150 - 0.0)} \\ \hline \text{Spin or layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or layers of rock, (145D = 15 - 6.0)} \\ \hline \text{Spin or layers of rock, (145D = 15 - 6.0)} \\ \hline Spin or layers of rock or layers or layers of rock or layers or l$		Smooth, concrete,	asphalt		1						
$\begin{aligned} \frac{Grass (3 centimeters in length)}{One layer of rock, diameter D, (HsD = 1.5 - 3.0)} (0.90 - 1.0)}{0.65 - 0.6} \\ \hline Two or more layers of rock, (HsD = 1.5 - 6.0)} (0.90 - 0.65) \\ \hline Tuo or more layers of rock, (HsD = 1.5 - 6.0)} (0.90 - 0.65) \\ \hline Tuo or more layers of rock, (HsD = 1.5 - 8.0)} (0.90 - 0.65) \\ \hline Tuo or more layers of rock, (HsD = 1.5 - 8.0)} (0.90 - 0.65) \\ \hline Tuo or more layers of rock, (HsD = 1.5 - 8.0)} (0.90 - 0.65) \\ \hline Tuo or more layers of rock, (HsD = 1.5 - 8.0)} (0.90 - 10) \\ \hline Tuo or more layers of rock, (HsD = 1.5 - 8.0)} (0.90 - 10) \\ \hline Tuo of variable A and B (USBR Table B-3:2011) \\ \hline Tuo of variable A and B (USBR Table B-4:2012) \\ \hline Run-Up parameters \\ \gamma_{1} = 0.55 \\ \gamma_{1} = 1 \\ \gamma_{1} = 0 \\ \gamma_{2} = 0.85 \\ A = 1.6 \\ C = 0 \\ R = H_{n} \times A \times \xi_{p} \times \gamma_{1} \times \gamma_{h} \times \gamma_{h} \times \gamma_{h} = 0.380 m \\ \hline \textbf{4.6. Wind Setup (n_w)} \\ n_{w} = \frac{1}{2} \cdot \frac{\rho_{afr}}{\rho_{w}} \cdot C_{D} \cdot \frac{U_{10}^{2}}{gh}, F \\ \dots \dots$		Smooth block reve	tment		1						
$\left \begin{array}{c} \text{One layer of rock, diameter D_{1}(HsO = 1.5 - 3.0) & 0.55 - 0.6} \\ \hline \text{Two or more layers of rock, (HsO = 1.5 - 6.0) & 0.50 - 0.55} \end{array} \right $ Figure 1: Surface roughness reduction factors (USBR Table B-3.2011) $\left \begin{array}{c} \hline \frac{k_{0} - \text{Limits}}{k_{0} - 1.5 - k_{0}} & \frac{k_{0}}{2.5 + k_{0} + 9} & \frac{k_{0}}{2.5 + k_{0} + 2} & \frac{k_{0}}{$		Grass (3 centimete	ers in length)		0.90 - 1.0	0					
$\begin{split} \hline \text{Two or more layers of rook, (HSD = 1.5 - 6.0)} & 0.80 - 0.65 \\ \hline \text{Figure 1: Surface roughness reduction factors (USBR Table B-3:2011)} \\ \hline \\ $		One layer of rock, o	diameterD, (Hs/D	= 1.5 – 3.0)	0.55 - 0.0	6					
Figure 1: Surface roughness reduction factors (USBR Table B-3:2011) $\frac{\xi_{g} < 2.5}{\xi_{g} < 9} < \frac{1}{2.5 < \xi_{g} < 1$	Two or more layers of rock, (Hs/D = 1.5 – 6.0) 0.50 – 0.55										
$\begin{split} \hline \frac{k_{B} - Limits}{k_{B} \leq 2.5} & \frac{1}{1.6} & \frac{1}{0} \\ \frac{k_{B} \leq 2.5}{2.5 \leq a \leq 9} & \frac{1}{0.2} & \frac{1}{4.5} \\ \hline Figure 2: Values of variable A and B (USBR Table B-4:2012) \\ \hline Run-Up parameters \\ \gamma_{1} = 0.55 \\ \gamma_{2} = 1 \\ \gamma_{2} = 1 \\ \gamma_{1} = 1 \\ \gamma_{1} = 1 \\ \gamma_{1} = 0.85 \\ A = 1.6 \\ C = 0 \\ \hline R = H_{a} \times A \times \xi_{p} \times \gamma_{r} \times \gamma_{b} \times \gamma_{h} \times \gamma_{p} = 0.380 \text{ m} \\ \hline \textbf{4.6. Wind Setup (n_{w})} \\ \hline \textbf{n}_{w} = \frac{1}{2} \cdot \frac{\rho_{atr}}{\rho_{w}} \cdot C_{D} \cdot \frac{U_{20}^{2}}{gh} \cdot F \\ \hline \\ \hline \\ \hline \\ \hline \\ \hline \textbf{Average Depth of basin; } h_{ave} = V_{FBI} / A_{FSL} = 0.056 \text{ m} \\ ; n_{w} = 0.5 \times (\rho_{oup} / \rho_{o}) \times C_{D} \times (U_{10})^{2} / (g \times h_{ave}) \times F = 3.508 \text{ m} \\ \hline \textbf{4.7. Recommended Design Discharge (RDD) \\ \hline From Flood Routing; \\ \hline \textbf{Height of water above spillway crest; } h_{RDD} = 447.5 \text{ m} \\ \hline \textbf{Height of water above spillway crest; } h_{RDD} = 1.5 \text{ m} \\ \hline \textbf{4.8. Surge and Seiche} \\ : h_{ourge} = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Wave} \\ \cdot h_{cr} = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Wave} \\ \cdot h_{cr} = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Wave} \\ \cdot h_{cr} = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Wave} \\ \cdot h_{cr} = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Wave} \\ \cdot h_{cr} = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Wave} \\ \cdot h_{cr} = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Wave} \\ \cdot h_{cr} = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Wave} \\ \cdot h_{cr} = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Wave} \\ \cdot h_{cr} = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Wave} \\ \cdot h_{cr} = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Wave} \\ \cdot h_{cr} = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Mark = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Wave} \\ \cdot h_{cr} = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Mark = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Mark = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Mark = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Mark = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Mark = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Mark = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Mark = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Mark = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Mark = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Mark = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Mark = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Mark = 0 \text{ m} \\ \hline \textbf{4.9. Eathquake Mark = 0 \text{ m} \\ \hline 4.9. Eathq$	F	igure 1: Surface roo	ughness reduction	factors (USBR T	able B-3:201	1)					
$\frac{k_{x} \leq 2.5}{2.5 < k_{x} < 9} \frac{1.6}{0.2} \frac{0}{4.5}$ Figure 2: Values of variable A and B (USBR Table B-4:2012) $\frac{Run-Up parameters}{y_{1} = 0.55}$ $\frac{y_{1} = 1}{y_{2} = 1}$ $\frac{y_{2} = 0.85}{4.5}$ A = 1.6 C = 0 R = H ₀ × A × $\xi_{p} × \gamma_{r} × \gamma_{b} × \gamma_{h} × \gamma_{p} = 0.380 \text{ m}$ 4.6. Wind Setup (n _w) $n_{w} = \frac{1}{2} \cdot \frac{\rho_{afr}}{\rho_{w}} \cdot C_{D} \cdot \frac{U_{10}^{2}}{g_{D}} \cdot F$		ξ _p - Limits	Α	С							
$\begin{array}{c c c c c c c c c c c c c c c c c c c $		ξ _p ≤ 2.5	1.6	0							
Figure 2: Values of variable A and B (USBR Table B-4:2012) $ \frac{Run-Up parameters}{\gamma_{1} = 0.55} \\ \gamma_{2} = 1 \\ \gamma_{1} = 1 \\ \gamma_{1} = 0.85 \\ A = 1.6 \\ C = 0 $ $ R = H_{a} \times A \times \xi_{p} \times \gamma_{1} \times \gamma_{b} \times \gamma_{h} \times \gamma_{p} = 0.380 \text{ m} $ 4.6. Wind Setup (n _w) $ n_{w} = \frac{1}{2} \cdot \frac{\rho_{afr}}{\rho_{w}} \cdot C_{D} \cdot \frac{U_{10}^{2}}{gh} \cdot F \dots Rock Manual $ Average Depth of basin; $h_{ave} = V_{FSL} / A_{FSL} = 0.056 \text{ m}$; $n_{w} = 0.5 \times (\rho_{mp} / \rho_{m}) \times C_{D} \times (U_{10})^{2} / (g \times h_{ave}) \times F = 3.508 \text{ m}$ 4.7. Recommended Design Discharge (RDD) From Flood Routing:; RL _{RDD} = 447.5 m Height of water above spillway crest; $h_{RDD} = 1.5 \text{ m}$ 4.8. Surge and Seiche ; $h_{surge} = 0 \text{ m}$ 4.9. Eathquake Wave : $h_{ron} = 0 \text{ m}$		2.5 < ξ _p < 9	-0.2	4.5							
$\frac{Run-Up \ parameters}{\gamma_{r} = 0.55}$ $\gamma_{r} = 1$ $\gamma_{r} = 1$ $\gamma_{r} = 1$ $\gamma_{r} = 0.85$ $A = 1.6$ $C = 0$ $R = H_{s} \times A \times \xi_{p} \times \gamma_{r} \times \gamma_{b} \times \gamma_{h} \times \gamma_{\beta} = 0.380 \text{ m}$ 4.6. Wind Setup (n _w) $n_{w} = \frac{1}{2} \cdot \frac{\rho_{atr}}{\rho_{w}} \cdot C_{D} \cdot \frac{U_{10}^{2}}{gh} \cdot F$	Figure 2: Values of variable A and B (USBR Table B-4:2012)										
$\begin{array}{l} \begin{array}{l} \gamma_{r} = 0.55 \\ \gamma_{h} = 1 \\ \gamma_{p} = 0.85 \\ A = 1.6 \\ C = 0 \end{array}$ $R = H_{s} \times A \times \xi_{p} \times \gamma_{r} \times \gamma_{b} \times \gamma_{h} \times \gamma_{p} = \textbf{0.380 m}$ $\textbf{4.6. Wind Setup (n_{w})}$ $n_{w} = \frac{1}{2} \cdot \frac{\rho_{atr}}{\rho_{w}} \cdot C_{D} \cdot \frac{U_{10}^{2}}{gh} \cdot F \qquad \dots \\ \dots$	Run-Up parameters										
$\begin{array}{l} \begin{array}{l} \begin{array}{l} \gamma_{e}=1\\ \gamma_{e}=1\\ \gamma_{e}=0\\ R=1, \\ C=0\\ R=H_{s}\times A\times\xi_{p}\times\gamma_{t}\times\gamma_{b}\times\gamma_{h}\times\gamma_{p}=0.380\ m\end{array}$ $\begin{array}{l} \textbf{4.6. Wind Setup (n_{w})\\ n_{w}=\frac{1}{2}\cdot\frac{\rho_{atr}}{\rho_{w}}\cdot C_{D}\cdot\frac{U_{10}^{2}}{gh}, \\ F\\ \hline \end{array}$ $\begin{array}{l} \textbf{Average Depth of basin; } h_{ove}=V_{FSL}/A_{FSL}=0.056\ m\\ ;\ n_{w}=0.5\times(\rho_{oup}/\rho_{w})\times C_{D}\times(U_{10})^{2}/(g\times h_{ave})\times F=3.508\ m\end{array}$ $\begin{array}{l} \textbf{4.7. Recommended Design Discharge (RDD)\\ From Flood Routing; \hline \end{array}; \\ RL_{RDD}=447.5\ m\\ Height of water above spillway crest. \hline \end{array}; \\ h_{surge}=0\ m$ $\begin{array}{l} \textbf{4.8. Surge and Seiche\\ \\ ;\ h_{surge}=0\ m\end{array}$		$v_{\rm r} = 0.55$									
$\begin{array}{l} \begin{array}{l} \gamma_{p} = 1 \\ \gamma_{p} = 0.85 \\ A = 1.6 \\ C = 0 \end{array}$ $R = H_{s} \times A \times \xi_{p} \times \gamma_{r} \times \gamma_{b} \times \gamma_{h} \times \gamma_{p} = \textbf{0.380 m} \end{array}$ $\begin{array}{l} \textbf{4.6. Wind Setup (n_{w})} \\ n_{w} = \frac{1}{2} \cdot \frac{\rho_{atr}}{\rho_{w}} \cdot C_{D} \cdot \frac{U_{10}^{2}}{gh} \cdot F \\ \dots \\$		$\gamma_{\rm b} = 1$									
$\begin{array}{l} \gamma_{B}=0.85\\ A=1.6\\ C=0\\ R=H_{s}\times A\times\xi_{p}\times\gamma_{r}\times\gamma_{b}\times\gamma_{h}\times\gamma_{B}=\textbf{0.380}\ m\\ \textbf{4.6. Wind Setup (n_{w})}\\ n_{w}=\frac{1}{2}\cdot\frac{\rho_{air}}{\rho_{w}}\cdot C_{D}\cdot\frac{U_{10}^{2}}{gh}\cdot F\\ \dots$		$\gamma_{\rm h} = 1$									
$A = 1.6$ $C = 0$ $R = H_6 \times A \times \xi_p \times \gamma_r \times \gamma_b \times \gamma_h \times \gamma_\beta = 0.380 \text{ m}$ 4.6. Wind Setup (n _w) $n_{w} = \frac{1}{2} \cdot \frac{\rho_{atr}}{\rho_w} \cdot C_D \cdot \frac{U_{10}^2}{gh} \cdot F$		$\gamma_{\beta} = 0.85$									
$R = H_{s} \times A \times \xi_{p} \times \gamma_{r} \times \gamma_{b} \times \gamma_{h} \times \gamma_{p} = 0.380 \text{ m}$ 4.6. Wind Setup (n _w) $n_{w} = \frac{1}{2} \cdot \frac{\rho_{atr}}{\rho_{w}} \cdot C_{D} \cdot \frac{U_{10}^{2}}{gh} \cdot F$ Rock Manual Average Depth of basin; $h_{ave} = V_{FSL} / A_{FSL} = 0.056 \text{ m}$; $n_{w} = 0.5 \times (\rho_{aup} / \rho_{w}) \times C_{D} \times (U_{10})^{2} / (g \times h_{ave}) \times F = 3.508 \text{ m}$ 4.7. Recommended Design Discharge (RDD) From Flood Routing;; RL _{RDD} = 447.5 m Height of water above spillway crest; $h_{RDD} = 1.5 \text{ m}$ 4.8. Surge and Seiche ; $h_{surge} = 0 \text{ m}$ 4.9. Eathquake Wave ; $h_{ron} = 0 \text{ m}$		A = 1.6 C = 0									
$R = H_{s} \times A \times \xi_{p} \times \gamma_{r} \times \gamma_{b} \times \gamma_{h} \times \gamma_{p} = 0.380 \text{ m}$ 4.6. Wind Setup (n_w) $n_{w} = \frac{1}{2} \cdot \frac{\rho_{atr}}{\rho_{w}} \cdot C_{D} \cdot \frac{U_{10}^{2}}{gh} \cdot F$ Rock Manual Average Depth of basin; $h_{ave} = V_{FSL} / A_{FSL} = 0.056 \text{ m}$; $n_{w} = 0.5 \times (\rho_{cup} / \rho_{w}) \times C_{D} \times (U_{10})^{2} / (g \times h_{ave}) \times F = 3.508 \text{ m}$ 4.7. Recommended Design Discharge (RDD) From Flood Routing;; RL _{RDD} = 447.5 m Height of water above spillway crest; $h_{RDD} = 1.5 \text{ m}$ 4.8. Surge and Seiche ; $h_{surge} = 0 \text{ m}$ 4.9. Eathquake Wave ; $h_{ron} = 0 \text{ m}$		0 - 0									
4.6. Wind Setup (n _w) $n_{w} = \frac{1}{2} \cdot \frac{\rho_{air}}{\rho_{w}} \cdot C_{D} \cdot \frac{U_{10}^{2}}{gh} \cdot F$ Rock Manual Average Depth of basin; $h_{ave} = V_{FSL} / A_{FSL} = 0.056 m$; $n_{w} = 0.5 \times (\rho_{mp} / \rho_{o}) \times C_{D} \times (U_{10})^{2} / (g \times h_{ave}) \times F = 3.508 m$ 4.7. Recommended Design Discharge (RDD) From Flood Routing;; RL _{RDD} = 447.5 m Height of water above spillway crest; $h_{RDD} = 1.5 m$ 4.8. Surge and Seiche ; $h_{surge} = 0 m$ 4.9. Eathquake Wave : $h_{ron} = 0 m$		$R = H_s \times A \times A$	$\xi_p \times \gamma_r \times \gamma_b \times \gamma_h$	$\times \gamma_{\beta} = 0.380 \text{ r}$	n						
4.6. Wind Setup (n _w) $n_{w} = \frac{1}{2} \cdot \frac{\rho_{air}}{\rho_{w}} \cdot C_{D} \cdot \frac{U_{10}^{2}}{gh} \cdot F$ Rock Manual Average Depth of basin; $h_{ave} = V_{FSL} / A_{FSL} = 0.056 \text{ m}$; $n_{w} = 0.5 \times (\rho_{mp} / \rho_{w}) \times C_{D} \times (U_{10})^{2} / (g \times h_{ave}) \times F = 3.508 \text{ m}$ 4.7. Recommended Design Discharge (RDD) From Flood Routing;; RL _{RDD} = 447.5 m Height of water above spillway crest; $h_{RDD} = 447.5 \text{ m}$ 4.8. Surge and Seiche ; $h_{surge} = 0 \text{ m}$ 4.9. Eathquake Wave : $h_{rop} = 0 \text{ m}$											
$n_{w} = \frac{1}{2} \cdot \frac{\rho_{air}}{\rho_{w}} \cdot C_{D} \cdot \frac{U_{10}^{2}}{gh} \cdot F$ Rock Manual Average Depth of basin; $h_{ave} = V_{FSL} / A_{FSL} = 0.056 \text{ m}$; $n_{w} = 0.5 \times (\rho_{atp} / \rho_{o}) \times C_{D} \times (U_{10})^{2} / (g \times h_{ave}) \times F = 3.508 \text{ m}$ 4.7. Recommended Design Discharge (RDD) From Flood Routing;; RL _{RDD} = 447.5 m Height of water above spillway crest; $h_{RDD} = 1.5 \text{ m}$ 4.8. Surge and Seiche ; $h_{surge} = 0 \text{ m}$ 4.9. Eathquake Wave ; $h_{ron} = 0 \text{ m}$	4.	6. Wind Setup	(n _w)								
$n_{w} = \frac{1}{2} \cdot \frac{\rho_{air}}{\rho_{w}} \cdot C_{D} \cdot \frac{U_{10}^{2}}{gh} \cdot F$ Rock Manual Average Depth of basin; $h_{ave} = V_{FSL} / A_{FSL} = 0.056 \text{ m}$; $n_{w} = 0.5 \times (\rho_{aup} / \rho_{w}) \times C_{D} \times (U_{10})^{2} / (g \times h_{ave}) \times F = 3.508 \text{ m}$ 4.7. Recommended Design Discharge (RDD) From Flood Routing;; RL _{RDD} = 447.5 m Height of water above spillway crest; $h_{RDD} = 1.5 \text{ m}$ 4.8. Surge and Seiche ; $h_{surge} = 0 \text{ m}$ 4.9. Eathquake Wave ; $h_{ron} = 0 \text{ m}$											
$n_{w} = \frac{1}{2} \cdot \frac{\rho_{atr}}{\rho_{w}} \cdot C_{D} \cdot \frac{q_{10}}{gh} \cdot F$ Rock Manual Average Depth of basin; $h_{ave} = V_{FSL} / A_{FSL} = 0.056 \text{ m}$; $n_{w} = 0.5 \times (\rho_{atp} / \rho_{w}) \times C_{D} \times (U_{10})^{2} / (g \times h_{ave}) \times F = 3.508 \text{ m}$ 4.7. Recommended Design Discharge (RDD) From Flood Routing;; RL _{RDD} = 447.5 m Height of water above spillway crest; $h_{RDD} = 1.5 \text{ m}$ 4.8. Surge and Seiche ; $h_{surge} = 0 \text{ m}$ 4.9. Eathquake Wave : $h_{ro} = 0 \text{ m}$		1 .	112								
$2 p_{w} gn$ Rock Manual Average Depth of basin; $h_{ave} = V_{FSL} / A_{FSL} = 0.056 m$; $n_w = 0.5 \times (p_{\alpha u \rho} / p_{\omega}) \times C_D \times (U_{10})^2 / (g \times h_{ave}) \times F = 3.508 m$ 4.7. Recommended Design Discharge (RDD) From Flood Routing;; $RL_{RDD} = 447.5 m$ Height of water above spillway crest; $h_{RDD} = 1.5 m$ 4.8. Surge and Seiche ; $h_{surge} = 0 m$ 4.9. Eathquake Wave : $h_{ro} = 0 m$		$n_w = \frac{1}{2} \cdot \frac{\rho_{air}}{r}$	$\cdot C_{D} \cdot \frac{U_{10}}{rh} \cdot F$								
Average Depth of basin; $h_{ave} = V_{FSL} / A_{FSL} = 0.056 \text{ m}$; $n_w = 0.5 \times (\rho_{\alpha \iota \rho} / \rho_{\omega}) \times C_D \times (U_{10})^2 / (g \times h_{ave}) \times F = 3.508 \text{ m}$ 4.7. Recommended Design Discharge (RDD) From Flood Routing;; $RL_{RDD} = 447.5 \text{ m}$ Height of water above spillway crest; $h_{RDD} = 1.5 \text{ m}$ 4.8. Surge and Seiche ; $h_{surge} = 0 \text{ m}$ 4.9. Eathquake Wave ; $h_{ro} = 0 \text{ m}$		$2 \rho_w$	gn				Rock Manual	1			
Average Depth of basin; $h_{ave} = V_{FSL} / A_{FSL} = 0.056 \text{ m}$; $n_w = 0.5 \times (\rho_{\alpha t\rho} / \rho_w) \times C_D \times (U_{10})^2 / (g \times h_{ave}) \times F = 3.508 \text{ m}$ 4.7. Recommended Design Discharge (RDD) From Flood Routing;; $RL_{RDD} = 447.5 \text{ m}$ Height of water above spillway crest; $h_{RDD} = 1.5 \text{ m}$ 4.8. Surge and Seiche ; $h_{surge} = 0 \text{ m}$ 4.9. Eathquake Wave ; $h_{ron} = 0 \text{ m}$											
$; n_{w} = 0.5 \times (\rho_{\alpha t \rho} / \rho_{\omega}) \times C_{D} \times (U_{10})^{2} / (g \times h_{ave}) \times F = 3.508 \text{ m}$ 4.7. Recommended Design Discharge (RDD) From Flood Routing;; RL _{RDD} = 447.5 m Height of water above spillway crest; h _{RDD} = 1.5 m 4.8. Surge and Seiche ; h _{surge} = 0 m 4.9. Eathquake Wave : h _{ro} = 0 m		Average Dep	th of basin; h	ave = V _{FSL} / A _{FS}	∟ = 0.056 n	n					
4.7. Recommended Design Discharge (RDD) From Flood Routing;; $RL_{RDD} = 447.5 \text{ m}$ Height of water above spillway crest; $h_{RDD} = 1.5 \text{ m}$ 4.8. Surge and Seiche ; $h_{surge} = 0 \text{ m}$ 4.9. Eathquake Wave : $h_{ro} = 0 \text{ m}$		•n −05×6		$(_{a})^{2} / (a \vee b)^{2}$)) ~ F - '	3 508 m					
 4.7. Recommended Design Discharge (RDD) From Flood Routing;; RL_{RDD} = 447.5 m Height of water above spillway crest; h_{RDD} = 1.5 m 4.8. Surge and Seiche ; h_{surge} = 0 m 4.9. Eathquake Wave : h_{EO} = 0 m 		, $\Pi_{W} = 0.5 \times (\mu$	$\sigma_{\alpha \rho} / \rho_{\omega} \times C_{D} \times$	(U ₁₀) / (g × I	lave) × F = .	3.306 111					
From Flood Routing;; $RL_{RDD} = 447.5 \text{ m}$ Height of water above spillway crest; $h_{RDD} = 1.5 \text{ m}$ 4.8. Surge and Seiche ; $h_{surge} = 0 \text{ m}$ 4.9. Eathquake Wave : $h_{ro} = 0 \text{ m}$	4.	7. Recommend	led Design Di	scharge (RD	D)						
Height of water above spillway crest; $h_{RDD} = 1.5 \text{ m}$ 4.8. Surge and Seiche ; $h_{surge} = 0 \text{ m}$ 4.9. Eathquake Wave : $h_{ro} = 0 \text{ m}$		From Flood R	outina:	- ·	: RLppn =	: 447.5 m					
 4.8. Surge and Seiche ; h_{surge} = 0 m 4.9. Eathquake Wave : h_{ro} = 0 m 		Height of water above epillway erect $h = 447.5$ m									
 4.8. Surge and Seiche ; h_{surge} = 0 m 4.9. Eathquake Wave : h_{FO} = 0 m 		Theight of wate		ay orest	, "RDD —	1.5 m					
; h _{surge} = 0 m <i>4.9. Eathquake Wave</i> : h _{FO} = 0 m	4.	8. Surge and S	eiche								
<i>4.9. Eathquake Wave</i> ∴ h _{FO} = 0 m	1	; h _{surge} = 0 m									
$h_{ro} = 0 m$	4.	4.9. Eathquake Wave									
, ned o m		; h _{EQ} = 0 m									

4		Project Title:	ROODEF EVALUA	ONTEIN TION	DAM: FO	URTH D	AM SAFETY	Sheet No.
	water & sanitation	Structure: SPI	LLWAY					4
	Water and Sanitation REPUBLIC OF SOUTH AFRICA	Calculation Title: FREEBOARD DETERMINATION						
		Calc: RW SIWE	ELANI	Check:K K	íhomo		Approval: CN Mah	labela

4.10. Land Slide

; h_L = 0 m

4.11. Flood Outlet

; $h_{FO} = 0 m$

4.12. Freebord Combinations

(Combination number	RDD Surchage	Wind wave and run- up 100- year event	Wind set- up	Surges and seiches	Earth- quake wave	Land-slide wave	Flood outlets
	1	Х	Х					
	2	Х	Х	Х	Х			
	3					Х		
	4						Х	
Γ	5	Х	Х	Х	Х			Х

Figure 3: Proposed Design Considerations of Freeboard condition to be considered with RDD Surcharge

4.12.1. Combination 1: FB₁

 $FB_1 = h_{RDD} + R = 1.880 \text{ m}$

4.12.2. Combination 2: FB₂

 $FB_2 = h_{RDD} + R + n_w = 5.387 \text{ m}$

4.12.3. Comination 3: FB₃

 $FB_3 = h_{EQ}$

4.12.4. Combination 4:FB₄

 $FB_4 = h_L$

4.12.5. Combination 5:FB 5

 $FB_5 = h_{RDD} + R + n_w + h_{surge} + h_{FO} =$ **5.387** m

Addendum G: Drawdown Capacity

PARAMETER	VALUE
Invert Level of the pipe - RL (m	32
Diameter of pipe (m)	0.7
Length of pipe (m)	110
Reynolds number	1000000
Pipe Roughness €	0.03
Entrey losses	0.5
Exit losses	1
Gate valve losses	0.2
Butterfly valve losses	1
Discharge Coefficient	0.61
Gravitational accelaration	9.81
Surface Area of reservoir (m2)	371000
Total height of the embankmer	10.3

Installed drawdown rate - Qd						
m^3/s	2.11					
%H/day	4.8					
mm/day	491					
Top 33% of H (m)	3.4					
RL of 33%H	38.9					
Time to empty top 33% of H	7.79					
Water Level Height - H (m)	18					
Total length of the embankment at base - L (m	20					
Hydraulic Gradient (I) - H/L	0.9					

		Increamental Volume	Average Head over outlet for the depth	Inflow pass- through allowance	ORIFICE FLOW			PIPE FLOW		
Resevoir Water Level	Resevoir Volume below depth				Average discharge rate	Time to empty this depth increame	Cumulative time	Average discharge rate	Time to empty this depth increament	Cumulativ e time
т	m ³	m ³	т	m³/s	m³/s	Hrs	Days	m³/s	Hrs	Days
42.3	2063000	108000	9.8	0	3.26	9.22	0.38	2.11	14.24	0.59
42	1955000	175000	9.4	0	3.19	15.25	1.02	2.06	23.56	1.57
41.5	1780000	170000	8.9	0	3.10	15.22	1.65	2.01	23.52	2.55
41	1610000	154000	8.4	0	3.01	14.19	2.25	1.95	21.93	3.47
40.5	1456000	146000	7.9	0	2.92	13.88	2.82	1.89	21.44	4.36
40	1310000	144000	7.4	0	2.83	14.14	3.41	1.83	21.85	5.27
39.5	1166000	131000	6.9	0	2.73	13.32	3.97	1.77	20.58	6.13
39	1035000	125000	6.4	0	2.63	13.20	4.52	1.70	20.39	6.98
38.5	910000	115000	5.9	0	2.53	12.65	5.04	1.63	19.54	7.79
38	795000	109000	5.4	0	2.42	12.53	5.57	1.56	19.36	8.60
37.5	686000	106000	4.9	0	2.30	12.79	6.10	1.49	19.76	9.42
37	580000	90000	4.4	0	2.18	11.46	6.58	1.41	17.71	10.16
36.5	490000	87000	3.9	0	2.05	11.77	7.07	1.33	18.18	10.92
36	403000	77000	3.4	0	1.92	11.16	7.53	1.24	17.23	11.64
35.5	326000	66000	2.9	0	1.77	10.35	7.96	1.15	15.99	12.30
35	260000	54000	2.4	0	1.61	9.31	8.35	1.04	14.39	12.90
34.5	206000	43000	1.9	0	1.43	8.33	8.70	0.93	12.87	13.44
34	163000	37000	1.4	0	1.23	8.35	9.05	0.80	12.91	13.98
33.5	126000	30000	0.9	0	0.99	8.45	9.40	0.64	13.05	14.52
33	96000	36000	0.15	0	0.40	24.83	10.43	0.26	38.36	16.12
32	60000									



Addendum H: Monitoring Data



Addendum I: Stability Analysis
		Project Title: ROODEFONTEIN DAM: FOURTH DAM SAFETY EVALUATION				
8	Water & sanitation	Structure/Component: EMBANKM	Date: : MARCH 2019	1		
		Calculation Title: STABILITY ANALYSIS				
		Calc: RW SIWELANI	Check: B SEAKE	Approval: CN MAHLABEL	A	

1. Soil Parameters

The relevant soil properties for stability analysis are strength parameters; Cohesion, Angle of frication and Density. Strength parameter values used in stability analysis for Roodefontein Dam were obtained from appendix 4 of a 2002 Design Report (*Roodefontein Dam: Raising the full supply level of the dam by 2.0 m by means of solid raising*) and section 4.4.1 of the 1987 Design Report. These parameters are summarized in Table 1.

SOIL PROPERTIES USED FOR STABILITY ANALYSIS						
	Unit Weight (kN/m ³)		Cohesion	Angle of Friction		
	Saturated Unsaturat		С	φ		
Core Material 1	22	20	5	24		
Core Material 2	22	20	5	24		
General Fill	22	20	2	24		
Rockfill/Gravel Toe	22	20	0	40		
Sand Filter	22	20	0	35		
Foundation Material	18	16	0	30		

Table 1: Shear strength parameters - Original Embankment

2. Analysis Criteria

The main criteria for Ultimate Limit State (ULS) design is governed by equilibrium principle and that is; driving moments (M_A) should be less or equal to the resisting moments (M_R). This criterion is expressed quantitatively in equation 1.

The second criteria is based on USBR (United States Department of Interior Bureau of Reclamation) Design Standard No. 13, Chapter 4, section 4.2.4 and (ADEDCR) Advance Dam Engineering for Design, Construction and Rehabilitation, page 275. The ADEDCR criteria is summarized in Table 2 and the USBR criteria is in Table 3.



2

Table 2: Safety Factor Criteria as per ADEDCR.

SAFETY FACTOR	CRITERIA - ADEDCR	
Loading Condition	Side of embankment	Minimum Safety
1 End of Construction	Upstream	1.25
	Downstream	1.25
2 End of Construction + earthquake Loading	Upstream	1.0
	Downstream	1.0
3 Steady Seepage at Partial Pool	Upstream	1.5
	Downstream	1.5
4. Steady Seepage at Partial Pool + Earthquake	Upstream	1.25
Loading	Downstream	1.25
5. Rapid drawdown	Upstream	1.25
6. Rapid drawdown + Earthquake Loading	Upstream	1.0

Table 3: USBR Safety factor criteria (Ashok Chung, P.E, 2011).

SAFETY FACTOR CRITERIA - USBR					
Loading Condition	Shear Strength parameters	Pore pressure characteristics	Min SF		
		Generation of excess pore pressures in embankment and foundation materials with laboratory determination of pore pressure and monitoring during construction.	1.3		
1. End of Construction	Effective	Generation of excess pore pressures in embankment and foundation materials where there is no field monitoring during construction and no laboratory determination determination.	1.4		
		Generation of excess pore pressures in embankment only with or without field monitoring during construction and no laboratory determination.	1.3		
	Undrained Strength		1.3		
2. Steedy State Seepage	Effective	Steady-state seepage under active conservation pool	1.5		
		Steady-state seepage under maximum reservoir level (during a probable maximum flood)	1.2		
3. Operational Conditions	Effective or Undrained	Rapid drawdown from normal water surface to inactive water surface	1.3		
	Charamed	Rapid drawdown from maximum water surface to active water surface (following a probable maximum flood)	1.2		
	Effective or	Drawdown at maximum outlet capacity (Inoperable internal drainage; unusual drawdown)	1.2		
4. Other	Undrained	Construction modifications (applies only to temporary excavation slopes and the resulting overall embankment stability during construction),	1.3		

3. Design Standards & References:

- a) USBR Design Standard No.13, Chapter 4: Static stability analysis.
- b) Craig's soil mechanics, 8th ed, Chapter 12: Stability of self-supporting soil masses.
- c) Advance Dam Engineering for Design, Construction and Rehabilitation.
- d) 2012 SANCOLD guidelines on Freeboard (to select earthquake loads).

4. Analysis Methodology

a) Fellenius/Swedish (ordinary) method of slices based on limit equilibrium is preferred for analysis in this fourth dam safety evaluation. The method is quantified by equation 3 below.

- b) Using Fellenius Method of analysis, safety factor of the downstream slope was determined and then a computer Program called SLIDE@ (a product of Rock-science) was used to perform detailed analysis of different scenarios.
- c) The results obtained using hand calculations were compared with those of SLIDE@ to verify the accuracy of the Program.
- d) SLIDE was thereafter used to evaluate safety factors for both the upstream and downstream slopes of the embankment under different load cases.
- e) Results based on Bishop's Method and Fellenius Method was compared as shown in Table 5.

5. Input Parameters & Loads

The trial slip circle used to determine the safety factor for the downstream slope is shown in Figure 1 and the used input parameters relevant to the slip circle are listed below.

5.1. input parameters/variables

Downstream Slope; $\beta_D = 1:2$	2
Upstream slope; $\beta_U = 1:3$	3
Radius; $R = 30 n$	ı
Arc Length; $L_a = 26.2$	2 m
Radius Angle; $\theta = 50^{\circ}$	
Unit weight of water; $\gamma_w = 10$	kN/m ³
Unit weight of soil; $\gamma_s = 20 \ k$	$\kappa N/m^3$
Cohesion; $C = 2 kP$	а
Angle of friction; $\emptyset = 24^{\circ}$	

Wate Departm Water an REPUBL		Project Title: ROODEFONTEIN DAM: FOURTH DAM SAFETY EVALUATION				
	Water & sanitation Department: Water and Sanitation REPUBLIC OF SOUTH AFRICA	Structure/Component: EMBANKM	Date: : MARCH 2019	4		
		Calculation Title: STABILITY ANA	LYSIS			
		Calc: RW SIWELANI	Check: B SEAKE	Approval: CN MAHLABELA	4	

5.2. Load cases

The following load cases were evaluated:

- a) Steady state seepage.
- b) Rapid drawdown.
- c) Steady state combined with Earthquake.
- d) Rapid drawdown combined with earthquake.



Figure 1: Trial slip circle

5.2.1. Earthquake loading

Earthquake prevalence in the Western Cape Province is relatively low. Figure 2.8-1 in 2012 SANCOLD guidelines forms a basis for selecting gravitational acceleration (g) for the dam, this figure is reproduced and shown in Figure 2 below for convenience of the reader. Gravitational acceleration for Roodefontein Dam was selected as 0.085g.

Water & sanit Department: Water and Sanitation REPUBLIC OF SOUTH /		Project Title: ROODEFONTEIN DAM: FOURTH DAM SAFETY EVALUATION				
	Water & sanitation Department: Water and Sanitation REPUBLIC OF SOUTH AFRICA	Structure/Component: EMBANKM	Date: : MARCH 2019	5		
		Calculation Title: STABILITY ANALYSIS				
		Calc: RW SIWELANI	Check: B SEAKE	Approval: CN MAHLABEL	4	



Figure 2: Seismic Hazard map for Council of Geoscience (Bosman, D.E etl, 2012)

6. Assumptions

The Fellenius/Swedish solution assumes that the resultant force for inter-slice is zero.

7. Calculations

Table 4 shows contribution of each slice to fulfill equation 2 and their summary is as follows:

$$F = \frac{C'L_a + \tan \emptyset' \sum_i (W_i \cos \alpha_i - U_i l_i)}{\sum_i W_i \sin \alpha_i}$$
$$F = \frac{2 \times 26.2 + \tan 24 \times 936.08}{348.44}$$
$$F = \frac{469.17}{348.44}$$
$$F = 1.35$$

		Project Title: ROODEFONTEIN DAM: FOURTH DAM SAFETY EVALUATION					
	Water & sanitation Department: Water and Sanitation REPUBLIC OF SOUTH AFRICA	Structure/Component: EMBANKM	Date: : MARCH 2019	6			
		Calculation Title: STABILITY ANALYSIS					
		Calc: RW SIWELANI	Check: B SEAKE	Approval: CN MAHLABELA	4		

Table 4: Calculation results

Slice No.	h _i (m)	b (<i>m</i>)	α _i (°)	α _i (rad)	W _i (<i>kN/m</i>)	<i>l_i (m</i>)	Y _w (m)	u _i (<i>kPa</i>)	(W _i cosα _i - u _i I _i) <i>kN/m</i>	W _i sinα _i (<i>kN/m</i>)
					$Y_{s}b_{i}h_{i}$	b/cosα _i		$Y_w Z_w$	α _i (rad)	α_i (rad)
1	0.62	2	44.3	0.77	24.8	2.79	0	0	17.75	17.32
2	1.6	2	39.2	0.68	64	2.58	0	0	49.60	40.45
3	2.3	2	34.4	0.60	92	2.42	0	0	75.91	51.98
4	2.76	2	29.9	0.52	110.4	2.31	0	0	95.71	55.03
5	3	2	25.6	0.45	120	2.22	0	0	108.22	51.85
6	3.1	2	21.4	0.37	124	2.15	0	0	115.45	45.24
7	3	2	17.4	0.30	120	2.10	0	0	114.51	35.88
8	2.74	2	13.4	0.23	109.6	2.06	0	0	106.62	25.40
9	2.34	2	9.5	0.17	93.6	2.03	0	0	92.32	15.45
10	1.81	2	5.6	0.10	72.4	2.01	0	0	72.05	7.07
11	1.1	2	1.8	0.03	44	2.00	0	0	43.98	1.38
12	0.35	2	-2	-0.03	14	2.00	0	0	43.98	1.38
								TOTAL	936.08	348.44

Table 5 below, shows the calculated safety factors for six (6) different load cases.

EMBANKMENT SAFETY FACTORS						
Side of Slope	Side of Slope Load Condition		Safety F	Limit		
			Fellenius	Bishops		
Downstream	FSL	Load case 1	1.27	1.30	1.5	
	FSL + EQ	Load case 2	1.00	1.03	1.25	
	FSL	Load case 3	1.56	1.7	1.5	
Upstream	FSL + EQ	Load case 4	0.88	1.11	1.25	
-	RDD	Load case 5	0.96	1.07	1.25	
	RDD + EQ	Load case 6	0.64	0.74	1.0	

Table 5: Slope stability calculation - results

8. Evaluation Of The Results

Stability results as shown in Table 5 reveal that Fellenius Method is more conservative than Bishops Method of slices. All slopes under load case 1 to case 5 satisfy principles of equilibrium when evaluated using Bishop's Method. The only condition satisfying USBR and ADEDCR criteria is load case 3 with Safety factor of 1.56 and 1.7 using Fellenius and Bishop Method, respectively. The other conditions do not comply with the two criteria. Fellenius results for load case 4 to 6 suggest that Roodefontein Dam will experience instability when there is an Earthquake or when the dam is rapidly drawn down.

Addendum J: Registration Information

#Name?

Department of Water and Sanitation - Dam Safety Office Registration Details of a Dam Registered in terms of Dam Safety Legislation of Chapter 12 of the National Water Act (Act No. 36 of 1998)

(Please note that registration for dam safety legislation is not an entitlement for water use in terms of Chapter 4 of the National Water Act)

Departmental File No. : 12/2/	K602/02 WARMS Dam ID:	
Water management area	8 Dam Status: REG Drainage Nr: K60G	
Name of dam	ROODEFONTEIN DAM	1 00
<i>Latitude</i> 34 4 1	Longitude 23 20 1	1.00
Town nearest:	PLETTENBERG BAY	1.00
Distance from town (km)	2 WMA Breede-Gouritz	
Name of farm	ROODEFONTEIN 440 PORTION 82	
Magisterial District	KNYSNA	
Province: WESTERN CA	APE Water Management Region: WESTERN CAPE	
Date of completion	1989	
Raising or Alteration Date	2004	
River	PIESANG	
Wall type	EARTHFILL	
Wall height (m)	18	
Crest length (m)	315	
Spillway	UNCONTROLLED OGEE	
Capacity (1000 cub. m)	2003	
Surface area of water (ha)	37 Catchment area (sa km)	28
Purpose	DOMESTIC SUPPLY & INDUSTRIAL USE	
Owner	Person in Control (if not the same as the owner) DIRECTOR: SOUTHERN OPERATIONS	
DEPT OF WATER & SANITATION	MR. H. W. GELDENHUYS	
DDIVATE BAG Y 212	BITOU MUNICIPALITY	
FREIORIA		
0001	0036	
<i>Tel no.</i> (012) 336 7500	Tel no. (044) 501 3265	
Cell no.	Cell no.	
Email Fax	Email / Fax	
Designer	Contractor	
NINHAM SHAND (CAPE) INC.	HERBST BROS (PTY) LTD.CERES	
Registration date: 1/2	29/1990 Status Dam Registered as a Dam with a Safety Risk	
Size Medium Haz	ard Rating: High Category 3	
Classification date:	9/2/1987 Date Last DSE 8/16/2010	C
Date Completion Report:	3/15/2005 Number Last DSE:	3

Addendum K: Mechanical Report

ROODEFONTEIN DAM

DAM SAFETY INSPECTION OF MECHANICAL AND ELECTRICAL PLANT AT WESTERN CAPE REGION

The operation, maintenance and general condition of the mechanical and electrical plant and equipment was evaluated on 11^{TH} February 2020.

INSPECTION

-

м ь

The outlet works were found to be in a reasonable operating condition and capable of performing the function of which they were intended. The required maintenance was not performed due to the fact that there's no maintenance contract in place.

RECOMMENDATIONS

The following recommendations are made with regard to the maintenance of the equipment.

	Levels of Priority	Priority	Picture
	Rectify as soon as possible Rectify within two years Rectify within five years Rectify as soon as opportune No action required	1 2 3 4 5	
1 1 1	ISOLATING VALVES – GATE VALVES The shaft on the insolating gate valve is bent and it is difficult to operate. It	1	A1
1.2 1.3	must be repaired or replaced. Upstream gate valve is not sealing. It must be inspected and repaired. The indication on the wheel (open-close) is missing and must be rectified.	2 1	A2 A3
2 2.1 2.2	CONTROL VALVE – SLEEVE VALVE The front seal rubber on the sleeve valve is cut and must be replaced. The inside of the sleeve valve has plenty of visible corrosion marks. Some paint is gone and there are plenty of blisters. General condition of the valve is poor and must be cleaned and refurbished.	1 1	B1, B2
2.3 2.4	The mild steel grease nipple on the sleeve valve must be replaced with stainless steel ones. Open and closed indicators are missing on the sleeve valve wheels. Indicators	1 1	B3, B4
	must be added.		
3 3.1	OUTLET PIPES The paint is flaking off from under water manifold with five inlets the corrosion protection must be repaired	2	C1
3.2	The sacrificial anodes on the manifold must be checked and corroding anodes bolders must be repaired.	1	
3.3	The rusted mild steel pipe protruding out of the concrete in the valve house has been refurbished from outcide, lining has been spot repaired with Hypote 151	5	
3.4	New possibilities must be investigated for the manifold outlet works.	3	
4 4.1	GENERAL The log books must be introduced as soon as possible to ensure that a good	1	
4.2	The drawings and information on the new outlet works should have been submitted to the Directorate Strategic Asset Management for approval before the extension were done. Drawings must be submitted to update the departmental records.	1	

- 4.3 The technical information and a copy of the operating manual must be submitted to Strategic Asset Management.
- 4.4 Roof damage and security doors must be fixed to ensure the outlet works room remains dry and secure.

5 OPERATING AND MAINTENANCE PROCEDURES

•

- 5.1 To enable the establishment and maintaining the required high standards of the condition of the dams the final responsibility of the dams must be clearly defined.
- 5.2 It is considered to be the responsibility of the Operational Personnel to implement the use of and ensure adherence to the procedures specified in the logbook and to inform the main maintenance personnel of the faults and maintenance procedures specified in the logbook.
- 5.3 Inspections by Competent Artisans must be done at regular intervals as also called for in Logbooks to ensure reliability of the plant and equipment and to comply with the Occupational Health and Safety Act.
- 5.4 Provision is made in the logbooks for senior (Supervisory) Personnel to certify that the condition of the plant recorded in the Logbooks is a true reflection of the condition of the plant and equipment. This is essential to ensure that the plant and equipment is correctly operated and adequately maintained and complies with the Occupational Health and Safety Act at all times.
- 5.5 All lifting equipment to be performance tested every twelve (12) months to comply with the regulations in terms of section 43 of the OHS Act.

J. KOLAROVIC CHIEF ENGINEER STRATEGIC ASSET MANAGEMENT DATE: 104-03-2020

Khi

A. JOOSTE GRADUATE INTERN STRATEGIC ASSET MANAGEMENT DATE: OL-03-2020

Alooste

1

1