

Enquiries: B Singh

Telephone: 012 336 7531 Reference: 21/15/P5

#### MINISTER OF WATER AND SANITATION

#### NATIONAL ASSEMBLY: QUESTION 107 FOR WRITTEN REPLY

A draft reply to the above mentioned question asked by Mrs A M Dreyer (DA)is attached for your consideration.

DRAFT REPLY: RECOMMENDED/ NOT RECOMMENDED/ AMENDED

ACTING DIRECTOR-GENERAL

DATE: 13 03 2019

DRAFT REPLY: APPROVED/ NOT APPROVED/ AMENDED

NKWINTI GE, MP

MINISTER OF WATER AND SANITATION

DATE: 94 03 2019

#### NATIONAL ASSEMBLY

#### FOR WRITTEN REPLY

#### **QUESTION NO 107**

# DATE OF PUBLICATION IN INTERNAL QUESTION PAPER: 7 FEBRUARY 2019 (INTERNAL QUESTION PAPER NO. 1)

## 107. Mrs A M Dreyer (DA) to ask the Minister of Water and Sanitation:

- (1) (a) How often must his department inspect dam infrastructure with regard to (i) dam walls and (ii) spillways and (b)(i) who conducts such inspections and (ii) under what statutory provisions is the person or entity authorised;
- (2) (a) on what date was the last inspection of each dam performed by his department in Gauteng and (b) what number of dams (i) passed and (ii) failed the inspection;
- with regard to dams situated within the City of Ekurhuleni, (a) what concerns and recommendations were raised in respect of each dam, (b) on what date was the City of Ekurhuleni notified about the concerns and recommendations and (c) by what date was the City of Ekurhuleni expected to rectify all defects in the dam infrastructure, including dam walls and spillways, in each case?

  NW112E

---00000---

## THE MINISTER OF WATER AND SANITATION

- (1)(a) All dams classified as dams with a safety risk by the Directorate: Dam Safety Regulation (i.e. Dam Safety Office) and are category II and III in terms of size must be subjected to a compulsory 5 yearly dam safety evaluation by an Approved Professional Person (APP).
- (1)(b) The owner of a Category II or III dam must appoint an Approved Professional Person (APP) to conduct a dam safety evaluation at 5 years intervals. This regulatory provision is in terms of Section 118 and 119 of the National Water Act as well as Government Notice R 139 of 24 February 2012 (i.e. Dam Safety Regulations).
- (2) Refer to **Annexure A** for the inspection dates, number of dams that passed or failed the inspection in Gauteng.
- (3)(a) Refer to **Annexure B** for the APP recommendations.
- (3)(b) Refer to **Annexure C** for the letters of acceptance or rejection sent to the City of Ekurhuleni after receipt of the Dam Safety Evaluation report from the APP.
- (3)(c) Refer to Annexure C.

--00000---

NATIONAL ASSEMBLY

No.	Name of dam	Owner Name	DSE Target Date	Date Last DSE	Number	Condition
,,,	1 WITKLIP BOTTOM DAM	SCHOEMAN BOERDERY (PTY) LTD	2023/11/30	2018/11/07	Last Dae	loamyc
, 4	2 VAN DYK'S DAM	EKURHULENI METROPOLITAN MUNICIPALITY	2018/07/05		4 (	u (
(1)	3 NIGEL DAM	EKURHULENI METROPOLITAN MUNICIPALITY	2023/07/04			
7	4 MIDDLE LAKE DAM	EKURHULENI METROPOLITAN MUNICIPALITY	2023/07/04			ء اد
,	5 HOMESTEAD MEER	EKURHULENI METROPOLITAN MUNICIPALITY	2023/07/04			٥
	6 HIPPO DAM	LETAMO GAME FARM (PTY) LTD.	2023/02/28			ے ر
	7 FLEURHOF DAM	CALGRO M3 HOLDINGS (PTY) LTD	2023/03/14			2 0
3	8 LUIPAARDSVLEI DAM	RAND URANIUM (PTY) LTD.	2023/03/14	2017/11/21		ء د
51	9 THEUNIS BESTER DAM	WATERLAKE FARM HOME OWNER ASSOCIATION	2022/12/31	2017/10/31		,   -
10	10 MEYER'S HILL RESERVOIR	RAND WATER	2022/12/08	2017/10/23	2	٥
17	11 KLIPRIVIERSBERG NO 2 RESERVOIR	RAND WATER	2022/12/08	2017/10/23	3	0
12	RIETFONTEIN WESTELIKE VLOEDVERTRAGINGS DAM	DEPARTMENT OF TRANSPORT	2022/12/07	2017/11/08	2	U
13	RIETFONTEIN OOSTELIKE VLOEDVERTRAGINGS DAM	DEPARTMENT OF TRANSPORT	2022/12/07	2017/11/08	2	D
14	14 RANDJIESLAAGTE RESERVOIR	JOHANNESBURG METROPOLITAN MUNICIPALITY	2022/10/30	2017/10/25	3	
15	15 DOORNPOORT RETURN WATER	SOUTH DEEP GOLD MINE	2022/08/24	2017/03/27	1	U
16	16 ADMA DAM	WONDERFONTEIN TRUST	2022/08/23	2017/07/13	1	)
17	17 BON ACCORD DAM	BON ACCORD IRRIGATION BOARD	2022/01/30	2016/12/01	4	
18	18 VAAL BARRAGE	RAND WATER	2022/07/04	2017/03/30	2	0 0
15	19 KRAPFONTEIN DAM	SASOL MINING (PTY) LTD	2022/06/21	2017/01/30	1 ~	_ m
20	20 SYFERFONTEIN DAM	SASOL MINING (PTY) LTD	2022/06/21	2017/01/30	0 0	2 0
21	21 TWEEDRAAI DAM	SASOL MINING (PTY) LTD	2022/06/20	2017/01/30	0 0	
22	22 PANFONTEIN POND NO.7	RAND WATER	2022/05/30	2017/03/13	0 0	, ,
23	23 RUSTICANA DAM 2	ANDRE TONKIN FAMILY TRUST	2022/05/12	2017/03/23	1	ساد
24	24 RUSTICANA DAM	ANDRE TONKIN FAMILY TRUST	2022/05/12	2017/03/24	1	0
25	25 LANGERAND NO 2 RESERVOIR	RAND WATER	2022/04/12	2017/01/13	2	
26	26 BENONI NO3 RESERVOIR	RAND WATER	2022/04/12	2017/02/02	2	
27	27 MEREDALE NO 1 RESERVOIR	RAND WATER	2022/04/11	2017/01/24	2	
28	28 BRAKPAN NO2 RESERVOIR	RAND WATER	2022/04/11	2017/02/27	2	
29	29 ELANDSRAND POLLUTION CONTROL DAM	HARMONY GOLD MINING COMPANY LTD	2022/03/22	2016/12/08	· ·	2 6
8 3	30 ASTON LAKE	SCHOEMAN FARMING (PTY) LTD.	2022/02/21	2016/11/22	2	B
31	31 LAURENTIA DAM	LOUW GELDENHUYS INVESTMENTS (PTY) LTD	2022/01/31	2017/01/31	2	٥
32	32 LANCASTER DAM	MINTAILS MINING S.A (PTY) LTD	2021/12/20	2016/06/01	1	D
33	33 MODDERFONTEIN FACTORY DAM NO. 1	AECI LIMITED	2021/08/30	2016/07/29	5	Ш

Ä

			00/00/1000	00/10/02/00	L	ш
34	34 MODDERFONTEIN FACTORY DAM NO. 4	AECI LIMITED	2021/08/30	2016/0/29	n	יו
35	35 MODDERFONTEIN FACTORY DAM NO. 3	AECI LIMITED	2021/08/30	2016/07/29	2	ц,
36	36 RYNFIELD DAM NO.1	EBOTSE GOLF AND COUNTRY ESTATE	2020/08/30	2014/08/21	4	O
37	NORTH DAM	NCP CHLORCHEM (PTY) LTD	2021/04/30	2015/12/04	4	В
38	S SOLITH DAM	NCP CHLORCHEM (PTY) LTD	2021/04/30	2015/12/04	4	В
39	SCOTT STATE OF THE STATE DAM	DEPT. OF WATER & SANITATION	2021/04/30	2016/03/30	4	ш
40	SELIFES DAM	MOGALE CITY MUNICIPALITY	2020/10/15	2015/10/14	1	۵
41	1 DIEPKI OOF RETURN WATER DAM	ERGO MINING (PTY) LTD	2020/06/30	2014/06/30	2	
42		ERGO MINING (PTY) LTD	2020/06/30	2014/06/30	2	
43	MAILIRA POWERSTATION ASH DUMP DAM NO.3	ESKOM-MAJUBA POWER STATION	2015/06/01	2014/01/21	1	
44	44 PRETORIA-BUITEKLUB DAM	PRETORIA-BUITEKLUB	2022/05/31	2014/12/01	3	В
45	45 VI AKFONTEIN RESERVOIR	RAND WATER	2025/04/29	2014/12/01	2	
46	46 HARTBEESPOORT DAM	DEPT. OF WATER & SANITATION	2019/03/28	2014/03/26	4	8
4	47 OLIFANTSVLEI MATURATION DAM	JOHANNESBURG METROPOLITAN MUNICIPALITY		2013/09/20	2	
48	48 HAMBERG	JOHANNESBURG METROPOLITAN MUNICIPALITY		2013/06/28	2	
45	49 PETER WRIGHT	EZULWUNI MINING Co. (PTY) LTD		2013/03/07	3	
12	50 DOORNKOP RETURN WATER DAM	HARMONY GOLD MINING COMPANY		2013/03/14	2	
5.1	51 CINDERELLA DAM	ERGO MINING (PTY) LTD	2018/05/16	2012/01/22	3	U
5,2	52 BRAKPAN TAILINGS DAM	ERGO MINING (PTY) LTD		2013/01/17	1	В
53	53 RIETVLEI DAM (was A210/05)	TSHWANE METROPOLITAN MUNICIPALITY		2012/10/18	4	
54	54 ROODEPLAAT DAM	DEPT. OF WATER & SANITATION		2011/08/15	4	U
55	55 NORTHERN FARM DAM P1	JOHANNESBURG METROPOLITAN MUNICIPALITY		2012/03/13	1	
56	56 NORTHERN FARM DAM P2	JOHANNESBURG METROPOLITAN MUNICIPALITY		2012/03/13	1	
5.	57 NORTHERN FARM DAM P4	JOHANNESBURG METROPOLITAN MUNICIPALITY		2012/03/13	2	
55	58 NORTHERN FARM DAM P5	JOHANNESBURG METROPOLITAN MUNICIPALITY		2012/03/13	2	
55	59 NORTHERN WORKS DAM NO.1	JOHANNESBURG METROPOLITAN MUNICIPALITY		2012/03/13	2	
9	60 NORTHENONNARN WORKS DAM NO.2	JOHANNESBURG METROPOLITAN MUNICIPALITY		2012/03/13	8	
9	61 KLIPDRIFT DAM	DEPT. OF WATER & SANITATION		2011/09/16	3	
.9	62 EAGLE CANYON DAM NO.5	EAGLE CANYON GOLF ESTATE (PTY) LTD		2011/09/19	2	
9	63 GROOTVLEI P/S RES 1 (North)&2(South)	ESKOM		2010/01/26	4	
9	64 ZINCOR RETURN WATER DAM	Senior Manager		2010/06/04	1	
19	65 ROODEPOORT SPORTKOMPLEKS LAKE/MEER	JOHANNESBURG METROPOLITAN MUNICIPALITY		2011/03/03	1	
et Ot	66 PRINCESS DAM	JOHANNESBURG METROPOLITAN MUNICIPALITY		2011/01/27	2	
9	67 GOLDEN HARVEST DAM	JOHANNESBURG METROPOLITAN MUNICIPALITY		2011/01/27	3	
9	68 CAMDEN RESERVOIR NO.3	DEPT. OF WATER & SANITATION		2007/10/31	2	
9	69 NO. 7 ANTI POLLUTION DAM	ANGLOGOLD ASHANTI LIMITED		2007/01/16	1	
7	70 DRIEFONTEIN 137 IS	MOONSTONE INVESTMENTS II (PTY) LTD.		2008/03/12	1	

RAND WATER	2017/04/13	2003/01/29	7	D
	2018/11/30	10/00/0000		
SAPI E LOI DINOS HE		TU/2U/6UU2	1	
SABLE HULDINGS LID	2018/01/31		0	
	2017/03/31		0	
TSHWANE METROPOLITAN MUNICIPALITY	2017/03/31	2007/05/28	1	
TSHWANE METROPOLITAN MUNICIPALITY	2017/03/31	10/01/1000	1	
ENVIROSERV WASTE MANAGEMENT PTY LTD	2016/04/29	10/71/007	C	
J.J JORDAAN FAMILIE TRUST	2017/04/28			
RAND WATER	07/10/1407	20/01/8/10/26	2 6	
RAND WATER	2013/09/30	2010/10/20	7 0	
RAND WATER		2018/08/31	2 0	
RAND WATER		2018/10/12	2 0	
RAND WATER		2018/08/31	7 (	
RAND WATER		2018/06/11	4 (	
RAND WATER	2021/12/30	2018/08/11	7 (	
RAND WATER	00 / /	00/00/01	7 (	۵
RAND WATER	20/21/2/08	2010/05/29	7 (	ماد
RAND WATER	00/21/2202	2010/11/20	7 (	ر
RAND WATER		2016/11/20	0 0	
ESKOM HOLDING LTD.		2010/11/20	2	(
TSHWANE METROPOLITAN MUNICIPALITY		2018/11/20		
RAND WATER		2018/11/30	7	
RAND WATER		2010/10/20	7 0	
RAND WATER		2019/06/21	2	
EKURHULENI METROPOLITAN MUNICIPALITY		2010/10/13	7 8	
RAND WATER	2021/12/30	2018/07/04	, ,	α
ENVIROSERV WASTE MANAGEMENT PTY LTD		2015/08/28	2	a a
CRADLE MOON LAKESIDE GAME LODGE	2019/11/30	2011/11/30	-	
RAND WATER	2019/11/30	2014/11/30		
CITY OF TSHWANE	2019/11/30	2013/04/17	, ,	
RAND WATER	2019/06/25	2014/06/25	1 0	
PORTLAND CEMENT CO. LTD.	2019/08/31		1 0	
SAND WATER	2018/11/30	2014/07/03	,	
SAND WATER	2018/11/30	2013/05/07	2	
CITY OF JOHANNESBURG METROPOLITAN MUNICIPALITY	2018/11/30	1999/04/16	1	
	TSHWANE METROPOLITAN MUNICIPALITY ENVIROSERV WASTE MANAGEMENT PTY LTD J.J JORDAAN FAMILIE TRUST RAND WATER EKURHULENI METROPOLITAN MUNICIPALITY RAND WATER RAND WATER CITY OF TSHWANE RAND WATER	Y LTD  ALITY  AL	TYT 2017/03/31  YLTD 2016/04/29  2013/09/30  2013/09/30  2013/09/30  2013/09/30  2013/09/30  2013/09/30  2013/09/30  2013/09/30  2019/11/30  2019/11/30  2019/11/30  2019/11/30  2019/11/30  2019/11/30  2019/06/25  2019/08/31  2018/11/30  2018/11/30  2018/11/30  2018/11/30	TY

-

			20/10/0700	20/ 20/ 0200	-	
106	106 ORLANDO POWER STATION DAM	JOHANNESBURG METROPOLITAN MUNICIPALITY	2018/07/31	70/90/5107	4	
107		JOHANNESBURG WATER (PTY) LTD	2018/10/31	2013/09/10	33	
100		TSHWANE METROPOLITAN COUNCIL	2018/03/30	2012/10/11	2	
100	CONDEDCTE DAM		2017/07/31	2014/09/11	2	
110			2017/11/30	2010/05/10	1	O
111		DEPARTMENT OF PUBLIC WORKS	2016/11/30	2006/09/18	1	
111	M	DEPARTMENT OF PUBLIC WORKS	2016/11/30	2006/09/18	1	
113		RAND WATER	2017/05/31	2010/08/25	1	
11/		WEST RAND DISTRICT MUNICIPALITY	2017/09/29	1998/09/11	1	
115	MA	TSHWANE METROPOLITAN MUNICIPALITY	2018/07/12		0	
116	CENTRE DAM	ESKOM: INFRASTRUCTURE DESIGN	2017/03/31	2010/01/02	1	
117	117 EMMARENTIA DAM	JOHANNESBURG METROPOLITAN MUNICIPALITY	2018/09/18	2009/06/03	3	
118	118 BETHAL DAM	GOVAN MBEKI LOCAL MUNICIPALITY	2018/05/30	2004/07/13	1	
119	119 WESTDENE DAM	JOHANNESBURG METROPOLITAN MUNICIPALITY	2018/09/30	2009/05/27	3	U
120	120 RIFTSPRIIT DAM 2	ВОТНА Ј.Н.	2018/12/31		0	
121	121 RIFTSPRIIT DAM 1		2018/12/31		0	
121	122 KI FINE ONTEIN 357 DAM	SAAYMAN FAMILY TRUST	2018/11/30		0	
173	123 KI IPFONTEIN NOT RESERVOIR	RAND WATER	2014/03/31	2008/07/04	1	
124	124 BALFOUR DAM	DR PIXLEY KA SEME LOCAL MUNICIPALITY	2018/12/09	2004/11/24	1	
125	125 SCHUII HOEK DAM	DR PIXLEY KA SEME LOCAL MUNICIPALITY	2018/12/09	2004/11/24	1	
126	126 BALFOUR/SIYATHEMBA DAM	DIPALESENG MUNICIPALITY	2016/08/31		0	
127	HOLFONTEIN LEACHATE STORAGE DAM - previously R201/33	ENVIROSERV WASTE MANAGEMENT PTY LTD	2006/09/30	2006/10/01	1	
128	GROOTVLEI POWERSTATION TERMINAL RESERVOIR 2	ESKOM		1988/01/31	1	
129	129 REGIONAL TAILINGS STORAGE FACILITY	SIBANYE GOLD			0	

A Score Card for the Condition of a Dam based on the "Recommendations and Findings of a Dam Safety Evaluation Report" by an Approved Professional

	unsafe condition. The Assinging of the score card system only started late in 2014 triefelore some dams will not have a condition symbol.
Table : Dam Safety: Proposed Score Card for the Condition of a Dam	
Symbol / Score	Analysis of condition from the Recommendations and Findings of a Dam Safety Evaluation Report by an APP
Dam in good co of longer than 5 municipalities.)	Dam in good condition and routine maintenance are acceptably up to date. An evaluation interval of longer than 5 years can be recommended (if the owner request it or for farmers/ smaller municipalities.)

В	Dam in reasonable condition but not complying to modern standards. Only routine maintenance and routine inspections recommended. An evaluation interval of longer than 5 years cannot be recommended.
O	Significant outstanding maintenance by the normal operation and maintenance staff recommended restoring dam to a functional state. Elementary monitoring systems like settlement beacons and flow monitoring included here.
Q	Significant rehabilitation recommended to restore dam components to its original state for example repair major erosion or cavitation's, repair slope protection, reinstate crest level, refurbish outlet works or gates. Work is considered significant rehabilitation if it is outside the capacity of the normal operation and maintenance staff and the appointment of a contractor is necessary and the work should be done under guidance of an APP. Drafting of an Operation and Maintenance Manual and or Emergency Preparedness Plan and install sophisticated monitoring instruments under guidance of an APP also included here.
Ш	Upgrading recommended for example increase spillway capacity, increase freeboard, provide buttress / thicken dam to improve stability or install stress cables, install slope protection, install additional drainage or grouting or water seals to reduce leakage. A licence to alter and the services of an APP will be required.
L	Dam unsafe. Restrictions on operation recommended, for example water level may not exceed a specified level.

ne



No of dam	Name of dam	Owner Name	Category	DSE Target Date	Date Last DSE	Number Last DSE	Condition ymbol
C212/46	KLEINFONTEIN DAM	EKURHULENI METROPOLITAN MUNICIPALITY	2		2-Aug-17	4	7
		RECOMMENDATIONS FO	R REMEDIAL	ACTIONS			
		Short 1	Геrm				
1	An operation and ma	intenance manual, which includes a	n emergency i	reparedness r	lan is required.		
2	The state of the s	apacity of the spillway must be incre				e flood. Thi	s work is
-		allocated a very high priority.	asca to accom	infodute the fi	iaxiiiiaiii possibi	e noou. mi	3 WUIK 13
		egetation in the spillway approach cl			ta atau sanatalan		
3						ed urgent.	
4	The immediate remov	val of the screens and galvanised me		way approach	channel.		
	T	Long T					
1		ed out in the spillway where required					
2	The elimination of wa	ater hyacinth in the dam basin.					
3	A series of stability ar	nalyses of the mine dump to assess t	he potential d	anger of a slip	failure into the	dam basin.	W-1863
221/68	VAN DYK'S DAM	EKURHULENI METROPOLITAN	2	5-Jul-23	25-Apr-18	2	D
		MUNICIPALITY			20 1.10		
		RECOMMENDATIONS FO					
		Recommendation(s) regard	ding maintena	ince work:			
1	The outlet pipe must	be grouted to prevent piping failure;	as recommer	nded in the pre	vious dam safet	y inspection	1.
2	All trees with trunk di	ameter of less than 100mm and shru	ubs must be e				
2							
3	The reeds growing at	the FSL on the upstream slope must	be eradicated	l as far as pract	tically possible.		
4	The embankment sho	ould be fenced to prevent cattle gaini	ng access to t	he embankme	nts		
		nt the operation and maintenance m				maintanan	as of the
5	1.00	it the operation and maintenance in	anual to form	anse the prope	er operation and	maintenan	ce of the
	dam.	December detion (s) recording rout	ine inemedia		-t		
		Recommendation(s) regarding rout					
1	Inree monthly routine	e inspections focussing on any signs				ne persons	in control
		Recommendation(s) and motivation					
1		o the spillway guide walls and erosic	on control stru	ctures should	be rehabilitated.		4-11-11-11-11-11-11-11-11-11-11-11-11-11
2		o the spillway guide walls and erosic eepage water at the left embankme	on control stru nt toe must fa	ctures should	be rehabilitated.		in
2	The free drainage of s	o the spillway guide walls and erosic eepage water at the left embankme Other recomm	on control stru nt toe must fa endations:	ctures should cilitated by the	be rehabilitated installation of a	subsoil dra	
	The free drainage of s	o the spillway guide walls and erosic eepage water at the left embankme	on control stru nt toe must fa endations:	ctures should cilitated by the	be rehabilitated installation of a	subsoil dra	
2	The free drainage of s  A detail survey of the	o the spillway guide walls and erosic eepage water at the left embankme Other recomm dam basin area should be undertake EKURHULENI METROPOLITAN	on control stru nt toe must fa endations:	ctures should cilitated by the	be rehabilitated installation of a	subsoil dra	
1	The free drainage of s  A detail survey of the	o the spillway guide walls and erosic eepage water at the left embankme Other recomm dam basin area should be undertake EKURHULENI METROPOLITAN MUNICIPALITY	on control strunt toe must fairendations: en including the	ctures should cilitated by the e relevant hou 5-Jul-23	be rehabilitated e installation of a uses which may b	subsoil dra	d during
1	The free drainage of s  A detail survey of the	o the spillway guide walls and erosic eepage water at the left embankmer Other recomm dam basin area should be undertake EKURHULENI METROPOLITAN MUNICIPALITY RECOMMENDATIONS FOR	on control strunt toe must farendations: en including the	ctures should cilitated by the e relevant hou 5-Jul-23	be rehabilitated e installation of a uses which may b	subsoil dra	d during
1 212/61	The free drainage of s  A detail survey of the  ALEXANDER DAM	o the spillway guide walls and erosic eepage water at the left embankmer Other recomm dam basin area should be undertake EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard	on control strunt toe must failendations: en including the 2 R REMEDIAL A	ctures should cilitated by the e relevant hou 5-Jul-23 ACTIONS nce work:	be rehabilitated. e installation of a uses which may b 26-Apr-18	a subsoil dra pe inundated 3	d during C
1 212/61	The free drainage of s  A detail survey of the  ALEXANDER DAM  The outlet works at th	o the spillway guide walls and erosic eepage water at the left embankmen.  Other recomm dam basin area should be undertaken.  EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard to spillway section with the excessive	on control structure to e must faitendations: en including the graph of the graph o	ctures should cilitated by the e relevant hou 5-Jul-23 ACTIONS nce work:	be rehabilitated. e installation of a uses which may b 26-Apr-18	a subsoil dra pe inundated 3	d during C
2 1 212/61	A detail survey of the  ALEXANDER DAM  The outlet works at th maintained without de	o the spillway guide walls and erosic eepage water at the left embankmen.  Other recomm dam basin area should be undertake.  EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard to spillway section with the excessive elay (including corrosion protection)	on control strumt toe must farendations: en including the control strumt farendations: en including the control strumt farendation farenda	ctures should cilitated by the e relevant hou 5-Jul-23 ccTIONS nce work:	be rehabilitated. e installation of a ses which may b 26-Apr-18  cut open and in	se inundated  3 spected, see	d during  C  rviced and
1 212/61 1	A detail survey of the  ALEXANDER DAM  The outlet works at th maintained without de	o the spillway guide walls and erosic eepage water at the left embankmen.  Other recomm dam basin area should be undertaken.  EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard to spillway section with the excessive	on control strumt toe must farendations: en including the control strumt farendations: en including the control strumt farendation farenda	ctures should cilitated by the e relevant hou 5-Jul-23 CCTIONS nce work:	be rehabilitated. e installation of a ses which may b 26-Apr-18  cut open and in	se inundated  3 spected, see	d during C
1 212/61 1	A detail survey of the  ALEXANDER DAM  The outlet works at th maintained without de	o the spillway guide walls and erosic eepage water at the left embankmen.  Other recomm dam basin area should be undertake.  EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard to spillway section with the excessive elay (including corrosion protection)	on control structure to e must fair toe must fair endations: en including the structure of	ctures should cilitated by the e relevant hou 5-Jul-23 CCTIONS nce work: rowth must be ees and shrubs	be rehabilitated. e installation of a sess which may b 26-Apr-18  cut open and in	a subsoil dra be inundated 3 spected, ser	d during  C  rviced and within 10
1 212/61 1 2	The free drainage of s  A detail survey of the  ALEXANDER DAM  The outlet works at th maintained without de  Other trees, with trunk metres of Alexander D	o the spillway guide walls and erosic eepage water at the left embankmen Other recomm dam basin area should be undertake EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard the spillway section with the excessive elay (including corrosion protection) k diameter of less than 100mm, all B	on control structure to e must faitendations: en including the structure of the structure o	e relevant hou  5-Jul-23  ACTIONS  nce work: rowth must be  ees and shrubs y spillway discl	be rehabilitated. e installation of a sess which may b 26-Apr-18  cut open and in a must be eradicated.	spected, ser	C  rviced and within 10 alls.
2 1 212/61 1 2	The free drainage of s  A detail survey of the  ALEXANDER DAM  The outlet works at th maintained without de  Other trees, with trunk metres of Alexander D  The reeds growing at the	o the spillway guide walls and erosic eepage water at the left embankmen Other recomm dam basin area should be undertake EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard the spillway section with the excessive elay (including corrosion protection) and wall structure, including the main the full supply level (FSL) on the upst	on control structure to e must fair toe must fair endations: en including the structure of	e relevant hou  5-Jul-23  ACTIONS  nce work: rowth must be  ees and shrubs y spillway discl	be rehabilitated. e installation of a sess which may b 26-Apr-18  cut open and in a must be eradicated.	spected, ser	C  rviced and within 10 alls.
1 212/61 1 2 3 4	The free drainage of s  A detail survey of the  ALEXANDER DAM  The outlet works at th maintained without de  Other trees, with trunk metres of Alexander D  The reeds growing at t  All ant and termite nes	o the spillway guide walls and erosic eepage water at the left embankmen.  Other recomm dam basin area should be undertake.  EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard the spillway section with the excessive elay (including corrosion protection) and wall structure, including the main the full supply level (FSL) on the upst sts must be eradicated on an ongoin.	on control strumt toe must farendations: en including the structure of the	ctures should cilitated by the e relevant hou 5-Jul-23 CCTIONS nce work: rowth must be ees and shrubs y spillway disclust be eradicated.	be rehabilitated. e installation of a sess which may b 26-Apr-18  cut open and in s must be eradica harge channels a ted as far as prace	spected, ser	C rviced and within 10 alls.
1 212/61 1 2 3 4	The free drainage of s  A detail survey of the  ALEXANDER DAM  The outlet works at th maintained without de  Other trees, with truni metres of Alexander D  The reeds growing at t  All ant and termite nes  The toe drain manhole	o the spillway guide walls and erosic eepage water at the left embankmen Other recomm dam basin area should be undertaked EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard the spillway section with the excessive elay (including corrosion protection) and wall structure, including the main the full supply level (FSL) on the upst sts must be eradicated on an ongoin e, including the drain pipe downstread	on control strumt toe must farendations: en including the structure of the	ctures should cilitated by the e relevant hou 5-Jul-23 CCTIONS nce work: rowth must be ees and shrubs y spillway disclust be eradicated.	be rehabilitated. e installation of a sess which may b 26-Apr-18  cut open and in s must be eradica harge channels a ted as far as prace	spected, ser	C rviced and within 10 alls.
1 212/61 1 2 3 4 5	The free drainage of some A detail survey of the ALEXANDER DAM  The outlet works at the maintained without details of Alexander Details	o the spillway guide walls and erosic eepage water at the left embankmen.  Other recomm dam basin area should be undertake.  EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard the spillway section with the excessive elay (including corrosion protection) and wall structure, including the main the full supply level (FSL) on the upst ests must be eradicated on an ongoin expincluding the drain pipe downstread closed.	on control structure to emust failendations: en including the graph of	e relevant hou  5-Jul-23  CCTIONS  nce work: rowth must be  ees and shrubs y spillway discl  ust be eradicat	be rehabilitated. e installation of a ses which may b 26-Apr-18  cut open and in a must be eradica harge channels a ted as far as prac	spected, see atted on and guide was citically poss	C rviced and within 10 alls. ible.
1 212/61 1 2 3 4 5	The free drainage of some A detail survey of the ALEXANDER DAM  The outlet works at the maintained without details of Alexander Details	o the spillway guide walls and erosic eepage water at the left embankmen Other recomm dam basin area should be undertaked.  EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard the spillway section with the excessive elay (including corrosion protection) and wall structure, including the main the full supply level (FSL) on the upst sts must be eradicated on an ongoin e, including the drain pipe downstread closed.	on control structure to emust failendations: en including the graph of	e relevant hou  5-Jul-23  CCTIONS  nce work: rowth must be  ees and shrubs y spillway discl  ust be eradicat	be rehabilitated. e installation of a ses which may b 26-Apr-18  cut open and in a must be eradica harge channels a ted as far as prac	spected, see atted on and guide was citically poss	C rviced and within 10 alls. ible.
1 212/61 1 2 3 4 5 6	The free drainage of some A detail survey of the ALEXANDER DAM  The outlet works at the maintained without details of Alexander Details	o the spillway guide walls and erosic eepage water at the left embankmen.  Other recomm dam basin area should be undertake.  EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard the spillway section with the excessive elay (including corrosion protection) and wall structure, including the main the full supply level (FSL) on the upst ests must be eradicated on an ongoin expending the drain pipe downstread control of the embankment crest must be to the control of the embankment crest must be the full supply level (FSL) and the embankment crest must be the control of the embankment crest must be the full supply level (FSL) and the embankment crest must be the full supply level (FSL) and the embankment crest must be the control of the con	on control structure to emust failendations: en including the graph of the control of the contro	e relevant hou  5-Jul-23  ACTIONS  nce work: rowth must be  ees and shrubs y spillway discl  ust be eradicat  eaned of any li  ding the dama	be rehabilitated. I installation of a sess which may be seen which may be cut open and in the service of the se	spected, see atted on and guide was citically possible manhole evehicles dr	C rviced and within 10 alls. ible.
1 212/61 1 2 3 4 5 6	The free drainage of some A detail survey of the ALEXANDER DAM  The outlet works at the maintained without details of Alexander Details	o the spillway guide walls and erosic eepage water at the left embankmen Other recomm dam basin area should be undertaked.  EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard the spillway section with the excessive elay (including corrosion protection) and wall structure, including the main the full supply level (FSL) on the upst sts must be eradicated on an ongoin e, including the drain pipe downstreationsed. In the embankment crest must be tall intenance manual should updated as intenance manual should	on control structure to emust failendations: en including the graph of the control of the contro	e relevant hou  5-Jul-23  ACTIONS  nce work: rowth must be  ees and shrubs y spillway discl  ust be eradicat  eaned of any li  ding the dama	be rehabilitated. I installation of a sess which may be seen which may be cut open and in the service of the se	spected, see atted on and guide was citically possible manhole evehicles dr	C rviced and within 10 alls. ible.
1 212/61 1 2 3 4 5 6	The free drainage of some A detail survey of the ALEXANDER DAM  The outlet works at the maintained without details of Alexander Details	o the spillway guide walls and erosic eepage water at the left embankmen.  Other recomm dam basin area should be undertake.  EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard the spillway section with the excessive elay (including corrosion protection) and wall structure, including the main the full supply level (FSL) on the upst ests must be eradicated on an ongoin expension, including the drain pipe downstreations on the embankment crest must be the intenance manual should updated as including.	on control structure to emust failendations: en including the grant of the control structure of	e relevant hou  5-Jul-23  CCTIONS  nce work: rowth must be  ees and shrubs y spillway discl  ust be eradicat  eaned of any li  ding the dama ed to formalise	be rehabilitated. I installation of a sess which may be seen which may be cut open and in the second as far as practical as fa	spected, see atted on and guide was citically possible manhole evehicles dr	C rviced and within 10 alls. ible.
1 212/61 1 2 3 4 5 6 7	The free drainage of s  A detail survey of the  ALEXANDER DAM  The outlet works at th maintained without de  Other trees, with trunk metres of Alexander D  The reeds growing at t  All ant and termite nes The toe drain manhole must be replaced and Low points and rutting the embankment crest The operation and mai maintenance of the da	o the spillway guide walls and erosic eepage water at the left embankmen Other recomm dam basin area should be undertaked EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard to spillway section with the excessive elay (including corrosion protection) and wall structure, including the main the full supply level (FSL) on the upst ests must be eradicated on an ongoin ele, including the drain pipe downstreationsed. So on the embankment crest must be the intenance manual should updated as im.  Recommendation(s) regarding routing the recommendation(s) regarding routing the manual should updated as im.	on control structure to e must farendations: en including the sent and auxiliar ream slope must be clarepaired including implement in einspection	ctures should cilitated by the e relevant hour 5-Jul-23 ACTIONS INCE WORK: Towth must be ees and shrubs by spillway disclust be eradical eaned of any liding the dama ed to formalises and monitor	be rehabilitated. It installation of a sess which may be 26-Apr-18  cut open and in a smust be eradicated as far as practiced	spected, see ated on and guide was circally possible manhole evehicles draward and	C rviced and within 10 alls. ible. cover
1 212/61 1 2 3 4 5 6 7	The free drainage of s  A detail survey of the  ALEXANDER DAM  The outlet works at th maintained without de  Other trees, with trunk metres of Alexander D  The reeds growing at the All ant and termite ness The toe drain manhole must be replaced and Low points and rutting the embankment crest The operation and main maintenance of the da  Three monthly routine	o the spillway guide walls and erosic eepage water at the left embankmen.  Other recomm dam basin area should be undertake.  EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard to spillway section with the excessive elay (including corrosion protection) and wall structure, including the main the full supply level (FSL) on the upst ests must be eradicated on an ongoin est, including the drain pipe downstreations. In the embankment crest must be the intenance manual should updated as the intenance manual should updated as the embankment crest must be endered in the embankment of the emban	on control struction to e must farendations: en including the sent including the sent including the sent including the sent including maintenate evegetation good including maintenate every sent including the sent including	ctures should cilitated by the e relevant hour 5-Jul-23 ACTIONS INCE WORK: Towth must be ees and shrubs by spillway disclust be eradical eaned of any liding the dama ed to formalises and monitor	be rehabilitated. It installation of a sess which may be 26-Apr-18  cut open and in a smust be eradicated as far as practiced	spected, see ated on and guide was circally possible manhole evehicles draward and	C  rviced and within 10 alls. ible.  cover
1 212/61 1 2 3 4 5 6 7	The free drainage of s  A detail survey of the  ALEXANDER DAM  The outlet works at th maintained without de  Other trees, with trunk metres of Alexander D  The reeds growing at the All ant and termite ness The toe drain manhole must be replaced and Low points and rutting the embankment crest The operation and main maintenance of the da  Three monthly routine	o the spillway guide walls and erosic eepage water at the left embankmen.  Other recomm dam basin area should be undertaken.  EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard the spillway section with the excessive elay (including corrosion protection) and wall structure, including the main the full supply level (FSL) on the upst ests must be eradicated on an ongoin est, including the drain pipe downstreations of the embankment crest must be the internance manual should updated and the embankment crest must be the internance manual should updated and the embankment of the embankment	on control struction control struction control struction to emust farendations:  en including the struction gradient of the structure of impending farending farending farending farending.	ctures should cilitated by the e relevant hour 5-Jul-23 ACTIONS INCE WORK: Towth must be ees and shrubs by spillway disclust be eradical eaned of any liding the dama ed to formalises and monitor	be rehabilitated. It installation of a sess which may be 26-Apr-18  cut open and in a smust be eradicated as far as practiced	spected, see ated on and guide was circally possible manhole evehicles draward and	C rviced and within 10 alls. ible. cover
1 212/61 1 2 3 4 5 6 7	The free drainage of s  A detail survey of the  ALEXANDER DAM  The outlet works at th maintained without de  Other trees, with trunk metres of Alexander D  The reeds growing at the All ant and termite ness The toe drain manhole must be replaced and Low points and rutting the embankment crest The operation and main maintenance of the da  Three monthly routine	o the spillway guide walls and erosic eepage water at the left embankmen.  Other recomm dam basin area should be undertake.  EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard to spillway section with the excessive elay (including corrosion protection) and wall structure, including the main the full supply level (FSL) on the upst ests must be eradicated on an ongoin est, including the drain pipe downstreations. In the embankment crest must be the intenance manual should updated as the intenance manual should updated as the embankment crest must be endered in the embankment of the emban	on control struction control struction control struction to emust farendations:  en including the struction gradient of the structure of impending farending farending farending farending.	ctures should cilitated by the e relevant hour 5-Jul-23 ACTIONS INCE WORK: Towth must be ees and shrubs by spillway disclust be eradical eaned of any liding the dama ed to formalises and monitor	be rehabilitated. It installation of a sess which may be 26-Apr-18  cut open and in a smust be eradicated as far as practiced	spected, see ated on and guide was circally possible manhole evehicles draward and	C  rviced and within 10 alls. ible.  cover
1 212/61 1 2 3 4 5 6 7	The free drainage of some A detail survey of the ALEXANDER DAM  The outlet works at the maintained without described of Alexander D. The reeds growing at the composition of the dam should be in the dam should be in the detail survey of the dam should be in the detail survey of the dam should be in the	o the spillway guide walls and erosic eepage water at the left embankmen.  Other recomm dam basin area should be undertaken.  EKURHULENI METROPOLITAN MUNICIPALITY  RECOMMENDATIONS FOR Recommendation(s) regard the spillway section with the excessive elay (including corrosion protection) and wall structure, including the main the full supply level (FSL) on the upst ests must be eradicated on an ongoin est, including the drain pipe downstreations of the embankment crest must be the internance manual should updated and the embankment crest must be the internance manual should updated and the embankment of the embankment	on control struction control struction control struction control struction control struction control c	ctures should cilitated by the erelevant hour 5-Jul-23 CCTIONS nce work: rowth must be ees and shrubs y spillway disclust be eradicate eaned of any liding the dama ed to formalise s and monitor failure should be cilitated by the control of the co	be rehabilitated. I installation of a sess which may be 26-Apr-18  cut open and in semust be eradicated as far as practiced as	spected, ser ated on and and guide was ctically poss the manhole e vehicles drawaration and	C  rviced and within 10 alls. ible.  cover

C221/63	ALBERTON DAM	EKURHULENI METROPOLITAN	2	4-Ju	1.22	16-Mar-18	. T		Τ
		MUNICIPALITY  RECOMMENDATIONS				10-10141-16	<u> </u>	2	D
		Recommendation(s) reg					-		
1	The outlet works	including outlet pipe and valve should	be serviced			ithout delay	(inclu	ıding drai	ining of th
	standing water in	the manhole and corrosion protection	n).						
2	appropriate.	the toe drain and outlet pipe should b							
3	The digging and b	urrowing animals must be prevented a	access to the	dam wall a	s they	are damaging	g the	dam wall	I.
4	The localised dam	age on the embankment crest and do	wnstream sle	ope and slo	oe prot	ection should	d be r	epaired.	
5	dam.	l maintenance manual must be implen					nd ma	aintenand	e of the
	<b></b>	Recommendation(s) regarding ro	utine inspec	tions and m	onitor	ing:			
1	of the dam should	itine inspections focussing on any sign be instructed how to do inspections o	ns of impendi or monitoring	ing failure s	nould b	e conducted	. The	persons	in control
		Recommendation(s) and motivat	ion regardin	g betterme	nt wor	ks:			
1	The extent of the s drainage ditch insta	eepage through the embankment and alled downstream should lower the ph	d or foundation	on is of con	ern an	d a subsoil to	oe dra	ain togetl age.	her with a
2	should be investiga	liary spillway discharge may impact or rm area. The extent of the inundation ted. This may include the option to clo compensate for the loss of the right l	n and options ose off the ri	s to address ght bank au	possib xiliary	le inundation	n of th	a anima	Loons
		Other recomn							
1	Upgrading of the cube undertaken to de	lverts downstream was previously rec etermine options to upgrade the road	commended	(Van Blader	en and	White: 2005	5). An	investiga	tion may
212/51	NIGEL DAM	EKURHULENI METROPOLITAN MUNICIPALITY	2	4-Jul-2	3	23-Nov-17		4	D
		RECOMMENDATIONS FO							
1	The outlet pipe and	Recommendation(s) regard Fulton sluice gate must be serviced an				cluding corre	osion	protectio	on).
2	All trees with trunk of	diameter of less than 100mm and shru he main and auxiliary spillway dischar	ubs must be						
3		t the FSL on the upstream slope must		das faras r		D			
4	All ant and termite n	ests must be eradicated on an ongoin	g hasis	u as iai as p	ractica	ny possible.			
5		ne lack of handrails on the access brid		llway and w	et well	inlet should	be inv	vestigate	d.
6		nt the operation and maintenance ma							- 1
7	Cracks on the concre	te spillway and in the guide walls shou	ıld bo ronair	o d					
	and don't le	Recommendation(s) regarding routing			itorina	•			
1	Three monthly routin	e inspections focussing on any signs o	of impending	failure shou	ild be c	onducted Ti	he ne	rsone in a	control
	of the dam should be	instructed how to do inspections or n	monitoring.				- pei	. 30/13 111 (	Sind Of
T.	The	Recommendation(s) and motivation	regarding b	etterment	works:				$\neg$
1	a geological and geote	e at the left flank next to the guide wa echnical investigation and design repo ent potential future internal erosion in	ort (including	ehabilitated a designed	. The r draina	ehabilitation ge system an	work d com	should in	nclude
2	ehabilitated while rei ehabilitation work fo	in southern embankment crest must b nstating a section of western embank r the western embankment crest shou ting analysis as part of the rehabilitati	ment as a fu ald include a	se plug type	spillw	av at an anni	ronria	te level	Γhe I
2/44 N	MIDDLE LAKE DAIN I	EKURHULENI METROPOLITAN MUNICIPALITY	2	4-Jul-23	7-	-Dec-17	4		D
		RECOMMENDATIONS FOR I							
		Recommendation(s) regardin	g maintenar	nce work:					

	All vegetation growing	ng in the concrete joints in the spillway	including t	he discharge ch	nannel and stillir	ng basin mu	ust be		
1	removed.								
٦	All trees, with trunk diameter of less than 100mm, and shrubs must be eradicated on and within 10 metres of Middle Lake wall structure including the main and auxiliary spillway discharge channel.								
2	wall structure includi	ng the main and auxiliary spillway disc	charge chan	nel.					
3	The reeds growing at	the FSL on the upstream slope must I	oe eradicate	d as far as prac	tically possible.				
4	Update and impleme dam.	nt the operation and maintenance ma	nual to forn	nalise the prop	er operation an	d maintena	ince of the		
		Recommendation(s) regarding routi	ne inspectio	ns and monito	ring:				
1	Three monthly routin	ne inspections focussing on any signs o	of impending	g failure should	be conducted.	The person	s in contro		
		Recommendation(s) and motivation							
1	Low points on the en	nbankment crests where not protected	d with amor	flex blocks mus	st be repaired ar	nd the non-	overspill		
212/45	HOMESTEAD MEER	EKURHULENI METROPOLITAN MUNICIPALITY	2	4-Jul-23	7-Dec-17	4	С		
		RECOMMENDATIONS FOR	REMEDIAL	ACTIONS					
		Recommendation(s) regardi	_						
1		t the outlet pipes must be drained and		nust be service	d and maintaine	d. Howeve	r if no		
		e outlet pipes must be sealed and gro							
2	All trees with trunk d	iameter of less than 100mm and shrul	os must be e	eradicated on a	nd within 20 me	tres of Ho	mestead		
		cluding the auxiliary spillway discharg							
		cluding the drainage pipe must be clea							
3	inspections. The man	hole cover must be recovered on the	downstream	i slope and ma	nhole no. 4 mus	t be closed			
4	The reeds growing at	the FSL on the upstream slope must b	e eradicate	d as far as prac	tically possible.				
-	Update and impleme	nt the operation and maintenance ma	nual to form	nalise the prop	er operation and	maintena	nce of the		
5	dam.								
		Recommendation(s) regarding routing							
1	Three monthly routin	e inspections focussing on any signs o	f impending	failure should	be conducted.	The person	s in contro		
1	of the dam should be	instructed how to do inspections or n	nonitoring.						



Private Bag X313, Pretoria 0001 / Sedibeng Building, 185 Francis Baard Street, Pretoria Tel: 012 336 7500 / Fax: 012 323 4470 or 012 326 2715

Enquiries: DJ Truter JJ Smith

Telephone: 012 336 7971 Telephone: 012 336 8894 E-mail: damsafety@dws.gov.za

Reference: 12/2/C212/46

Mr Philip Nice Ekurhuleni Local Municipality Private Bag X014 BENONI 1500

E-mail: phillip.nice@ekurhuleni.gov.za

Dear Sir

KLEINFONTEIN DAM: PROGRESS WITH THE IMPLEMENTATION OF RECOMMENDATIONS OF A DAM SAFETY INSPECTION REPORT SUBMITTED IN TERMS OF THE DAM SAFETY REGULATIONS IN GOVERNMENT NOTICE R. 139 OF 24 FEBRUARY 2012

The 2<sup>nd</sup> dam safety evaluation report for the above dam dated October 2010 has reference.

The Dam Safety Regulations require in Regulation 35(1) (d) that the owner of a dam with a safety risk must regularly report on progress with the recommendations made in the dam safety evaluation report until all recommendations have been addressed.

A compliance monitoring inspection was performed by officials of this office on 04 December 2018 to evaluate your compliance to the dam safety regulations and a copy of the report is attached for your information and further action.

The inspection concluded that very little progress have been made with most of the recommendations and that there are a number of recommendations that must still be addressed.

You are requested to assign a higher priority to the implementation of the outstanding recommendations and to comply with the requirement to regularly report on progress. The DW19E form can be used for the progress reports. Please kindly submit the completed form to the centralised Dam Safety Office, email address at damsafety@dws.gov.za.

Please ensure that funds are made available on your budget to implement the recommended actions. You are requested to respond before 31 January 2019 with a programme of implementation of the recommendations.

You are commended for complying with the dam safety regulations published in Government Notice R. 139 of 24 February 2012 that requires a dam safety evaluation by an Approved Professional Person to be performed every 5 years for a Category II dam. We have received your latest dam safety evaluation report done in November 2018 and it will be subjected to inspection by an official from this office.

Yours faithfully

DAM SAFETY REGULATION

amoka

DATE: 2018 -12- 11

Copies to: Gauteng Provincial Operations, Mr L.L. Ngelenga, NgelengaL@dws.gov.za



R. Cai(012) 336-848012/2/C221/68

Ekurhuleni Metropolitan Municipality Roads & Stormwater Department (East) Private Bag X014 BENONI 1500

phillip.nice@ekurhuleni.gov.za

ATTENTION: MR PHILLIP NICE

Dear Sir.

VAN DYK'S DAM: SECOND DAM SAFETY EVALUATION (DSE), UPDATED OPERATION MAINTENANCE MANUAL (OMM) AND EMERGENCY PREPAREDNESS PLAN (EPP) IN TERMS OF CHAPTER 12 OF THE NATIONAL WATER ACT, 1998 (ACT 36 OF 1998), READ WITH REGULATION 27, 28 AND 35 OF THE DAM SAFETY REGULATIONS PROMULGATED IN GOVERNMENT NOTICE R. 139 OF 24 FEBRUARY 2012

Receipt is acknowledged of the second DSE, updated OMM and EPP of the above mentioned dam dated May 2018, which was submitted by Ms H Anderson, the Approved Professional Person for the evaluation. The report has been evaluated by the DSO in accordance with the requirement of the Dam Safety Regulations published in Government Notice R.139 of 24 February 2012 and they are accepted with the comments. From the 2<sup>nd</sup> DSE report, the condition of the dam has been classified as Condition D (Significant rehabilitation recommended). It is noted that the dam is in a general poor maintenance condition and a few critical recommendations were made including the spillway guide walls, erosion control structures and drainage system required rehabilitation works. You are hereby requested to assign higher priority duty to implement it accordingly and ensure the dam's function and structure stability meet the SANCOLD guideline and design criteria for the category dam classified.

It is noted that an additional recommendation made with regards to the dam basin area which require a detail survey to determine the flood lines, thereafter the relevant houses may be inundated during floods can be identified. The EPP should include the inundation map and flood warning or evacuation contact list for the dam basin area, however the updated EPP did not cover this. Could you please rectify the updated EPP to address this recommendation accordingly?

There are some recommendations made in the report; you are requested to report on progress made with the implementation of the recommendations until all recommendations have been implemented. A 12-month reporting interval is suggested.

The next dam safety evaluation should be done in 5 years time from today i.e. by 5 July 2023 but a longer interval can be considered if good progress is made to implement the recommendations of this report. This Department would like to express its appreciation for your co-operation with regard to dam safety matters and wishes you success with the continued operation of the dam.

Yours faithfully

Letter signed by: Mrs R Cai

Designation: Specialist Engineer: Dam Safety Office

Date: 5 July 2018

#### Copies to:

- i) Ms N Mabe, <a href="maben@dwa.gov.za">maben@dwa.gov.za</a> Acting Director: Regulation, Gauteng Regional Office, Department Of Water and Sanitation, Private Bag X 995, Pretoria 0001
- ii) Ms H Anderson, the APP, anderson hen riette@gmail.com



R. Cai(012) 336-848012/2/C212/61

Ekurhuleni Metropolitan Municipality Roads & Stormwater Department (East) Private Bag X014 BENONI 1500

phillip.nice@ekurhuleni.gov.za

ATTENTION: MR PHILLIP NICE

Dear Sir,

ALEXANDER DAM: THIRD DAM SAFETY EVALUATION (DSE), UPDATED OPERATION MAINTENANCE MANUAL (OMM) AND EMERGENCY PREPAREDNESS PLAN (EPP) IN TERMS OF CHAPTER 12 OF THE NATIONAL WATER ACT, 1998 (ACT 36 OF 1998), READ WITH REGULATION 27, 28 AND 35 OF THE DAM SAFETY REGULATIONS PROMULGATED IN GOVERNMENT NOTICE R. 139 OF 24 FEBRUARY 2012

Receipt is acknowledged of the third DSE, updated OMM and EPP of the above mentioned dam dated May 2018, which was submitted by Ms H Anderson, the Approved Professional Person for the evaluation. The report has been evaluated by the DSO in accordance with the requirement of the Dam Safety Regulations published in Government Notice R.139 of 24 February 2012 and they are accepted. From the 3<sup>rd</sup> DSE report, the condition of the dam has been classified as Condition C (Significant maintenance recommended). It is noted that the dam is in a general poor maintenance condition and you are hereby requested to undertake the routine maintenance work according to the instituted OMM and maintain the dam at favourable operational and safe condition.

There are some recommendations made in the report; you are requested to report on progress made with the implementation of the recommendations until all recommendations have been implemented. A 12-month reporting interval is suggested.

The next dam safety evaluation should be done in 5 years time from today i.e. by 5 July 2023 but a longer interval can be considered if good progress is made to implement the recommendations of this report. This Department would like to express its appreciation for your co-operation with regard to dam safety matters and wishes you success with the continued operation of the dam.

(P) ei

Letter signed by: Mrs R Cai

Designation: Specialist Engineer: Dam Safety Office

Date: 5 July 2018

### Copies to:

i) Ms N Mabe, <a href="maben@dwa.gov.za">maben@dwa.gov.za</a> Acting Director: Regulation, Gauteng Regional Office, Department Of Water and Sanitation, Private Bag X 995, Pretoria 0001



R. Cai(012) 336-848012/2/C221/63

Ekurhuleni Metropolitan Municipality Roads & Stormwater Department (East) Private Bag X014 BENONI 1500

phillip.nice@ekurhuleni.gov.za

ATTENTION: MR PHILLIP NICE

Dear Sir,

ALBERTON DAM: SECOND DAM SAFETY EVALUATION (DSE), UPDATED OPERATION MAINTENANCE MANUAL (OMM) AND EMERGENCY PREPAREDNESS PLAN (EPP) IN TERMS OF CHAPTER 12 OF THE NATIONAL WATER ACT, 1998 (ACT 36 OF 1998), READ WITH REGULATION 27, 28 AND 35 OF THE DAM SAFETY REGULATIONS PROMULGATED IN GOVERNMENT NOTICE R. 139 OF 24 FEBRUARY 2012

Receipt is acknowledged of the second DSE, updated OMM and EPP of the above mentioned dam dated May 2018, which was submitted by Ms H Anderson, the Approved Professional Person for the evaluation. The report has been evaluated by the DSO in accordance with the requirement of the Dam Safety Regulations published in Government Notice R. 139 of 24 February 2012 and they are accepted. From the 4<sup>th</sup> DSE report, the condition of the dam has been classified as Condition D (Significant rehabilitation recommended). It is noted that the dam is in a general poor maintenance condition and some betterment works required to be done. A subsoil toe drain together with a drainage ditch should be installed downstream in order to lower the phreatic level in the embankment and to allow for monitoring of the seepage. You are hereby requested to assign higher priority duty to implement it accordingly and ensure the dam's structure stability meet the SANCOLD guideline and design criteria for the category dam classified.

There are some recommendations made in the report; you are requested to report on progress made with the implementation of the recommendations until all recommendations have been implemented. A 12-month reporting interval is suggested.

The next dam safety evaluation should be done in 5 years time from today i.e. by 5 July 2023 but a longer interval can be considered if good progress is made to implement the recommendations of this report. This Department would like to express its appreciation for your co-operation with regard to dam safety matters and wishes you success with the continued operation of the dam.

Letter signed by: Mrs R Cai

Designation: Specialist Engineer: Dam Safety Office

Date: 5 July 2018

## Copies to:

i) Ms N Mabe, <a href="maben@dwa.gov.za">maben@dwa.gov.za</a> Acting Director: Regulation, Gauteng Regional Office, Department Of Water and Sanitation, Private Bag X 995, Pretoria 0001



R. Cai
(012) 336-8480
(12/2/C212/51

Ekurhuleni Metropolitan Municipality Roads & Stormwater Department (East) Private Bag X014 BENONI 1500

phillip.nice@ekurhuleni.gov.za

ATTENTION: MR PHILLIP NICE

Dear Sir,

NIGEL DAM: FOURTH DAM SAFETY EVALUATION (DSE), UPDATED OPERATION MAINTENANCE MANNUAL (OMM) AND EMERGENCY PREPAREDNESS PLAN (EPP) IN TERMS OF CHAPTER 12 OF THE NATIONAL WATER ACT, 1998 (ACT 36 OF 1998), READ WITH REGULATION 27, 28 AND 35 OF THE DAM SAFETY REGULATIONS PROMULGATED IN GOVERNMENT NOTICE R. 139 OF 24 FEBRUARY 2012

Receipt is acknowledged of the fourth DSE, updated OMM and EPP of the above mentioned dam dated May 2018, which was submitted by Ms H Anderson, the Approved Professional Person for the evaluation. The report has been evaluated by the DSO in accordance with the requirement of the Dam Safety Regulations published in Government Notice R.139 of 24 February 2012 and they are accepted. From the 4<sup>th</sup> DSE report, the condition of the dam has been classified as Condition D (Significant rehabilitation recommended). It is noted that the dam is at very poor maintenance status and some betterment works required to be done. The area of subsidence with the sinkhole at the left flank of the main southern embankment next to the guide wall must be rehabilitated, low points on the main southern embankment crest must be repaired and the western embankment crest must be rehabilitated while reinstating a section of western embankment as a fuse plug spillway. You are hereby requested to assign higher priority duty to implement it accordingly and ensure the dam's spillway capacity and structure stability meet the SANCOLD guideline and design criteria for the category dam classified.

It is noted that the attached registration information on the dam as Appendix A in your report, it is shown the hazard potential as High which agree to our data base record. But in your report of 5.4 Checking of Registration Information, Hazard potential is referred to Significant and 5.5 Evaluation of The Hazard Potential, Hazard potential is graded to Significant. Could you please clarify this discrepancy accordingly? If you are disagreed the registration information with regard to the classification, please submit the motivation to reclassify the dam accordingly.

Pew

Letter signed by: Mrs R Cai

Designation: Specialist Engineer: Dam Safety Office

Date: 5 July 2018

## Copies to:

i) Ms N Mabe, <a href="maben@dwa.gov.za">maben@dwa.gov.za</a> Acting Director: Regulation, Gauteng Regional Office, Department Of Water and Sanitation, Private Bag X 995, Pretoria 0001



⊒ Fax

cair@dwa.gov.za (012) 336-8674 R. Cai(012) 336-848012/2/C212/44

Ekurhuleni Metropolitan Municipality Roads & Stormwater Department (East) Private Bag X014 BENONI 1500

phillip.nice@ekurhuleni.gov.za

ATTENTION: MR PHILLIP NICE

Dear Sir,

MIDDLE LAKE DAM: FOURTH DAM SAFETY EVALUATION REPORT IN TERMS OF CHAPTER 12 OF THE NATIONAL WATER ACT, 1998 (ACT 36 OF 1998), READ WITH REGULATION 35 OF THE DAM SAFETY REGULATIONS PROMULGATED IN GOVERNMENT NOTICE R. 139 OF 24 FEBRUARY 2012

Receipt is acknowledged of the fourth dam safety evaluation report of the above mentioned dam dated April 2018, which was submitted by Ms H Anderson, the Approved Professional Person for the evaluation. The report has been evaluated by the DSO in accordance with the requirement of the Dam Safety Regulations published in Government Notice R.139 of 24 February 2012 and is accepted. From the report, the condition of the dam has been classified as Condition D (Significant rehabilitation recommended). It is recommended by the APP that the non-overspill crest of the left flank embankment crest should be reinstated up to the top of the guide walls (i.e. raised by 0.7 m from the lowest crest level) to accommodate the routed SEF with limited overtopping and ensure the dam safe.

You are hereby requested to assign higher priority duty to implement it accordingly and ensure the dam's spillway capacity meet the SANCOLD guideline and design criteria for the category dam classified.

There are some recommendations made in the report; you are requested to report on progress made with the implementation of the recommendations until all recommendations have been implemented. A 12-month reporting interval is suggested.

The next dam safety evaluation should be done in 5 years time from today i.e. by 4 July 2023 but a longer interval can be considered if good progress is made to implement the recommendations of this report. This Department would like to express its appreciation for your co-operation with regard to dam safety matters and wishes you success with the continued operation of the dam.

Yours faithfully

1 .


Letter signed by: Mrs R Cai

Designation: Specialist Engineer: Dam Safety Office

Date: 4 July 2018

#### Copies to:

i) Ms N Mabe, <a href="maben@dwa.gov.za">maben@dwa.gov.za</a> Acting Director: Regulation, Gauteng Regional Office, Department Of Water and Sanitation, Private Bag X 995, Pretoria 0001



R. Cai(012) 336-848012/2/C212/45

Ekurhuleni Metropolitan Municipality Roads & Stormwater Department (East) Private Bag X014 BENONI 1500

phillip.nice@ekurhuleni.gov.za

ATTENTION: MR PHILLIP NICE

Dear Sir,

HOMESTEAD LAKE DAM: FOURTH DAM SAFETY EVALUATION (DSE), UPDATED OPERATION MAINTENANCE MANNUAL (OMM) AND EMERGENCY PREPAREDNESS PLAN (EPP) IN TERMS OF CHAPTER 12 OF THE NATIONAL WATER ACT, 1998 (ACT 36 OF 1998), READ WITH REGULATION 27, 28 AND 35 OF THE DAM SAFETY REGULATIONS PROMULGATED IN GOVERNMENT NOTICE R. 139 OF 24 FEBRUARY 2012

Receipt is acknowledged of the fourth DSE, updated OMM and EPP of the above mentioned dam dated May 2018, which was submitted by Ms H Anderson, the Approved Professional Person for the evaluation. The report has been evaluated by the DSO in accordance with the requirement of the Dam Safety Regulations published in Government Notice R.139 of 24 February 2012 and they are accepted. From the 4<sup>th</sup> DSE report, the condition of the dam has been classified as Condition C (Significant maintenance recommended). It is noted that the dam is in a general poor maintained condition. You are hereby requested to undertake the routine maintenance work according to the OMM and maintain the dam safe.

There are some recommendations made in the report; you are requested to report on progress made with the implementation of the recommendations until all recommendations have been implemented. A 12-month reporting interval is suggested.

The next dam safety evaluation should be done in 5 years time from today i.e. by 4 July 2023 but a longer interval can be considered if good progress is made to implement the recommendations of this report. This Department would like to express its appreciation for your co-operation with regard to dam safety matters and wishes you success with the continued operation of the dam.



Letter signed by: Mrs R Cai

Designation: Specialist Engineer: Dam Safety Office

Date: 4 July 2018

### Copies to:

i) Ms N Mabe, <a href="maben@dwa.gov.za">maben@dwa.gov.za</a> Acting Director: Regulation, Gauteng Regional Office, Department Of Water and Sanitation, Private Bag X 995, Pretoria 0001

,