## APPENDIX 1 REFERENCE LIST

## **REFERENCE LIST**

Reference No	Details
1	Ninham Shand Inc, 2002. Report No. P 15000/00/0101. Fish to Tsitsikamma Water Management Area, Water Resource Situation Assessment, Vol 1 – Main Report
2	Ninham Shand Inc, 2002. Report No. P 15000/00/0101. <i>Fish to Tsitsikamma Water Management Area</i> , Water Resource Situation Assessment, Vol 2 – Appendices
3	Markdata (Pty) Ltd, 2001. Report No. P RSA /00/2200. The Distribution of South Africa's Population, Economy and Water Usage Into the Long Term Future
4	BKS, 2003.Report No. P WMA 15/000/00/0203. Fish to Tsitsikamma Water Management Area, Overview of Water Resources Availability and Utilisation
5	Department of Water Affairs, 1988. Report No. OKS/1/88. <i>Report on Preliminary</i> <i>Investigations Into Various Means of Supplying Supplementary Water to the Albany</i> <i>Coast Water Board</i> (This report was never finalized and was only issued in a Draft format).
6	Van Wyk & Louw Inc, 1991. Report No. P400/xx/0191. Investigation Into the Possible Contribution of the Proposed Bushmans River Water Transfer Scheme to Towns in the Lower Bushmans River Valley
7	Water Services Development Plan, 2003.Report No: 24526 Ndlambe Municipality
8	Kwezi V3 Engineers, 2003. Report No: 161780Q0. Water Services Development Plan, Makana Munic ipality (Draft)
9	Kwezi V3 Engineers, 2003. Report No: 161800Q0. Water Services Development Plan, Sundays River Valley Municipality (Draft)
10	Ninham Shand Inc, 2003. Report No: 400014.Water Service Development Plan, Blue Crane Route Municipality (Draft)
11	Ninham Shand Inc, 1998. Report No. P 1834A/5644. Operation and Maintenance Manual for Safety of Sarel Hayward Dam
12	Ninham Shand Inc, 1991. Report No. P 1834/5644. Report on the Safety Inspection of the Sarel Hayward Dam
13	Ninham Shand Inc, 1987. Report No. 1124/3777. Bathurst Stream Dam : Expected Salinities and Salinities Management Options
14	Ninham Shand Inc, 1984. Report No. P 915/3777. Design Report : Construction of a dam on the Bathurst Stream and Ancillary Pumpstations and Pipelines
15	Ninham Shand Inc, 1985. Report No. P 954/3777. Supplementary Design Report : Construction of a dam on the Bathurst Stream and Ancillary Pumpstations and Pipelines

16	Ninham Shand Inc, 1982. Report No. P 749/3777. Report on Proposals for Augmenting the Water Supply, Port Alfred Municipality
17	Stewart Sviridov & Oliver, 1973. Report on Extensions to the Water Scheme for the Municipality of Port Alfred
18	Stewart Sviridov & Oliver, 1975. Supplementary Report on Extensions to the Water Scheme for the Municipality of Port Alfred
19	WSM (Pty) Ltd, 2004. Albany Coast Situation Assessment, Water Quality of Drainage Region P