



Enquiries: L.T. Kobe Telephone: 015 290 1230 Reference: 21/19/D3

# MINISTER OF WATER AND SANITATION

# NATIONAL ASSEMBLY: QUESTION 2934 FOR WRITTEN REPLY

A draft reply to the above mentioned question asked by Mr L J Basson (DA) is attached for your consideration.

DIRECTOR-GENERAL

DATE: 26/8/1>

DRAFT REPLY APPROVED/AMENDED

MRS NP MOKONYANE
MINISTER OF WATER AND SANITATION

DATE: 30.08.15

### NATIONAL ASSEMBLY

### FOR WRITTEN REPLY

### **QUESTION NO 2934**

# <u>DATE OF PUBLICATION IN INTERNAL QUESTION PAPER: 14 AUGUST 2015</u> (INTERNAL QUESTION PAPER NO. 30)

# 2934. Mr L J Basson (DA) to ask the Minister of Water and Sanitation:

- (1) Why is the Groblersdal Wastewater Treatment Plant in the Greater Sekhukhune District Municipality not in working order:
- (2) whether her department has done anything to assist the specified municipality to get the specified plant in working order; if not, why not; if so, what are the relevant details;
- (3) has any water tests been done at the specified plant's outlet into the Olifants River since 1 January 2010; if not, why not; if so, what are the results of the specified tests;
- (4) has she taken any action against the specified municipality or any individual for polluting the river; if not, why not; if so, what are the relevant details;
- (5) what is the specified plant's current Green Drop status?

NW3438E

#### ---00000---

#### REPLY:

- (1) The plant is currently not in working order because the plant was affected by floods during 2014. In addition, theft and vandalism of mechanical and electrical equipment contributed to the plant not working properly.
- (2) My Department has not done any intervention since the Greater Sekhukhune District Municipality proactively appointed the Lepelle Northern Water Board under a bulk contract to operate and maintain the plant. The Lepelle Northern Water is in the process of finalizing the appointment of a service provider to refurbish the Works (the process is at adjudication stage of appointment of the service provider). It is envisage that the plant will be fully restored to its normal operational status during December 2015.
- (3) Yes, tests have been done at the plant's outlet. Test results are attached as **Annexure A.**
- (2) Yes, a non-compliance notification has been issued to the municipality for not taking reasonable measures to prevent pollution from occurring. However, the municipality is in the process to refurbish mechanical and electrical components of the waste water plants. This is set to improve the quality of effluent prior to discharge.
- (5) 29.76 %.

---00000---



Risk and Quality Unit Lepelle Central Laboratory Microbiology Test Report



T0516

Date: 07 July 2015

Postal address:

Lepelle Northern Water P/Bag X104000 Haenertsburg,0730

Physical Address: Van Zyl Rust Farm

Georges Valley Road

Haenertsburg, 0730

Sample Information

Sample Name:Groblesdal

Sampler: Mpho

Sample Date: 30/06/2015 Time received: 07:30 Test date: 01/07/2015

Temp: 10°C

Report No: SDM-GS-30-06-2015

(Sewage)

Tel No:015 276 9904 Fax No:015 276 4998

Email: maserolem@lepelle.co.za

Sample No	Sample Name	*Free Chlorine(mg/L)	AND CONTRACTOR OF THE PARTY OF		E. coli MPN/100mL	
SANS 241 Requirements:			1000	1000	1000	
			MP01	MP01	MP02	
	Groblesdal	Not taken	>2420	ND	>2420	

MPN- Most Probable Number; <1- Results not positive

HPC- Heterotrophic Plate Count

cfu/mL: Colony Forming Units per milli-liter

Tests marked with "\* ", are not included in the SANAS schedule of accreditation for this laboratory.

Test results relate only to the items tested. Shaded column-field test (not done in the lab)

For results sent electronically, signatures are on file

Analyst:	Approved By:( Technical Signatory)
Signature:	Signature:
Date:	Date:



# Risk and Quality Unit Lepelle Central Laboratory Microbiology Test Report



T0516

Date: 20 July 2015

Postal address: Lepelle Northern Water

P/Bag X104000 Haenertsburg,0730

Physical Address: Van Zyl Rust Farm

Georges Valley Road Haenertsburg, 0730

Tel No:015 276 9904 Fax No:015 276 4998

Email: maserolem@lepelle.co.za

# Sample Information

Sample Name:Groblesdal

Sampler: Senyolo

Sample Date: 14/07/2015 Time received: 15:23 Test date: 15/07/2015

Temp: 5°C

Report No: SDM-GS-14-07-2015

(Potable Water)

MPN/100mL		MPN/100mL	Chlorine(mg/L)		Sample No	
1000	1000	1000	SANS 241 Requirements:			
MP02	MP01	MP01				
344800	260300	1046200	Not taken	Groblersdal Sewage		
_				Groblersdal Sewage		



Postal address:Lepelle Northern Water P/Bag X104000 Date: 16 July 2015

Georges Valley Road Haenertsburg,0730 Van Zyl Rust Farm Haenertsburg,0730 Physical address:Ebenezer Plant

Lepelle Central Laboratory Chemistry Test Report Risk and Quality Unit

Sample Date:14/7/15 Sample Information Sampler: Senyolo

Time sample received: 15H23

Report No. GBS-C-14-07-2015(Sewage water) Test Date:15-16/07/2015 Sample Name: Groblersdal sewage

\*Sanas T0516

maserolem@lepelle.co.za Tel No:015 276 9904

	*Chlorides		CP007 No standard		vo standard	70.16			74 70			
	*C. Inhate	emperature	N/A				ALIA		00.00	24.00		24.00
	*Culmbata	Sulphate		2020	N		chandard	Digital of	150.00	130.00		132 GR
	Hd		20004	200		5.5 -9.5			6.82		000	/ 03
*Ortho-			CP018	21010			10 ma/l	0	14 52	30.7	7 45	04.7
	*Nitrate	*Nitrate				≤ 150 mS/m 15mg/l			0.00		200	30.5
	Conductivity		CP003			10000	E/SE DOI 7	00000	118.00		118 20	03.01
			SLOS			75ma/l			30.176	00.00	17400	00:1
	Ammonia	CD044	1000			3mg/l	Light.	8	3	000	33.0	
		Mothod	METHOD									
SAMDIE DOINT	SOUTH LE LOIN							Groblersdal Raw Sewane	ORDINA ORDINA	Groblersdal Final Sewage	ממום מחום מחום	

Tests marked with "", are not included in the SANAS schedule of accreditation for this laboratory. Results are only related to the test items

Note: Results sent electronically signature are on file N/A: Not applicable

Analyst:\_

Signature:

Date:

(Technical signatory) Signature: Date:

Approved by:

Page 1of 1