## PHOTO REPORT FOR THE SITE NOTICE PLACEMENT AS PART OF PUBLIC PARTICIPATION PROCESS FOR COERNEY DAM (November 30<sup>th</sup> & Dcember 1<sup>st</sup> 2021)







Figure 3: Untidy Chemical toilets noted at the MIS site

<complex-block>

Figure 4: Placement at local shop along R336

Figure 5: Placement on site (eastern boundary)



*Figure 6*: Placement on site (northern boundary / Farm Enon Mission)

## Figure 1: Placement at Kirkwood Spar

Figure 2: Placement at Kirkwood Public Library

## PHOTO REPORT FOR THE SITE NOTICE PLACEMENT AS PART OF PUBLIC PARTICIPATION PROCESS FOR COERNEY DAM (November 30<sup>th</sup> & Dcember 1<sup>st</sup> 2021)







Figure 7: Placement at entrance of Scheepers Vlakte Dam

Figure 8: Placement at Access Road into Scheepers Vlakte

Figure 10: Placement at Saint Colmcille Public S School (Eureka Drive)



Figure 11: Placement at Sundays Valley Aided Hospital

**Figure 9**: Placement at intersection of R336 and an unknown road in Kirkwood (The Kirkwood Lookout - Lodge / Chapel)